					Printed on:	14/03/2016	09:05:19		
Application No:	<b>Consultees Name:</b>	Consultees Addr:	Received:	<b>Comment:</b>	Response:				
2016/0295/P	Philip Stone	10 Merlin House Oak Hill Park London NW3 7LJ	11/03/2016 14:32:10	INT	(1) Application incorrectly states in para 2.2 of Design and Access Doc that develop to conservation area. However, estate plaque shows that the design received a Civic 1961. Whilst some aspects of refurbishment would restore features of the original de additional balconies would not. Please see following points (2) Upper 2 floor wind not comply with original design on earlier replacement with UPVC - window replace conform to design and spec of original building and reinstatement should take this in not follow current white PVC) (3) Enclosure of 5th floor SE terrace sets a precedent upper floor balconies and leads to loss of integrity of building design and overbearing appearance that increases the building skyline profile. if applied in the estate would hodge-podge ad-hoc, over-bearing and random design appearance of a good example modern architecture in Hampstead.	trust Award in sign, enclosure of ows currently do ement should to account (and for enclosure of g/ lopsided lead to	rust Award in ign, enclosure of ws currently do ment should o account (and for enclosure of / lopsided ead to		