40 Great James Street

Window Schedule

C(30.5)02

co	Room	Drawing	Comments
	Name	Ref.	Comments

Eviatina \A/			
Existing Wi	naows		N 15/45/0/
WB/01	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
WB/02	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
WB/03	EXTERIOR	L(00)221	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
₩ <u>B/04</u>	EXTERIOR		not used
₩B/05	EXTERIOR		not used
WB/06	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement

co	Room	Drawing	Comments
	Name	Ref.	Comments

Existing Wi	ndows		
W2/01	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
W2/02	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
W2/03	EXTERIOR	L00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
W2/04	EXTERIOR	L(00)221	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
W2/05	EXTERIOR	L(00)221	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
W2/06	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement

co	Room	Drawing	Comments
	Name	Ref.	Comments

1	F:-4: \A/:			
	Existing Wi	ndows		
	WG/01	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
	WG/02	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
	WG/03	EXTERIOR	L(00)221	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
	WG/04	EXTERIOR		not used
	WG/05	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement
	WG/06	EXTERIOR	L(00)220	New sashes as consent 15/4560/L. Rotten cills and lower sash boxes require repair as per method statement

со	Room Name	Ref.	Comments
Existing Wi	ndows		
			New sashes as consent

			New sasnes as consent
W3/01	EXTERIOR	L(00)220	15/4560/L. Rotten cills and lower
VV3/01	LXTERIOR	L(00)220	sash boxes require repair as per
			method statement
			New sashes as consent
W3/02	EXTERIOR	L(00)220	15/4560/L. Rotten cills and lower
VV3/02	EXTERIOR	L(00)220	sash boxes require repair as per
			method statement
			New sashes as consent
W3/03	EXTERIOR	L(00)220	15/4560/L. Rotten cills and lower
VV3/03	LXTERIOR	L(00)220	sash boxes require repair as per
			method statement
			New sashes as consent
W3/04	EXTERIOR	L(00)221	15/4560/L. Rotten cills and lower
VV3/04	EXTERIOR	L(00)221	sash boxes require repair as per
			method statement
			New sashes as consent
W3/05	EXTERIOR	L(00)221	15/4560/L. Rotten cills and lower
**3/03	LXTERIOR	L(00)221	sash boxes require repair as per
			method statement
			New sashes as consent
\\/3/06	W3/06 EXTERIOR	L(00)220	15/4560/L. Rotten cills and lower
¥¥3/00			sash boxes require repair as per
			method statement

co	Room	Drawing	Comments
	Name	Ref.	Comments

PURCELL

Existing Win	dows		
			New sashes as consent 15/4560/L.
14/1/01	=>/====	. (20) 222	Rotten cills and lower sash boxes
W1/01	EXTERIOR	L(00)220	require repair as per method
			statement
			New sashes as consent 15/4560/L.
W1/02	FXTERIOR	L(00)220	Rotten cills and lower sash boxes
VV 1/02	LXTERIOR	L(00)220	require repair as per method
			statement
			New sashes as consent 15/4560/L.
W1/03	EXTERIOR	L(00)220	Rotten cills and lower sash boxes
***1703	EXTERIOR	L(00)220	require repair as per method
			statement
			New sashes as consent 15/4560/L.
W1/04	FXTFRIOR	L(00)221	Rotten cills and lower sash boxes
	27 (12 (13) (1	_(00)	require repair as per method
			statement
			New window box, see drawing
			A(42)221. New sashes as consent
W1/05	EXTERIOR	L(00)221	15/4560/L. Rotten cills and lower
			sash boxes require repair as per
			method statement
			New sashes as consent 15/4560/L.
W1/06	EXTERIOR	L(00)220	Rotten cills and lower sash boxes
	EXTENSION	_(00)220	require repair as per method
			statement

со	Room	Drawing	Comments
	Name	Ref	Comments

co	Room	Drawing	Comments
	Name	Ref.	Comments

co	Room	Drawing	Comments
	Name	Ref.	Comments

co	Room	Drawing	Comments
	Name	Ref	Comments

co	Room	Drawing	Comments
	Name	Ref.	Comments

co	Room	Drawing	Comments
	Name	Ref.	Comments