					Printed on: 29/03	03/2016	09:05:06
Application No:	<b>Consultees Name:</b>	<b>Consultees Addr:</b>	Received:	<b>Comment:</b>	Response:		
2016/0892/P	A M Fox	15 MAKEPEACE AVENUE	25/03/2016 11:41:59	INT	I do not have an issue with two side gables.		
		highgate			My issue is that the existing west side dormer has been built gable end, not hipped, as all others on the street are. This looks overly bulky. There were several objections to this design in the original		
		N6 6EL					
		N6 6EL			application.		
					If they are given consent for this application, it should be on the basis that BOTH side dorme	ners be	
					hipped, to reduce bulk, retain symmetry and fit in with the street scene.		