

## Contents

### 01 Introduction

Introduction				

### 02 Analysis

Spedan Close	07
The 4P Flat Type	08
Dwelling Schedule	09
Original Features	10

### 03 Proposed Works

Design Approach	1
Kitchen Details	1
The Original Kitchen	1
The Modified Kitchen	1
The Replaced Kitchen	1
Products	1

### 04 Appendix

No. 15 Spedan Close
No. 16 Spedan Close
No. 17 Spedan Close
No. 19 Spedan Close
No. 21 Spedan Close
No. 22 Spedan Close

#### Introduction




Image reference: 01 North / south route through the estate

Section 01

## Introduction

This Design and Access statement has been produced by Levitt Bernstein, on behalf of Camden Council, as part of a Listed Building Consent application for the six four person Council leased dwellings at Spedan Close.

#### **Better Homes**

still owned and leased by Camden Council. As of the original design intent as possible to allow part of the council's programme of 'Better Homes' the proposed works to be sensitive to the listing. improvements, which apply to every council owned and rented property, the council are preparing a The Three Types programme of works for the estate. In order to The dwellings on the estate are split into three meet the 'Better Homes' standard the majority types depending on the number of inhabitants; of dwellings on the estate are to have, where four person, five person and six person. The layouts necessary, the refurbishment and alterations to of the four and five person dwellings are almost kitchens and bathrooms, and general re-wiring. identical with the main difference being that the

document.

#### A Grade II Listed Estate


The listing of the estate covers all external and Application Structure internal features and whilst the external condition 
The applications for these works have been or due to the desire to install modern appliances. type.

The following drawings and photos have been Of the 42 dwellings on the estate, 28 of them are pieced together to provide as complete an image

second living room in the four person dwelling is Not all properties require the same level of designated a bedroom in the five person layout. refurbishment to meet the 'Better Homes' standards The six person dwelling has more significant and each property has previously been surveyed by differences with an additional floor that houses two Savilles to assess the necessary upgrades required bedrooms and a bathroom. These dwellings are for each dwelling. A table of the affected dwellings also arranged at the top of the site and therefore and the necessary works is included later in this have unobstructed windows to the north and south allowing them significantly more natural light than the other dwelling types.

of the estate has been thoroughly documented and split into three separate documents for the three relatively unchanged over the years, the internal dwelling types. Each application contains a heritage layout and fittings have little remaining evidence statement, details the original characteristics of the of their original state and are in varying states of type and describes the design approach. Each condition. Over the years many of the properties individual dwelling's current condition is then have been altered by the tenants and Camden recorded along with a specific proposed schedule Council, either where original features have failed of works as an appendix to the application for the Section 02

### Analysis



02 Location plan

- Flat Type Location

to application

DI LUCED IN

time a me am felt felt in 15 bern E.

# Spedan Close

The quality and importance of the estate has been widely recognised both in England and abroad. It is a powerful icon of the optimism and idealism that underpinned post-war public sector architecture.

#### Statement of Significance

Section 02

Grade II listed in 2010.

Camden Council bought the Edwardian mansion Branch Hill Lodge and its grounds in 1965, Externally the materials are restricted to expressed, allocating the grounds for social housing and textured grey concrete frame and slab edges converting the mansion into housing for the elderly. with smooth rendered walls and dark stained In 1970 the council commissioned Gordon Benson timber windows and doors. The bold modernist and Alan Forsyth, of London Borough of Camden aesthetic typical of Camden Council is softened Architects Department, for the design of the estate. by the stepped garden terraces and brick paved The architects were heavily influenced by their time passageways. working with Neave Brown for Camden Council and the design is reminiscent of a number of post-war Internally the dwellings feature open flowing spaces, modernist housing estates built by Camden Council bespoke fitted furniture and a restrained palette of and overseen by borough architect Sydney Cook; materials. The openness of the space is achieved for example Alexandra Road Estate.

be no more than two storeys in height and must long-term issues. be semi-detached. Conscious of this restriction, 01 Cross section and with a desire to maintain the existing trees on the site, the architects utilised the sloping site and designed a series of stepped and overlapping dwellings that achieved the density of a high rise development. In order to achieve the semidetached constraint the estate is intersected by a grid of narrow brick paved passageways that define

The dwellings at Spedan Close form a residential the ground floor plan of the dwellings and provide estate of 42 semi-detached dwellings in Camden, additional space and light for the tenants. The NW3. The estate was built between 1974-76 and estate has a mix of 4-, 5- and 6 person dwellings and is designed to the Parker Morris standards for space and storage.

through the use of sliding partitions and mezzanine levels with large South West facing windows One of the key influences on the massing of the flooding the dwellings with light. The number of estate was the existence of a restrictive covenant bespoke elements is unusual in authority-built that stipulated that any new development must housing, and the level of ambition has led to some

The four person properties are all identical in layout although each is a mirror image of its neighbour. The dwellings are paired between the external access routes that run from north to south.

#### Type Description

The dwelling is a two storey arrangement, as per The kitchen is a galley arrangement, with an insitu

Entering the dwelling from the north/south street, mounted units. These cupboards are solid timber arrival is into the kitchen and mid-level which also construction with plain sliding timber ply doors. houses the dining room and some storage. Taking full height solid timber handles and a distinctive the stair up, the mezzanine level houses the living horizontal trim at top and bottom. The sink is fitted room and main bedroom with a small WC attached. within the main tiled worktop with the appliances The living room opens out to the bridge leading to located within the concrete island which also serves the main external space for the dwelling, hosted to separate the kitchen from the entrance. This on the roof of the adjacent dwelling. The remaining island would have originally been fitted with spur bedrooms and the family bathroom are located on shelving, a lightweight and removable feature that the lowest level which also opens out onto a small allowed tenants a degree of flexibility in the layout enclosed courtyard.


#### **Features**

The open, flowing organisation of the space within the dwelling is achieved through a series of unique features that also allow a degree of flexibility in the use of the spaces: sliding partitions; low levels walls and clean, uncluttered walls and ceilings.

#### **Kitchen Design**

the covenant, with the top floor a split level rising concrete worktop along the north facing wall, clad to a mezzanine. There is access from the living with tiles that also extend up the walls to form a room, via a bridge that crosses the public footpaths splashback. The worktop stops short of the full below, to an external terrace above their neighbour width of the room with a full height cupboard at one end. There are built-in cupboards above and below this worktop and high-level glazing above the wall

of their kitchen.



Ground Plan



Lower Ground Plan

Section 02

## **Original Features**

The level of bespoke fittings is highly unusual for council-built housing, although Camden Council completed several estates in the 1970's with a similar level of high quality fittings. This level of detail is an important part of the historic significance of the estate that led to its listing.

The listing of the estate is for both the interiors **Sliding Partitions:** and exteriors of the dwellings. The description for The use of sliding partitions between rooms towards height doors and bespoke staircases. Unfortunately living spaces and master bedroom. there is very little evidence of the detail of these features as originally installed, either through Other features: drawings or photos.

heritage surveys completed by Levitt Bernstein. storage shelving units. Using this survey information and the few drawings that do exist, the following list has been compiled Maintenance: to catalogue the original features:

fittings can be found. These include insitu tiled sliding doors are prone to stick and fail and tiled concrete worktops, fitted cupboards with sliding surfaces over time become damaged and hard to timber doors and a half-height permanent island maintain are two examples of this.

#### Sliding cupboard doors:

The majority of the cupboards within the dwelling were fitted with sliding plywood timber doors. This was a common detail throughout the property from 01 Kitchen with original worktop and wall the kitchen through to the storage cupboards in the mounted cupboards. (Green paint original) bedrooms and loft door above the kitchen.

the listing of the interiors specifically mentions the the south side of the dwelling allows the space to internal layout of the property, the tiled concrete be opened up across the width of the property on kitchen worktop, the built-in cupboards and both levels. It gives the inhabitants more flexibility shelves, the room-dividing sliding partitions, storey- in the use of the space and allows light to flood the

There are a number of fittings throughout the dwellings that are unique to the estate such as the The images collated here show the best examples timber stairs and handrails, storey height doors, of the surviving features as found through the recent alcoves with fitted shelving and low blockwork


It has become clear through conducting the surveys and discussion with the tenants that several of the bespoke features have, over time, presented The kitchen where the majority of the bespoke maintenance issues. Plywood cupboards featuring

02 Original sliding cupboard doors

03 Original loft access doors

04 Original Timber stairs and handrail







8 | Design & Access Statement, Type 4P, January 2016 | Rev 2 Rev 2 | Design & Access Statement, Type 4P, January 2016 | 9 Levitt Bernstein **Levitt Bernstein** 

**Proposed Works** 



# Design Approach

The proposed works are generally limited to refurbishment and reinstatement of the existing scheme. The arrangement of the flat will be unchanged.

### **Basic Principles**

outline a refurbishment approach based on the to match original. current condition of the dwellings. The proposals 2. The Replaced Kitchen: Where the original must take into account current regulations (e.g. features have been comprehensively altered or gas, electrical and energy certificates, the client removed, the kitchen will be replaced with one that brief) and the needs and aspirations of the residents is sympathetic to the original design intent. whilst maintaining the historic, listed interiors.

London Borough of Camden's Conservation There are no proposed changes to the use, scale Team requires original features removed without or layout of each dwelling. authorisation/consent to be reinstated as original or introduced by residents present a maintenance There are no proposed changes to transport liability for London Borough of Camden and are provision or the external approach to the dwelling. generally stripped out when renovating for the It is not proposed to change the dwelling itself, Better Homes programme.

#### Approaches to existing features

Wherever possible, the original features will be retained and refurbished. There are however many instances where there have been significant alterations or complete removal of the original features. The proposed works will therefore follow one of two approaches:

1. The Modified Kitchen: Where a significant number of original features have been retained and minimal intervention is required to refurbish these features and accommodate modern appliances.

The proposals described in the following pages Where features are missing they will be reinstated

#### Use, scale and layout

beyond reconfiguration of the kitchen and refurbishment of the bathroom.

01 The Estate photographed soon after completion

## **Kitchen Details**

The most significant works within the dwelling will affect the kitchen, where changes are required to accommodate modern appliances within the constraints of the original layout and materials.

The level of remodelling carried out by previous **Cupboards** tenants is extensive in some of the dwellings Many of the original cupboards have been replaced reinstatement of the original kitchen design.


#### Worktop materials


panels that provided a more flexible area that could any exposed ends. accommodate appliances as necessary.


The concrete worktop in most instances has been retained although not always with the original tiles. Where it has been retained and is in good condition it is proposed to carry out minor refurbishment as necessary and leave intact. Where the tiles have been painted or changed it is proposed to replace the tiles with a close match to the original.


The spur shelves in the island unit have not been found to be original in any of the dwellings surveyed. As, by modern standards, the shelving is not practical for the installation of modern appliances, it is proposed to install a solid timber worktop to complement the timber cupboard doors of the original kitchen.


making it necessary to carry out a comprehensive in whole or have had their sliding doors removed or replaced. Where the carcass has been retained it is proposed to refurbish the sliding tracks and replace the doors. Where the cupboards have been The original worktops, terracotta tiling over completely removed it is proposed to replicate reinforced concrete, formed a striking, heavy feature the original using standard carcass units behind that related to the bold aesthetic of the estate. sympathetic plywood cladding. The sliding doors, This was, in the original design, complemented by horizontal timber head and base details will all be lightweight elements: Steel sink units, and shelf infill reproduced, as will the vertical plywood panel at












#### Key:


- 01 Tiled worktop
- 02 SS sink
- 03 Ply faced cupboards 04 - Concrete block 'island'
- 05 Full height cupboard
- 06 Original windows
- 07 Tiled splashback
- 08 Sliding doors to loft
- 09 Spur shelving


## **The Original Kitchen**


01 Original section through kitchen

12 | Design & Access Statement, Type 4P, January 2016 | Rev 2 **Levitt Bernstein Levitt Bernstein** Rev 2 | Design & Access Statement, Type 4P, January 2016 | 13













## Key:

- 01 Tiled worktop
- 02 SS sink and taps
- 03 Ply faced cupboards
- 04 Concrete block 'island'
- 05 Full height cupboard
- 06 Original windows
- 07 Tiled splashback
- 08 Sliding doors to loft
- 09 Timber drawer unit
- 10 Freestanding cooker
- 11 Freestanding washing machine
- 12 Freestanding dishwasher
- 13 Freestanding fridge freezer
- 14 Solid timber worktop









Key:

- 01 Solid timber worktop
- 02 SS sink and taps
- 03 Ply faced cupboards
- 04 Concrete block 'island'
- 05 Full height cupboard
- 06 Original windows
- 07 Tiled splashback
- 08 Sliding doors to loft
- 09 Timber drawer unit
- 10 Freestanding cooker
- 11 Freestanding washing machine
- 12 Freestanding dishwasher
- 13 Freestanding fridge freezer

### Contemporary Kitchen Layout - Replaced

### The Replaced Kitchen

Where there has been a comprehensive level of refurbishment over the years and little of the original kitchen fittings remain, the proposal is to replicate the original fittings and materials in the style of the original. This would incorporate modifications to certain elements of the design such as replacing the sliding doors, an unpopular and difficult to maintain feature, with swing doors. As with the Modified option the island would also be used to incorporate modern appliances and additional worktop space.

### The Modified Kitchen

Where there are a significant number of original fittings in place and in good condition the proposal is to retain and refurbish with missing features restored to their original design. This kitchen will replicate the original design as closely as possible and modern interventions would be limited to the island unit, utilising the flexible space for modern appliances and additional worktop space.

14 | Design & Access Statement, Type 4P, January 2016 | Rev 2 **Levitt Bernstein** Levitt Bernstein Rev 2 | Design & Access Statement, Type 4P, January 2016 | 15

## **Products**

Alterations by the tenants of the dwelling over time has resulted in a mix of original fabric, in need of restoration, and contemporary replacements not in line with the heritage listing of the dwelling. The products below are suggested susbstitutions for the original fabric that maintain the aesthetic and functional aspirations of the original designs.

#### Kitchen Tiles

## original specification:

### Plywood Cabinetry

## varnished to match existing:

### **Bathroom Tiles** A plain terracotta matt tile, as per the High grade birch plywood stained and A plain off-white matt tile, as per the

original specification:







16 | Design & Access Statement, Type 4P, January 2016 | Rev 2

Levitt Bernstein

Levitt Bernstein

### **Appendix**

No. 15 Spedan Close


No. 16 Spedan Close

No. 17 Spedan Close

No. 19 Spedan Close


No. 21 Spedan Close No. 22 Spedan Close

## No. 15 Spedan Close









Dwelling Type: Four person Modified Design Approach: Better Homes works: Kitchen, bathroom and rewiring

### **Current condition of dwelling**

#### Kitchen:

- Original concrete worktop with tiled surface 


  Non-original flooring and wallpaper applied. and tiled splashback. [01+04+05+06]
- Original timber doors to high all cupboards Original wall panels to wall above WC removed. replaced. Original carcass retained with sliding

  • Sliding door painted. tracks. Replacement doors in poor condition.
- Original drawer unit retained and in good Non-original tiling applied to walls. [08] condition. [04+05]
- Island tiled with non-original tiles. [02+03]
- Non-original worktop installed to island.
- Loft door above island painted.


- Non-original flooring laid. [08]











Levitt Bernstein

#### Note:


- Where existing tiles are in good condition, retain and repair any damage and replace any missing.
- Any original fabric removed is to be retained and stored for future use.
- All wiring at low level to be concealed in skirting.
- All wiring at high level to be chased into plaster and made good.

## No. 15 Spedan Close

#### **Proposed Schedule of Works** Works Listing sensitive feature Feature Condition 1.0 Worktop Tiled worktop Some damage to tiles around the sink, grout in poor condition Replace damaged tiles and renew all grout 1.2 Stainless steel sink Sink and taps to be replaced 2.0 Tiled splashback Retained and in good condition Tiles retained and grout to be renewed Tiled splashback 3.0 Cupboards 3.1 Cupboard doors below worktop Non-original doors fixed to original carcass Replica doors to be birch plywood facing with solid timber replica handle Replica doors to be birch plywood facing with solid timber replica handle 3.2 Cupboard doors wall mounted Non-original doors fixed to original carcass 4.0 Half-height kitchen island 4.1 Solid walls Non-original tiles applied to the internal face Tiles to be removed and replacement tiles to be applied to match original tiling 4.2 Shelves Original shelves removed. Non-original worktop installed Worktop to be removed and solid hardwood worktop replacement installed 5.0 Flooring and walls Sheet lino flooring In poor condition Sheet lino replacement to be laid 5.2 Walls In good condition To be repainted 6.0 Loft door 6.1 Sliding timber doors Doors to be replaced to match original Doors missing 7.0 Sanitary fixtures 7.1 WC To be replaced In poor condition 7.2 Sink To be replaced In poor condition 8.0 Flooring and walls 8.1 Flooring Lino tiles in poor condition Sheet lino replacement to be laid 8.2 Walls Non-original wallpaper applied to walls Wallpaper to be removed and wall painted white 8.3 Access panels to rear of WC Panels missing Marine ply, painted white and screw fixed to the wall 9.0 Door 9.1 Timber sliding door Door painted Door to be stripped and repainted BATHROOM 10.0 Sanitary fixtures 10.1 Bath Not original, poor condition To be replaced 10.2 WC Not original, poor condition To be replaced 10.3 Sink Not original, poor condition To be replaced 11.0 Flooring and walls 11.1 Flooring Non-original lino in poor condition Sheet lino replacement to be laid 11.2 Tiling Tiling doesn't meet regulations for showers Tiling to be extended to meet height 11.3 Walls Walls semi-painted Walls to be repainted 12.0 Door 12.1 Timber swing door Original door and ironmongery in good condition Door to be repainted









## No. 16 Spedan Close

Dwelling Type: Four person
Design Approach: Modified

Better Homes works: Kitchen, bathroom and rewiring

### Current condition of dwelling

#### Kitchen:

Bath panel painted. [05]

Non-original tiling applied to walls.

- Original concrete worktop with tiled surface Bathroom: and tiled splashback. [01+03]
- Original timber doors to high all cupboards retained. [01+03]
- Original low level cupboard doors replaced. [01+03]
- Original spur shelves to island removed and replaced with non-original worktop. [02]

#### W

- Non-original flooring laid. [05]
- Non-original tiles to rear of wall-mounted basin.
   [05]

#### Note:


- Where existing tiles are in good condition, retain and repair any damage and replace any missing.
- Any original fabric removed is to be retained and stored for future use.
- All wiring at low level to be concealed in skirting.
- All wiring at high level to be chased into plaster and made good.

## No. 16 Spedan Close

#### **Proposed Schedule of Works** Works Listing sensitive feature Feature Condition 1.0 Worktop 1.1 Tiled worktop Some damage to tiles around the sink, grout in poor condition Replace damaged tiles and renew all grout 1.2 Stainless steel sink Sink and taps to be replaced 2.0 Tiled splashback Tiled splashback Retained and in good condition Tiles retained and grout to be renewed 3.0 Cupboards 3.1 Cupboard doors below worktop Non-original doors fixed to original carcass Replica doors to be birch plywood facing with solid timber replica handle To be refurbished 3.2 Cupboard doors wall mounted Original doors fixed to original carcass 4.0 Half-height kitchen island 4.1 Solid walls Island to be tiled to internal face Tiles to be applied to match original tiling 4.2 Shelves Original shelves removed. Non-original worktop installed Worktop to be removed and solid hardwood worktop replacement installed 5.0 Flooring and walls Sheet lino flooring In poor condition Sheet lino replacement to be laid 5.2 Walls In good condition To be repainted WC - Limited access to room 7.0 Sanitary fixtures 7.1 WC No access If in poor condition: To be replaced 7.2 Sink No access If in poor condition: To be replaced 8.0 Flooring and walls 8.1 Flooring No access If in poor condition: Sheet lino replacement to be laid 8.2 Walls No access Walls to be painted white 8.3 Access panels to rear of WC If panel missing: Marine ply, painted white and screw fixed to the wall No access 9.0 Door 9.1 Timber sliding door If door painted: Door to be stripped and repainted No access BATHROOM 10.0 Sanitary fixtures 10.1 Bath Not original, poor condition To be replaced 10.2 WC Not original, poor condition To be replaced 10.3 Sink Not original, poor condition To be replaced 11.0 Flooring and walls 11.1 Flooring Non-original lino in poor condition Sheet lino replacement to be laid 11.2 Tiling Tiling doesn't meet regulations for showers Tiling to be extended to meet height 11.3 Walls Walls in poor condition Walls to be repainted







## No. 17 Spedan Close

Dwelling Type: Fou Design Approach: Mor Better Homes works: Kito

Four person

Modified

omes works: Kitchen, bathroom and rewiring

### Current condition of dwelling

#### Kitchen:


- Original concrete worktop retained and overclad. [01+03]
- Original tiled splashback replaced. [01]
- Original timber doors to wall mounted cupboards replaced with swing doors.
   Original carcass retained.[01]
- Original timber doors to below-counter cupboards replaced. Original carcass retained. [01+03]
- Half-height island walls reduced in height.
   Worktop fitted to top. [01+02+04]
- Loft door above island removed. [01]

#### WC:

Original sliding door retained and painted.

#### **Bathroom:**


Original wall tiles replaced with mosaic. [05]



- Where existing tiles are in good condition, retain and repair any damage and replace any missing.
- Any original fabric removed is to be retained and stored for future use.
- All wiring at low level to be concealed in skirting.
- All wiring at high level to be chased into plaster and made good.

## No. 17 Spedan Close

#### **Proposed Schedule of Works** Works Feature Condition Listing sensitive feature 1.0 Worktop Tiled worktop Non-original tiles applied over original Terracotta quarry tile with white grout, sealed around the edges 1.2 Stainless steel sink To be replaced Sink and taps to be replaced 2.0 Tiled splashback Non-original tiles applied over original Non-original tile to be removed and replaced with new to match original 2.1 Tiled splashback 3.0 Cupboards Replica doors to be birch plywood facing with solid timber replica handle 3.1 Below worktop cupboards Non-original doors fixed to original carcass 3.2 Wall mounted cupboards Non-original doors fixed to original carcass Replica doors to be birch plywood facing with solid timber replica handle 4.0 Half-height kitchen island 4.1 Solid walls Walls to be restored to original height and tiled to internal face Original shelves removed. Non-original worktop installed 4.2 Infill shelving Worktop to be removed and solid hardwood worktop replacement installed 5.0 Flooring and walls 5.1 Sheet lino flooring In poor condition Sheet lino replacement to be laid 5.2 Walls In good condition To be repainted 6.0 Loft Door 6.1 Sliding timber door Door missing Doors to be replaced to match original 7.0 Sanitary Fixtures To be replaced In poor condition 7.2 Sink In poor condition To be replaced 8.0 Flooring and Walls 8.1 Flooring Laminate timber flooring in good condition 8.2 Walls Textured wallpaper applied to all walls Wallpaper to be removed and walls painted white 8.3 Access panels to rear of WC In good condition To be repainted 9.0 Door 9.1 Timber sliding door Door painted Door to be stripped and repainted BATHROOM 10.0 Sanitary fixtures 10.1 Bath Not original, poor condition To be replaced 10.2 WC Not original, poor condition To be replaced 10.3 Sink Not original, poor condition To be replaced 11.0 Walls and flooring 11.1 Flooring Sheet lino replacement to be laid Laminate timber flooring in poor condition 11.2 Tiling Non-original tiles applied to walls and bath New tile to be 11.3 Walls Tiles to be removed where not necessary and wall painted 12.0 Door 12.1 Timber swing door Door in good condition Door to be repainted







## No. 19 Spedan Close

**Dwelling Type:** Four person **Design Approach:** Modified **Better Homes works:** Kitchen and rewiring

### Current condition of dwelling Kitchen:

- Original concrete worktop retained and Half-height walls infilled to the underside of covered over. [01+03]
- replaced. Original carcass retained with sliding tracks. [01+03+05]
- Original timber doors to below-counter cupboards replaced. Original carcass retained with sliding tracks. [01+03]
- Half-height island walls adjusted return

Original tiled splashback replaced / tiled over. • New worktop and cupboards installed to island. [04]

ceiling. [06]

- Original timber doors to high all cupboards 

   New high-level cupboards fitted above original island. [04]
  - Loft door above island replaced. [05]



**Levitt Bernstein** 





24 | Design & Access Statement, Type 4P, January 2016 | Rev 2

**Levitt Bernstein** 

Rev 2 | Design & Access Statement, Type 4P, January 2016 | 25

## No. 19 Spedan Close

#### **Proposed Schedule of Works**

	Element	Condition	Works	Listing sensitive feature			
KITCH	KITCHEN						
1.0	Worktop						
1.1	Tiled worktop	Retained and covered over	Non-original worktop to be removed and original tiles made good - or replaced if damaged beyond repair	Υ			
1.2	Stainless steel sink	To be replaced	Sink and taps to be replaced				
2.0	Tiled splashback						
2.1	Tiled splashback	Non-original tiles applied in place of original	Non-oringinal tiles to be removed and splashback to be retiled to match existing	Y			
3.0	Cupboards						
3.1	Below worktop cupboards	Non-original doors fixed to original carcass	Replica doors to be birch plywood facing with solid timber replica handle	Y			
3.2	Wall mounted cupboards	Non-original doors fixed to original carcass	Replica doors to be birch plywood facing with solid timber replica handle	Υ			
4.0	Half-height kitchen island						
4.1	Solid walls	Walls modified, height reduced at one end, return demolished and	Replacement tiles to be applied to match original tiling. Red quarry tile with white grout. Edges	Υ			
		height extended elsewhere	to be sealed with mastic sealant				
4.2	Shelves	Original shelves removed. New worktop to be installed in sympathetic	Solid hardwood worktop to be installed. Sealant to be applied to surface				
		material					
<u>5.0</u>	Flooring and walls						
5.1	Sheet lino flooring	In poor condition	Sheet lino replacement to be laid	N			
5.2	Walls	In good condition	To be repainted	N			
6.0	Loft door						
6.1	Sliding timber door	Doors replaced	Non-original doors to be replaced to match original	Υ			
WC							
NO V	VORKS						
BATH							
NO V	VORKS						

- Where existing tiles are in good condition, retain and repair any damage and replace any missing.
- Any original fabric removed is to be retained and stored for future use.

# No. 21 Spedan Close







**Dwelling Type:** Four person Design Approach: Modified **Better Homes works:** Kitchen, Bathroom and rewiring Current condition of dwelling Kitchen:

- Original concrete worktop retained. [03+04+05] New tiles applied to wall below window. [02]
- Original tiled splashback retained. [03+05] Loft door above island replaced. [02]
- Original timber doors to high all cupboards WC: replaced with swing doors. Original carcass

  • Original sliding door removed. adjusted. [03+05]
- Original timber doors to below-counter cupboards replaced. Original carcass retained 


  Original tiles replaced. with sliding tracks. [03]
- Half-height island walls retained and tiled to

   Original WHB, WC and bath replaced. internal face. [02]
- New cupboards and worktop installed to island. [02]

- Original door replaced.







- All wiring at low level to be concealed in skirting.


- All wiring at high level to be chased into plaster and made good.

#### Note:

- Where existing tiles are in good condition, retain and repair any damage and replace any missing.
- Any original fabric removed is to be retained and stored for future use.
- All wiring at low level to be concealed in skirting.
- All wiring at high level to be chased into plaster and made good.


## No. 21 Spedan Close

#### **Proposed Schedule of Works** Element Condition Works Listing sensitive feature 1.0 Worktop Tiled worktop Retained and in good condition Replace damaged tiles and renew all grout 1.2 Stainless steel sink To be replaced Stainless steel sink replacement to match original 2.0 Tiled splashback Retained and in good condition To be retained and grout renewed Tiled splashback 3.0 Cupboards 3.1 Below worktop cupboards Non-original doors fixed to original carcass Replica doors to be birch plywood facing with solid timber replica handle 3.2 Wall mounted cupboards Non-original doors fixed to original carcass Replica doors to be birch plywood facing with solid timber replica handle 4.0 Half-height kitchen island Retained and non-original tiles applied to internal face Non-original tiles to be removed and new tiles applied to match original Solid walls 4.2 Shelves Shelving replaced by worktop with fitted cupboards below Worktop and cupboards to be removed and replaced with solid hardwood worktop 5.0 Flooring and walls Sheet lino to be laid Flooring 5.2 Walls Tiles applied under window, cornicing fitted to top Walls to be repainted and non-original tiles and cornicing to be removed 6.0 Loft Doors 6.1 Sliding timber doors Doors replaced Non-original doors to be replaced to match original 7.0 Sanitary Fixtures In poor condition To be replaced 7.2 Sink To be replaced In poor condition 8.0 Flooring and Walls Flooring To be replaced with sheet lino 8.2 Walls Wallpaper applied to walls Wallpaper to be removed and walls made good 8.3 Access panels to rear of WC Panels to be repainted Panels to be repainted 9.0 Sliding door 9.1 Sliding timber door Original door missing Door to be replaced to match original BATHROOM 10.0 Sanitary Fixtures 10.1 Bath In poor condition To be replaced 10.2 WC In poor condition To be replaced 10.3 Sink In poor condition To be replaced 11.0 Swing door 11.1 Timber door Original door and ironmongery replaced To be repainted 12.0 Walls and flooring Non-original tiling applied to all walls To be replaced to meet standards 12.2 Flooring Floor carpeted To be replaced with sheet lino









### Current condition of dwelling

#### Kitchen:

- Original concrete worktop retained. [01+02+05]
- Original tiled splashback retained. [01+02+04+05]
- Original timber doors and carcass to wall mounted cupboards replaced. [01+02+05]
- Original timber doors to below-counter cupboards replaced. Original carcass retained with sliding tracks. [01+02]
- Half-height island walls retained and tiled to internal face. Textured wallpaper applied to external face. [03+05]

- New cupboards and worktop installed to island. [02]
- Loft door above island replaced. [02]


#### WC:

No. 22 Spedan Close

Original sliding door replaced with curtain.

#### Bathroom:

- Bath removed and accessible shower installed.
- Original door replaced with sliding door.





**Appendix** 

## No. 22 Spedan Close

Prop	osed Schedule of Works Element	Works	Specification notes	Listing sensitive featur	
KITCHEN		Works	opeomoation notes	Listing sensitive leatu	
1.0	Worktop				
.1	Tiled worktop	Retained and in good condition	Replace damaged tiles and renew all grout	Y	
.2	Stainless steel sink	To be replaced	To be replaced to match original	N	
.0	Tiled splashback				
.1	Tiled splashback	Retained and in good condition	Replace damaged tiles and renew all grout	Υ	
.0	Cupboards				
.1	Wall mounted cupboards	Cupboards replaced	Replica doors to be birch plywood facing with solid timber replica handle	Y	
.2	Below worktop cupboards	Cupboard carcass retained and new doors fitted	Replica doors to be birch plywood facing with solid timber replica handle	Υ	
.0	Half-height kitchen island				
.1	Solid walls	Non-original tiles and wallpaper to be removed and new tiles applied	Replacement tiles to be applied to match original tiling. Red quarry tile with white grout. Edges	Y	
			to be sealed with mastic sealant		
2	Shelving	Non-original worktop and cupboards to be removed and replaced	Solid hardwood worktop to be installed. Sealant to be applied to surface and around edges	Y	
		with new worktop			
0	Flooring and walls				
1	Flooring	Flooring to be replaced with suitable alternative	Sheet lino to be agreed	N	
.2	Walls	Textured wallpaper applied to all walls	Wallpaper to be stripped and walls painted	N	
.0	Loft door				
3.1	Sliding timber doors	Doors replaced	Non-original doors to be replaced to match original	Υ	
VC	WORKS				
	ROOM VORKS				
10 V	WORKS				

Not

- Where existing tiles are in good condition, retain and repair any damage and replace any missing.

- Any original fabric removed is to be retained and stored for future use.

- All wiring at low level to be concealed in skirting.

- All wiring at high level to be chased into plaster and made good.

Job number
3325
File name
3325\_Design & Access Statement\_4P

Status

PLANNING

2 29.03.16

Output date
January 2016
Client
LB Camden