

24 Redington Gardens
London NW3 7RX

Basement Impact Assessment
Audit

For
London Borough of Camden

Project Number: 12336-34

Rev: D1

April 2016

Campbell Reith Hill LLP
Friars Bridge Court
41-45 Blackfriars Road
London
SE1 8NZ

T: +44 (0)20 7340 1700
F: +44 (0)20 7340 1777
E: london@campbellreith.com
W: www.campbellreith.com

Document History and Status

Revision	Date	Purpose/Status	File Ref	Author	Check	Review
D1	April 2015	Comment	AJMav12336-34-120416-24 Redington Gardens-D1.doc	A Marlow	A Marlow	E Brown

This document has been prepared in accordance with the scope of Campbell Reith Hill LLP’s (CampbellReith) appointment with its client and is subject to the terms of the appointment. It is addressed to and for the sole use and reliance of CampbellReith’s client. CampbellReith accepts no liability for any use of this document other than by its client and only for the purposes, stated in the document, for which it was prepared and provided. No person other than the client may copy (in whole or in part) use or rely on the contents of this document, without the prior written permission of Campbell Reith Hill LLP. Any advice, opinions, or recommendations within this document should be read and relied upon only in the context of the document as a whole. The contents of this document are not to be construed as providing legal, business or tax advice or opinion.

© Campbell Reith Hill LLP 2015

Document Details

Last saved	19/04/2016 17:35
Path	AJMav12336-34-120416-24 Redington Gardens-D1.doc
Author	A J Marlow, BSc CEng MStructe FConSE
Project Partner	E M Brown, BSc MSc CGeol FGS
Project Number	12336-34
Project Name	24 Redington Gardens, London NW3 7RX
Planning Reference	2016/1015/P

Contents

1.0 Non-technical summary 1
2.0 Introduction 3
3.0 Basement Impact Assessment Audit Check List 5
4.0 Discussion 9
5.0 Conclusions 12

Appendices

- Appendix 1: Residents' Consultation Comments
- Appendix 2: Audit Query Tracker
- Appendix 3: Supplementary Supporting Documents

1.0 NON-TECHNICAL SUMMARY

- 1.1. CampbellReith was instructed by London Borough of Camden (LBC) to carry out an audit on the Basement Impact Assessment submitted as part of the Planning Submission documentation for 24 Redington Gardens, London NW3 7RX (planning reference 2016/1015/P). The basement is considered to fall within Category B as defined by the Terms of Reference.
- 1.2. The Audit reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development in accordance with LBC's policies and technical procedures.
- 1.3. CampbellReith was able to access LBC's Planning Portal and gain access to the latest revision of submitted documentation and review it against an agreed audit check list.
- 1.4. It has been confirmed that the development site does not involve a listed building, nor is it in the neighbourhood of listed buildings.
- 1.5. The BIA has confirmed that the proposed basement will be located within the Claygate Beds and that the surrounding slopes are stable.
- 1.6. There is a shallow groundwater level which will require the use of a secant pile wall, or similar, to permit excavation of the basement.
- 1.7. The BIA noted that the construction of the basement could alter the groundwater flow. Subsequent information provided by Chord Environmental Ltd confirmed the locations of nearby basements and that significant groundwater flow is not anticipated. It concluded that the development proposal will have no significant impact on groundwater/hydrogeological conditions.
- 1.8. The proposed basement will be excavated and constructed utilising established techniques.
- 1.9. It is accepted that the risk of surface water flooding the buildings is low, despite nearby streets having been flooded in 2002.
- 1.10. The initial BIA identified that part of the basement will be within alluvial soils which have the potential for groundwater flow within them. It included a proposal to provide a 1m deep granular trench around the basement to permit any such flow around the basement. Information from Chord described how the alluvial soils are of a limited nature, annual recharge will be very low and other nearby basement developments will have reduced their water bearing potential further. It concluded that the proposed development would have no

significant groundwater effects. Notwithstanding that, it is suggested that the concept for a trench to potentially cut off any groundwater be carried through to detailed design.

- 1.11. The BIA indicates that although the basement extends beneath the existing garden soft landscaping / SUDS will be provided above this part of the basement. It is accepted that will not significantly alter the existing surface water drainage conditions.
- 1.12. The ground movement assessment provided as part of the BIA indicates that damage to the adjacent properties will be Burland Category 2 or less, using conservative assessments for soil parameters and wall stiffness. It is suggested that these be reviewed at detailed design stage and detailed design can be modified e.g. prop details, wall stiffness in order to reduce the predicted damage to Burland Category 1 as required by CPG4.
- 1.13. It is recommended that outstanding items should be contained within a Basement Construction Plan. These are discussed in Section 4 and summarised in Appendix 2.

2.0 INTRODUCTION

- 2.1. CampbellReith was instructed by London Borough of Camden (LBC) on 17th March 2016 to carry out a Category B Audit on the Basement Impact Assessment (BIA) submitted as part of the Planning Submission documentation for 24 Redington Gardens, Camden Reference 2016/1015/P.
- 2.2. The Audit was carried out in accordance with the Terms of Reference set by LBC. It reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development.
- 2.3. A BIA is required for all planning applications with basements in Camden in general accordance with policies and technical procedures contained within
- Guidance for Subterranean Development (GSD). Issue 01. November 2010. Ove Arup & Partners.
 - Camden Planning Guidance (CPG) 4: Basements and Lightwells.
 - Camden Development Policy (DP) 27: Basements and Lightwells.
 - Camden Development Policy (DP) 23: Water.
- 2.4. The BIA should demonstrate that schemes:
- a) maintain the structural stability of the building and neighbouring properties;
 - b) avoid adversely affecting drainage and run off or causing other damage to the water environment; and,
 - c) avoid cumulative impacts upon structural stability or the water environment in the local area

and evaluate the impacts of the proposed basement considering the issues of hydrology, hydrogeology and land stability via the process described by the GSD and to make recommendations for the detailed design.

- 2.5. LBC's Audit Instruction described the planning proposal as the "*The demolition of the existing dwelling house and the erection of a replacement dwelling house together with associated landscaping and car parking.*"

The Audit Instruction also confirmed that the basement proposals did not involve a listed building nor the site neighboured listed buildings.

2.6. CampbellReith accessed LBC's Planning Portal on 8th April 2016 and gained access to the following relevant documents for audit purposes:

- Basement Impact Assessment (BIA) dated December 2015 by Michael Alexander
- Ground Movement & Building Damage Assessment Report (GMA) dated November 2015 by Byland Engineering Ltd
- Desk Study & Ground Movement Investigation Report for 25-26 Redington Gardens dated May 2015 by GEA
- Letter report by Chord Environment Ltd – 1127/LJE020915 for 25-26 Redington Gardens

3.0 BASEMENT IMPACT ASSESSMENT AUDIT CHECK LIST

Item	Yes/No/NA	Comment
Are BIA Author(s) credentials satisfactory?	Yes	The authors of the BIA, the Ground Investigation report and the Ground Movement Assessment all have suitable credentials. Letter report by Chord Environmental also by individual with suitable credentials.
Is data required by Cl.233 of the GSD presented?	Yes	
Does the description of the proposed development include all aspects of temporary and permanent works which might impact upon geology, hydrogeology and hydrology?	Yes	BIA Sections 3.02, 4.02 and 5.02.
Are suitable plan/maps included?	Yes	BIA and appendices.
Do the plans/maps show the whole of the relevant area of study and do they show it in sufficient detail?	Yes	
Land Stability Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	BIA Section 4.01.
Hydrogeology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	BIA Section 3.01.
Hydrology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	BIA Section 5.01.
Is a conceptual model presented?	No	

Item	Yes/No/NA	Comment
Land Stability Scoping Provided? Is scoping consistent with screening outcome?	Yes	BIA Section 4.02.
Hydrogeology Scoping Provided? Is scoping consistent with screening outcome?	Yes	BIA Section 3.02.
Hydrology Scoping Provided? Is scoping consistent with screening outcome?	Yes	BIA Section 5.02.
Is factual ground investigation data provided?	Yes	Ground investigation report for neighbouring property.
Is monitoring data presented?	Yes	Groundwater monitoring in the Ground investigation report.
Is the ground investigation informed by a desk study?	Yes	Desk study and ground investigation report.
Has a site walkover been undertaken?	Yes	Ground investigation report Section 2.0.
Is the presence/absence of adjacent or nearby basements confirmed?	Yes	Initial BIA had limited discussion on basements, documents refer to only one nearby basement being present. However, additional letter report by Chord Environmental covers this issue.
Is a geotechnical interpretation presented?	Yes	Ground investigation report Section 6.0.
Does the geotechnical interpretation include information on retaining wall design?	Yes	Ground investigation report Section 7.1.2.
Are reports on other investigations required by screening and scoping presented?	Yes	Thames Water asset search.
Are baseline conditions described, based on the GSD?	Yes	

Item	Yes/No/NA	Comment
Do the base line conditions consider adjacent or nearby basements?	Yes	Only the nearest basement. Resident comment indicates other basements in the area. Further addressed in Chord Environmental letter report.
Is an Impact Assessment provided?	Yes	Ground Movement Assessment.
Are estimates of ground movement and structural impact presented?	Yes	Ground Movement Assessment.
Is the Impact Assessment appropriate to the matters identified by screen and scoping?	Yes	Initial BIA did not consider impact on subterranean flow in sufficient detail. Additional letter report by Chord Environmental covers this.
Has the need for mitigation been considered and are appropriate mitigation methods incorporated in the scheme?	Yes	Secant piled wall SUDS on top of basement under garden Granular trench around basement.
Has the need for monitoring during construction been considered?	Yes	BIA.
Have the residual (after mitigation) impacts been clearly identified?	Yes	Impacts on subterranean flow and adjacent highway addressed in Chord Environmental letter report.
Has the scheme demonstrated that the structural stability of the building and neighbouring properties and infrastructure been maintained?	Yes	Some of the assumptions within the ground movement assessment need to be confirmed during the detailed design.
Has the scheme avoided adversely affecting drainage and run-off or causing other damage to the water environment?	Yes	Not possible to confirm in original BIA. Additional letter report by Chord Environmental covers this.
Has the scheme avoided cumulative impacts upon structural stability or the water environment in the local area?	Yes	Not possible to confirm in original BIA. Additional Ground Movement Assessment and additional letter report by Chord Environmental covers this.

Item	Yes/No/NA	Comment
Does report state that damage to surrounding buildings will be no worse than Burland Category 2?	Yes	Estimated to be Burland Category 2 or less.
Are non-technical summaries provided?	No	But BIA is written so as to be understandable.

4.0 DISCUSSION

- 4.1. The BIA submitted for 24 Redington Gardens makes reference to a site soils investigation previously submitted for an adjoining planning submission for 25-26 Redington Gardens. CampbellReith carried out the audit for this previous application, which required additional information to be supplied by Chord Environmental before our concerns were satisfied. Although neither the soils investigation by GEA nor the Chord Environmental letter report have been formally submitted as part of the documentation for 24 Redington Gardens, CampbellReith will assess this additional information as though it had been submitted, in order to expedite this application.
- 4.2. The BIA and subsequent information has been carried out by an established firm of structural engineers, Michael Alexander, who have employed the services of GEA and Byland to supplement the work needed to form the BIA. The authors and reviewers from all of these organisations have suitable qualifications. Supporting information was also subsequently provided by Chord Environmental Ltd whose author has suitable qualifications.
- 4.3. The proposed basement will generally be excavated with the sides supported by a propped secant pile wall. This is an acceptable methodology using established techniques.
- 4.4. The BIA mentioned only one nearby basement. An investigation of the presence of other nearby basements has subsequently been produced by Chord Environmental.
- 4.5. It is acknowledged that the basement is founded within the Claygate Beds, overlying the London Clay. The ground investigation report and BIA refer to a water course that once traversed the site and a former tributary to the River Westbourne that ran along the south eastern boundary. The BIA notes that the site may be located adjacent to a spring line. The basement extends through the alluvial soils and Claygate Beds. A full hydrogeological impact assessment has been included in Section 7.6 of the BIA to confirm that the proposed 1m deep granular trench around the basement is sufficient to permit flow around the basement when other surrounding basements are considered. A site specific soils investigation should be undertaken prior to construction commencement.
- 4.6. Further information is provided in Chord Environmental Ltd letter 1127/LJE020915. The review of existing basements is based on a search of Camden's Planning Portal to establish which properties in the vicinity of 24 Redington Gardens have had basement developments. Numbers 4 and 6 Templewood Avenue both have double basements and lie immediately to the north and approximately 60m north east of the site. In addition, 38 Redington Avenue and 16-17 Redington Gardens also both have double level basements and are located immediately to the south west and across the road to the south east of the site respectively. The letter report concludes that neither the existing basements nor the current proposal will impact on the

hydrogeological conditions. Since Chord's letter, 25-26 Redington Gardens has received planning consent but the basement construction has yet to commence. It is accepted that the conclusions of their report will be unaffected.

- 4.7. The ground investigation report suggests that groundwater flow is to the south or south west and that the alignment of the basement has the potential to alter the flow of groundwater. Further information is provided in Chord Environmental Ltd letter 1127/LJE020915. The letter states that the proposed basement development would extend through alluvial deposits in the north of the site and then Claygate Member silty clays. It states that there is no significant groundwater flow through the clays of the Claygate Member and therefore there is no potential groundwater impact from the basement development within these deposits.
- 4.8. As the Alluvium deposits would have a relatively narrow extent due to the size of the former tributary, any groundwater encountered by the proposed basement excavation would also be similarly limited. Annual recharge through these deposits would be very low. Recent basement developments across the former path of the tributary up gradient of the site will have reduced the water bearing potential of the Alluvium even further. The letter concludes that the proposed basement development would have no significant groundwater effects i.e. the direction of groundwater flow is not relevant.
- 4.9. The groundwater is shown to be at 1-1.5m depth and so the basement will be significantly below the groundwater level. The proposal to use a secant piled wall to form the sides of the basement should be adopted.
- 4.10. The BIA has shown that the surrounding slopes to the development are stable.
- 4.11. The BIA indicates that the new foundations will be deeper than any neighbouring foundations, and the same depth as 25-26 Redington Gardens next door.
- 4.12. The BIA indicates that although the basement extends beneath the existing garden soft landscaping / SUDS will be provided above this part of the basement. It is accepted that will not significantly alter the existing surface water drainage conditions.
- 4.13. The BIA includes an assessment of whether the development is likely to be affected by surface water flooding, and even though nearby streets were flooded in 2002, the risk is accepted as being low.
- 4.14. The Ground Movement Assessment prepared by Byland Engineering concludes that any damage to the neighbouring properties will be Burland Category 2 or less. The report follows methodology advocated in CIRIA 580. Limited data was available for foundations to the adjacent properties and the analysis assumes stiff clay is to be retained. Since alluvial soils and softened Claygate soils are to be retained (i.e. not stiff clay as per the CIRIA methodology),

modelling uses conservative assumptions i.e a medium stiffness wall. Any reductions due to heave effects were ignored. These predictions were taken forward to the damage impact assessment.

- 4.15. It is believed that a review of wall stiffness and soil parameters should be undertaken at detailed design stage. However, modification of the detailed design e.g. propping details and wall stiffness would provide an opportunity to ensure the predicted settlements in the ground movement assessment are achieved. It is considered therefore that the movement assessment is acceptable as far as planning purposes are concerned. A detailed temporary works scheme should be provided in due course and reviewed against wall stiffness.
- 4.16. A basic/outline movement monitoring regime is included in Byland Engineering's updated report. It states that, the plan should include a traffic light system which identifies safe (green), trigger (amber) and action (red) values of ground or wall deflection. Precise surveys of ground markers and targets fixed to building walls and the basement capping beam and pile deflection measurements using inclinometers cast into a few wall piles are recommended. The monitoring plan should identify specific measures to be implemented should specific thresholds be met in order to minimise any problems to neighbouring properties. A particular specification for piling based on the ICE specification for piling and embedded retaining walls 2nd edition (SPERW2) should be prepared. The specification should include the movement monitoring requirements. This is an acceptable approach.
- 4.17. It is recommended that the issues contained within items 4.5, 4.15 and 4.16 should be addressed within a Basement Construction Plan prior to construction commencement.

5.0 CONCLUSIONS

- 5.1. The BIA and subsequent supporting information have been prepared by established organisations. The authors and reviewers from all of these organisations have suitable qualifications.
- 5.2. The proposed basement will generally be excavated with the sides supported by a propped secant pile wall. This is an acceptable methodology using established techniques.
- 5.3. The basement is founded within the Claygate Beds, overlying the London Clay and it is noted that the groundwater flow may be altered. A hydrogeological impact assessment has confirmed that the proposed 1m deep granular trench around the basement is adequate mitigation.
- 5.4. Further monitoring to confirm the direction of flow of the groundwater was requested based on the BIA. Additional supporting information described how groundwater flow would be negligible. Notwithstanding, it is suggested that the concept for a trench to potentially cut off any groundwater be carried through to detailed design.
- 5.5. The groundwater is shown to be at 1-1.5m depth and so the basement will be significantly below the groundwater level. The proposal to use a secant piled wall to form the sides of the basement should be adopted.
- 5.6. The BIA indicates that although the basement extends beneath the existing garden soft landscaping / SUDS will be provided above this part of the basement.
- 5.7. The BIA includes an assessment of whether the development is likely to be affected by surface water flooding, and even though nearby streets were flooded in 2002, the risk is accepted as being low.
- 5.8. The Ground Movement Assessment concludes that any damage to the neighbouring properties will be less than Burland Category 2. The analysis used conservative assessments for soil parameters and wall stiffness. It is suggested that these be reviewed at detailed design stage and the detailed design can be modified/mitigation measures incorporated e.g. prop details, wall stiffness in order to limit the predicted damage to Burland Category 1 as required by CPG 4.
- 5.9. A movement monitoring regime on the adjacent properties during construction is proposed and this should be provided.
- 5.10. It is recommended that outstanding issues should be contained within a Basement Construction Plan.

Appendix 1: Residents' Consultation Comments

Residents' Consultation Comments

Surname	Address	Date	Issue raised	Response
Heath and Hampstead Society		08/03/16	Burland damage assessment required.	This comment pre-dates the Ground Movement Assessment report provided for this audit. See Sections 4.14 and 5.8

Appendix 2: Audit Query Tracker

Audit Query Tracker

Query No	Subject	Query	Status	Date closed out
1	Stability	Ground movement assessment to be refined	To be supplied as part of a Basement Construction Plan.	N/A
2	Stability	Outline movement monitoring regime to be provided	To be supplied as part of a Basement Construction Plan	N/A
3	Stability	Detailed temporary works scheme to be provided	To be supplied as part of a Basement Construction Plan	N/A
4	Stability	Site specific soils investigation to be undertaken	To be supplied as part of a Basement Construction Plan	N/A

Appendix 3: Supplementary Supporting Documents

None

London

Friars Bridge Court
41- 45 Blackfriars Road
London, SE1 8NZ

T: +44 (0)20 7340 1700
E: london@campbellreith.com

Birmingham

Chantry House
High Street, Coleshill
Birmingham B46 3BP

T: +44 (0)1675 467 484
E: birmingham@campbellreith.com

Surrey

Raven House
29 Linkfield Lane, Redhill
Surrey RH1 1SS

T: +44 (0)1737 784 500
E: surrey@campbellreith.com

Manchester

No. 1 Marsden Street
Manchester
M2 1HW

T: +44 (0)161 819 3060
E: manchester@campbellreith.com

Bristol

Wessex House
Pixash Lane, Keynsham
Bristol BS31 1TP

T: +44 (0)117 916 1066
E: bristol@campbellreith.com

UAE

Office 705, Warsan Building
Hessa Street (East)
PO Box 28064, Dubai, UAE

T: +971 4 453 4735
E: uae@campbellreith.com

Campbell Reith Hill LLP. Registered in England & Wales. Limited Liability Partnership No OC300082
A list of Members is available at our Registered Office at: Friars Bridge Court, 41- 45 Blackfriars Road, London SE1 8NZ
VAT No 974 8892 43