

43 - 45 Bedford Square

Works to existing doors to achieve fire rating



It is proposed to carefully remove and set aside the existing doors and remove the existing brass ironmongery



The existing frames will be repaired where damaged by previous installations, and the doors will be re-hung on new fire rated hinges.



New knobs, locks, escutcheons and closers will be provided. For safety purposes we will provide finger guards to the hinged edge of the door. The doors will be prepared and decorated with an intumescent coating prior to receiving the finishing coats of paint or varnish sympathetic to the existing condition.