

Vritten dimensions to be taken in preferences to scale imensions. The Contractor is responsible for checking all dimensions before work starts.

All work is to be carried out to the requirements, and to the satisfaction of the Local Authority. These drawings are for planning purposes only

Any discrepancies to be brought to the attention of 4D Planning Consultants immediately.

Location Plan



www.GetMePlanning.com®

Marc Mannatt

9B Wedderburn Road, NW3 5QS

Detailed Window Drawings