

BRICK FACING PANEL - APPENDIX A



Existing brickwork stained from WC overflow pipes



Sample Panel of Sto brick slips in front of existing