



## PLANTING NOTES

All planting to adhere to all the relevant British Standards and Codes of Practice including:
 BS 3882 Recommendations for topsoil
 BS 3936 Part 1 Nursery stock Specification for trees and shrubs
 BS 3936 Part 1 Nursery stock Specification for trees and shrubs
 BS 3936 Part 1 Nursery stock Specification for trees and shrubs

BS 3998 Recommendations for tree work
BS 4043 Recommendations for transplanting root balled trees
BS 4428 Code of Practice for general landscape operations (excluding hard surfaces)
BS 5837:2012 Guide for trees in relation to construction

BS 5837:2012 Guide for trees in relation to construction
BS 7370 Recommendations for maintenance of soft landscaping
BS 8545: From nursery to independence in the landscape
2. All planting to be carried out with reference to the issued NBS
specification 03/03/14
3. The minimum topsoil depth for trees should be 600mm
4. Trees shall be planted in tree pits as detailed in Drg. No. HO-439-200-142
7. On site checks should be made by the engineer to ensure that tree roots will not cause any future damage to any structures or underground services.

8. Plants should be supplied exactly true to name, in the event that this is not possible an alternative should be found following consultation with the landscape consultant (tel. 07990 576 900, email info@hannahoakden.co.uk)



## Hannah Oakden Landscape Design

4 Byelaw Cottages, Spithurst Road, Barcombe, BN8 5EF Tel. 07990 576 900 Email: info@hannahoakden.co.uk

Client: Rydon Construction Ltd

Title: DHO Gateway Replacement Tree Planting Plan

Rev 01 28/11/2014
1. Plant substitution
Rev 02 14/01/2015
1. Tree species changed to Platanus x hispanica as requested by

1. Planting layout amended in line with revised Detailed
Arrangement HO-439\_DA\_001\_R012
2. Updated Plant Schedule
Rev 05 08/12/2016
1. All planting at ground level removed as requested by KCA



Project: Bacton Low Rise

HO-439-200-115 08/12/2016

Rev: Drawn by: 1:50 @A1

Tree Officer
Rev 03 07/08/2015

1. Planting layout amended in line with revised Detailed Arrangement HO-439\_DA\_001\_R09

2. Updated Plant Schedule
Rev 04 04/08/2016

