



brick on edge coping detail

25°

70°

remove and make good redundant chimney stack - this is currently half removed

flank wall extended in multi stock brickwork to match exg. wall

chimney stack at number 4

line of existing wall

repair

boundary

BALCONY

Exg.

GARAGE

FLOOR LEVEL No.2

1-5 BEAUMONT MEWS
NEW HOUSING
No.10 CHARLTON KING'S RD.

REVISIONS:
A. 27.1.17 EXTENSION TO REAR REMOVED, FLANK WALL ADAPTED IN TRADITIONAL MANSARD IN LINE WITH CAMPDEN GUIDANCE DOCUMENT

JON LAWLER ARCHITECTS

2 CHARLTON KING'S ROAD

PROPOSED SIDE ELEVATION

1:50 @ A3

2 CKR/14A