

/// Indicates elements to be removed	(52) Concrete cornice to be removed and reinstated with higher quality material	No	Date		Issue For	Issue By	Michael and Kelly Pawlyn		ex	(plorc	noitk
Cement rendered brickwork to be cut back (refer to AR-301 and sections 3.7.9 and 4.9 in the Heritage, Design and Access Statement) Brick parapet extensions to be removed		00			ed for info . submission	MP MP		rd Floor, 28-42 Banner Street, London, EC1Y 8QE fice: +44 (0) 207 251 8088			
		02	27-03-17	Rev. s	submission	MP	Project: Grove End House	info@exploration-architecture.com www.exploration-architecture.com			
(refer to section 3.7.10 in the Heritage, Design and Access Statement) 7 Corbelled bricks and upper part of chimney to be carefully dismantled to allow											
chimney to be heightened and top part reinstated 33) Wherever possible vents/pipes to be removed and brickwork repaired							Title: End (south) elevation as existing	Drawn: MP Scale:	MP	Project Number: 1502 Dwg No:	Rev:
								1:50 @ A1 1:100 @ A	1	AR-301	02