

Remove lino, stain and polish existing floorboards. Hack off existing plaster, 1m from floor level, to install damp proofing adnd repair with lime plaster where applicable




Retain existing fireplace.



Overhaul and repair existing timber sash windows and panel door.

Strip, stain and polish existing floorboards.



**EXISTING BASEMENT PLAN** 



Existing cellars to be

tanked


Retain & overhaul metail railings around existing lightwell, replace missing metal slim arrowhead to match existing. All external features are to be retained and overhauled



Strip and repair existing wooden staircase and balustrade.



Retain and repair existing lath and plaster ceiling from above.






Retain, strip and repair; wooden wall panelling, sash windows and window shutters.




Retain fireplace surround and reinstate hearth.



Retain, strip and repair; wooden wall panelling, sash windows and window shutters.



Strip and repaint all timber doors.



EXISTING GROUND FLOOR



Retain wooden wall panelling and wooden staircase with balustrade.

Retain sitting room door architrave



Retain and repair areas of water damaged lath and plaster ceiling and cornice.



Retain, strip and paint skirting board.



## Architects Planners Designers

121 Gloucester Place, London W1U Tel: 020 7486 3666 Pax: 020 7486 3888 e-mail: architect@archetype.org.uk

## roject:

18 GROVE TERRACE LONDON NW5 1PH

## Drawing Title:

GROUND FLOOR CONDITION SCHEDULE




Existing ceiling and cornice to be retained and repaired.



Existing fireplace surround to be retained. The fireplace and hearth to be reinstated.



Overhaul and repair sash windows. Retain skirting and floorboards.



Existing door and frame to be retained and fixed

in position

EXISTING FIRST FLOOR




Strip and repaint timber door. Retain skirting and architrave. Remove cupb. door and retain door opening with architrave.



Overhaul and repair sash window.
Repair and retain cornice.
New bathroom stud wall partition shall have moulded plaster cornice and timber skirting to match the existing.



Retain hallway panelling.
Retain wooden staircase and balustrade.






Existing alcove and shelving removed and opening reinstated with new door.



Retain fireplace and reinstate hearth.



Overhaul and repair sash windows. Retain skirting and floorboards. Existing ceiling and cornice to be retained and repaired from water damage.




**EXISTING SECOND FLOOR** 



Fireplace to be retained.




Strip and repaint timber door. Retain skirting and architrave. Retain and repair cornice.






Retain fireplace surround and remove electric heater. Re-instate fireplace and hearth.



Overhaul and repair sash window. Retain fireplace surround and remove electric heater. Re-instate fireplace and hearth.



Overhaul and repair sash windows. Retain skirting and floorboards.



Remove new stud wall and doors and form new studwork wall to form bedroom and shower.

## Archetype

Architects Planners Designers

121 Gloucester Place, London WIU
Tel: 020 7486 3666 Fax: 020 7486 3888
e-mail: architect@archetype.org.uk

Projec

18 GROVE TERRACE LONDON NW5 1PH

Drawing Title:

LOFT FLOOR CONDITION SCHEDULE

OCT 14 1:100 @ A3

1049 (08) -05

e: Status:
Preliminary
Tender draw
Working dra