



- Key**
- Existing lowered plaster board ceilings
 - Existing Soffit
 - Existing main lowered ceiling spine
 - Existing linear light fitting

CDM Information
 The following information is provided in pursuance of the CDM Regulations.
 The information is to be read in conjunction with the Designers Hazard Log.

- Used to warn of significant design hazards and site risks
- Used to avoid or prevent a particular action
- Used to encourage a particular action
- Used to convey some relevant CDM information

Risk No. Description of Residual Hazard & Risk

The purpose of this schedule is to identify significant risks, not necessarily those that involve the greatest risks, but those (including health risks) that are not likely to be obvious, are unusual, or likely to be difficult to manage effectively.

- General Asbestos is present in the building.
- General A reciprocal means of escape is in place for the neighboring institute.
- General Low contrast between rise and going on steps.

Revision	Date	Amendment	Notes					Client	UoL	Burwell Deakins
/	10.11.17	Planning Issue					Project	IALS Refurbishment Project	info@burwellarchitects.com www.burwellarchitects.com	
A	22.11.17	Final Planning Issue					Drawing	Existing 1st Floor RCP		
				Scale	1:100 @ A1	Drawn	BM			
				Date	October 2017					
Project N°		Drawing N°		Revision						
739		739-PL-054		A						
				Unit 0.01		California Building		First Floor		
				London SE13 7SF		© Southendby		West Exeter EX1 1JG		
				+44 (0) 2083 056010		+44 (0) 1392 423981				

NO DIMENSIONS ARE TO BE SCALED FROM THIS DRAWING. THE CONTRACTOR/MANUFACTURER IS RESPONSIBLE FOR CHECKING ALL DIMENSIONS AND QUERING ANY DISCREPANCIES. THIS DRAWING IS THE PROPERTY OF BDA ARCHITECTS LTD. COPYRIGHT IS RESERVED BY THEM AND THE DRAWING IS ISSUED ON CONDITION THAT IT IS NOT COPIED, REPRODUCED, RETAINED OR DISCLOSED TO ANY UNAUTHORISED PERSON, EITHER WHOLLY OR IN PART, WITHOUT WRITTEN CONSENT.