

Key	Notes
	Removal of main lowered ceiling spine
	Extent of fixture to be removed
	Extent of lowered plaster board ceilings to be removed



CDM Information
 The following information is provided in pursuance of the CDM Regulations. The information is to be read in conjunction with the Designers Hazard Log.

- Used to warn of significant design hazards and site risks
- Used to avoid or prevent a particular action
- Used to encourage a particular action
- Used to convey some relevant CDM information

Risk No. Description of Residual Hazard & Risk

The purpose of this schedule is to identify significant risks, not necessarily those that involve the greatest risks, but those (including health risks) that are not likely to be obvious, are unusual, or likely to be difficult to manage effectively.

General Asbestos is present in the building.
 General A reciprocal means of escape is in place for the neighboring institute.
 General Low contrast between rise and going on steps.



Revision	Date	Amendment	Notes
/	10.11.17	Planning Issue	
A	22.11.17	Final Planning Issue	

Client	UoL		
Project	IALS Refurbishment Project		
Drawing	Demolition RCP 5th Floor		
Scale	1:100 @ A1	Drawn	GB
Date	October 2017		
Project N°	739	Drawing N°	739-PL-068
		Revision	A

Burwell Deakins	
info@burwellarchitects.com www.burwellarchitects.com	Unit 0.01 California Building London SE13 7SF +44 (0) 2083 056010
First Floor © Southenbury West Exeter EX1 1JG +44 (0) 1392 423981	

NO DIMENSIONS ARE TO BE SCALED FROM THIS DRAWING. THE CONTRACTOR/MANUFACTURER IS RESPONSIBLE FOR CHECKING ALL DIMENSIONS AND QUERING ANY DISCREPANCIES. THIS DRAWING IS THE PROPERTY OF IDA ARCHITECTS LTD. COPYRIGHT IS RESERVED BY THEM AND THE DRAWING IS ISSUED ON CONDITION THAT IT IS NOT COPIED, REPRODUCED, RETAINED OR DISCLOSED TO ANY UNAUTHORISED PERSON, EITHER WHOLLY OR IN PART, WITHOUT WRITTEN CONSENT.