





NOTE:

Existing ceiling plasterboard to be replaced (1 hour fire resisting) on resilient bars.

Existing, flush internal doors to be replaced with solid timber flush fire doors.

Defective, non-original sash windows to be replaced like-for-like but without horns and using stretched ovolo mouldings/glazing bars & hardwood cills.

| <b>project5</b><br>ARCHITECTURE | PROJECT 5                                                             | job title                           | scale     | drawn   | drawing no.  |
|---------------------------------|-----------------------------------------------------------------------|-------------------------------------|-----------|---------|--------------|
|                                 | ARCHITECTURE LLP<br>8 Waterson Street<br>London E2 8HL                | 3 FREDERICK STREET, LONDON WC1X 0NG | 1:50 @ A3 | SA      | 6214-FS3-P04 |
|                                 | T: +44 (0)20 7739 9131<br>F: +44 (0)20 7739 3687<br>E: info@p5a.co.uk | drawing                             | date      | checked |              |
|                                 |                                                                       | SECOND FLOOR PLAN - PROPOSED        | NOV 2017  | XX      |              |