


Note: The existing window joinery does not include shutters but has simple plastered reveals



Internal Elevation

Revision	Date	Amendment
1.0	12-10-2017	Issued for listed building consent application

Do not reproduce this drawing without written permission
 All dimensions are in millimetres unless stated otherwise

hs
engine for growth
 High Speed (HS2) Limited
 25th Floor
 One Canada Square
 Canary Wharf
 London E14 5AB

COSTAIN
SKANSKA
 1 Triton Square
 Euston Road
 London
 NW1 3AN

Ingram Consultancy Limited
 HISTORIC BUILDING CONSULTANTS & CHARTERED SURVEYORS
Consultants in the repair and conservation of historic buildings, ancient monuments and their sites
 HOLLY COTTAGE LOWER STREET
 UPTON NOBLE
 SOMERSET BA4 6BB
 t. 01749 850 900
 enquiries@ingram-consultancy.co.uk
 www.ingram-consultancy.co.uk

Site Address: 34 Park Village East, Regents Park, London NW1			
Drawing Title: Second Floor Bedroom: EXISTING Internal Joinery Elevation - Sheet 2 of 6			
Surveyed by: GA	Drawn by: GA	Checked by: GR	Presentation Scale: 1:5 @ A1
Date: 12-10-2017	Drawing No: 2016-005-34PVE-EX-SF-J-02	Revision: 1.0	