

Bri as
Bri

Brickwork - First quality multi facings as F10/111 Brickwork - Linfield yellow as

Brickwork - TBC as F10/111


— · — · — · – · – MJ— Movement joint

----- Brick support level

Cavity tray and weep hole level

NOTE: HEAD RESTRAINT REQUIRED FOR DEFLECTION AT SOFFITS TO SLABS. REFER TO (21) SERIES FOR FURTHER DETAILS. THERMAL BLOCK SHOULD BE USED AT ALL SLAB TO BRICK JUNCTIONS INC. GROUND CONDITIONS. REFER TO CX_(21)_6015 AND 6016 AND (19) SERIES FOR DETAILS.

F10/111



02 BUILDING C2 SOUTH EAST PLANT ENCLOSURE ELEVATION BRICK SCOPE

CONSULTANTS	NOTE	
CLIENT: Stanley Sidings	 Do not scale from this drawing. All dimensions to be checked on 	HAW EV DOLL
CONTRACTOR: Mace	site by the contractor and such dimensions to be his responsibility.	5-23 OLD STREET, LONDON, EC1V 9HL TEL 020 7251 5261 FAX 020 7251 5123 WEB WWW.AHMM.CO.UK
STRUCTURAL ENGINEER: Walsh Group	3. Report all drawing errors, omissions	
MECHANICAL ENGINEER: AECOM	and discrepancies to the architect. 4. This document may be issued in an	
COST CONSULTANT: Gardiner & Theobald	uncontrolled CAD format to enable others to use it as background	
PROJECT MANAGER: Gardiner & Theobald	information to make alterations and/or additions. In that instance	drawing title / location BRICKWORK - C2 SOUTH EAST ELEVATION
ACOUSTIC CONSULTANT: Hoare Lea	the file will be accompanied by a	
TRANSPORT CONSULTANT: Arup	PDF version. It is for those making such alterations and additions to	drawn by checked Iscale Istatus
PLANNING CONSULTANT: Gerald Eve	ensure that they make use of current background information.	KP KH 1:100 @ A1 CONSTRUCTION
LANDSCAPE ARCHITECT: Fabrik	AHMM Ltd accepts no liability for any such alterations or additions to	project zone CI/SfB drawing no. revision
CDM CO-ORDINATOR: MSA Safety	the background information or arising	
PRINCIPAL DESIGNER: Gardiner & Theobald	out of changes to background information which occur prior to	[14045 C2_(23)_2050 C03
	alterations of additions being made.	