



Key

TEXT Proposed layout

TEXT Existing layout

Upper section of boundary walls to be repaired where cracking in joints apparent

Outline of new extension - Planning application ref: 2016/6143/P

Lower section of boundary walls to be rebuilt due to cracking and movement in bricks

Lower section of boundary walls to be rebuilt due to cracking and movement in bricks

