



= Existing window openings where internal secondary glazing will be installed. The scope of secondary glazing work is limited to these openings only

Basement level kitchen window is shown indicatively

Revisions:



High Speed (HS2) Limited
25th Floor
One Canada Square
Canary Wharf
London E14 5AB



Costain Skanska Joint Venture
1 Triton Square
Euston Road
London
NW1 3AN

Historic Building Consultants:
Ingram Consultancy Limited
Holly Cottage
Lower Street
Upton Noble
Somerset
BA4 6BB
T. 01749 850 900
E. enquiries@ingram-consultancy.co.uk
www.ingram-consultancy.co.uk

Site Address:
12 Park Village East, London
Drawing Title:
East Elevation with Location of Internal Secondary Glazing

Drawn by:
GA

by:
GA

Checked By:
GR

Drawing No:
2016-005-12PVE-EX-EL-01

Scale:
NTS @ A3:

Revision:
00