



Second floor attic level bedroom window

Ground floor level kitchen/diner
French doors

Ground floor level
Kitchen/Diner window



= Existing window openings where internal secondary glazing will be installed.
The scope of secondary glazing work is limited to these openings only

Revisions:



High Speed (HS2) Limited
25th Floor
One Canada Square
Canary Wharf
London E14 5AB



Costain Skanska Joint Venture
1 Triton Square
Euston Road
London
NW1 3AN

Historic Building Consultants:

Ingram Consultancy Limited

Holly Cottage
Lower Street
Upton Noble
Somerset
BA4 6BB

T. 01749 850 900

E. enquiries@ingram-consultancy.co.uk
www.ingram-consultancy.co.uk

Site Address:
14 Park Village East, London

Drawing Title:
South Elevation with Location of Internal Secondary Glazing

Drawn by:
GA

by:
GA

Checked By:
GR

Scale:
NTS @ A3:

Drawing No:
2016-005-14PVE-EX-EL-02

Revision:
00