



= Existing window openings where internal secondary glazing will be installed.  
The scope of secondary glazing work is limited to these openings only

Revisions:



**High Speed (HS2) Limited**  
25<sup>th</sup> Floor  
One Canada Square  
Canary Wharf  
London E14 5AB



**Costain Skanska Joint Venture**  
1 Triton Square  
Euston Road  
London  
NW1 3AN

Historic Building Consultants:  
**Ingram Consultancy Limited**  
Holly Cottage  
Lower Street  
Upton Noble  
Somerset  
BA4 6BB  
T. 01749 850 900  
E. enquiries@ingram-consultancy.co.uk  
www.ingram-consultancy.co.uk

Site Address:  
14 Park Village East, London  
Drawing Title:  
East Elevation with Location of Internal Secondary Glazing

Drawn by:  
GA

by:  
GA

Checked By:  
GR

Drawing No:  
**2016-005-14PVE-EX-EL-01**

Scale:  
NTS @ A3:

Revision:  
**00**