

<b>Application No:</b>	<b>Consultees Name:</b>	<b>Received:</b>	<b>Comment:</b>	<b>Response:</b>
2018/2904/L	Debbie Radcliffe for Bloomsbury CAAC	11/07/2018 23:33:42	OBJ	As this is a Grade II listed building within a conservation area, it is not appropriate to replace existing single glazed sash windows, which reflect the period of the host building, with double glazing. Listed windows are an integral part of the listed building. As well as creating a visual alteration to the facade, double glazed windows can harm heritage interiors during installation. Secondary glazing is usually acceptable.

---