



notes

- PLEASE NOTE ALL VERY FEW OF THE ORIGINAL YORK STONE TREADS AND RISERS REMAIN. MOST HAVE BEEN REPLACED BY CONCRETE TREADS AND RISERS AT SOME TIME IN THE PAST. THOSE THAT DO REMAIN HAVE SEVERELY DETERIORATED, THE STONE IS DELAMINATING AND HAS LOST BETWEEN $\frac{1}{3}$ AND $\frac{1}{2}$ OF ITS ORIGINAL THICKNESS. ALSO IN THESE ORIGINAL STONE TREADS, WHERE THE BALUSTRADE IS LEADED IN, CORNERS HAVE BEEN REPLACED BY CONCRETE.

HYLE LLP
 48B GRAFTON ROAD, LONDON NW5 3DY

project name and address
LIGHTWELL STAIR RENOVATION
 17 Regents Park Terrace, NW1 7ED

date	rev	description	dwn

drawing title
PARTIAL SECTION & FRONT ELEVATION
LIGHTWELL AND VAULT AREA
AS EXISTING

scale	size	drawn	passed	date
1:25	A2	MGB	-	27/07/2018

drawing number	rev
RPT(L)20	-

1
 RPT(L)20
PARTIAL SECTION AND FRONT ELEVATION - AS EXISTING