

3.01.01 Replace damaged slates to existing pitched roof

Lightening protection to M&E Engineer's specification. Locations of lightening tape to be agreed.

Roof Top
16265

8.04.12 Redecorate existing external metalwork

Fourth Floor
14100

Third Floor
11200

Second Floor
7695

3.10.01 Existing rainwater goods to be refurbished

First Floor
3780

0.01.01 Remove single storey lean-to. Existing brickwork made good as 5.01.01. New window as 5.02.06

Ground Floor
0

Combined sounder and visual warning device, to M&E Engineer's specification

5.01.07 Remove paint from bottom of wing buildings no 37 & 38

Lower Ground
-3040

4.08.02 New roof guarding to match existing (no 36)

5.01.06 Repoint existing brick copings

5.01.04 Brick up existing window and arch

5.02.06 Reinstall missing glazing bars to opening casement

5.02.02 Supply and fit new window in new opening

5.01.03 Form new window opening and arch

5.01.04 Brick up existing window and arch

3.10.02 Rainwater goods to be adapted

5.02.01 Overhaul and repaint existing windows in existing window opening

4.06.01 Renovate existing external balcony balustrading. Decorate as section 8.04


5.01.06 Repoint existing brick copings

KEY LEGEND

 Demolition Works

 New Construction

Read in conjunction with SEPP-NHA-XX-XX-SH-A-42030 Outline schedule of works for full details



Nicholas Hare Architects
 3 Bamsbury Square London NI 1JL
 telephone +44 (0)20 7619 1670
 fax +44 (0)20 7619 1671
 e-mail info@nicholashare.co.uk

project UCL SEPP Gordon Square
 for UCL
 site GA Elevations-Proposed-Rear

scale	size	drawing number	rev.
1:50	A1	SEPP-NHA-XX-XX-PL-A-00132	00