
## General notes:

- 1. Shading indicates new construction.
- 2. All existing bathroom, kitchen and sanitaryware fittings to be removed.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- 5. Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined.
- Existing services and drains removed and replaced throughout. 6.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms 8.
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed. 9.
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.
- 11. All services and pipe routes to follow existing routes where possible to avoid additional notching of joists or removal of existing fabric.
- 12. All new doors to be timber 4 panelled doors of traditional Georgian detailing.




No. 28




No.	NOTES (STATUS: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL D. I	DESIGN DEV	/ PRELIM M. 1	MEASUI	REME	ENT T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASS
1	For construction use only if status 'C' and checked against current revision	F	24/03/2014	TJB	ACS	General notes added, LGF floor level lowered by height of one step	12 Devonshire Street London W1G 7AB Tel: 020 7245
2	All dimensions to be checked on site by contractor	Е	10/03/2014	SZP	ACS	Ground floor Mews rear wall aligned with Mews walls above.	12 Devolutine Street London W1G /AD 161. 020 /243
3	Do not scale from this drawing	D	17/02/2014	JXA	ACS	Re-submission of planning issue	<b>Job</b> 27 John Street & 21 John's Mews
4	Unless otherwise indicated all dimensions are in millimetres	С	10/01/2014	JXA	ACS	Reinstatement of existing light well	
		В	05/09/2013	JXA	ACS	Planning Issue and alterations to layout	<b>Title</b> Proposed Lower Ground Floor Plan
Ι	16/06/17 TOB ACS Basement extension removed	А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	1
Н	12/02/15 ERH ACS Basement extension removed	-	30/07/2013	JXA	ACS	Initial Issue	
G	25/06/14 TJB ACS Car stacker converted to Store	Rev	Date	Dwn	Auth	REVISIONS	


## Notes on Lower Ground Floor:

• Internal doors: S/F new traditionally detailed painted SW door and architraves throughout except where indicated otherwise.






Job JS27.02	Statu	P	
No 2000	Rev	Ι	
Scale (A3) 1:	1	2	5




No.	NOTES	(STATU	JS: F. F	EASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL	. D. DESIGN DEV	/PRELIM M. N	MEASU	REME	NT T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCIA
1	For cons	struction	n use or	nly if status 'C' and checked against current revision	F	24/03/2014	TJB	ACS	General notes added	12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 En
2	All dime	nsions t	o be ch	necked on site by contractor	Е	10/03/2014	SZP	ACS	Ground floor Mews rear wall aligned with Mews walls above.	12 Devolishire Street London WIG /AB Tel: 020 /245 9888 Eh
3	Do not se	cale from	n this c	drawing	D	17/02/2014	JXA	ACS	Re-submission of planning issue	<b>Job</b> 27 John Street & 21 John's Mews
4	Unless of	therwise	e indica	ted all dimensions are in millimetres	С	05/09/2013	JXA	ACS	Reinstatement of existing light well, reduction in size of Mews extension	
					В	05/09/2013	JXA	ACS	Planning Issue	<b>Title</b> Proposed Ground Floor Plan
Ι	22/06/17	TOB	ACS	Sheffield stands added	А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	
Н	12/03/15	ERH	ACS	Basement extension removed	-	30/07/2013	JXA	ACS	Initial Issue	
G	25/06/14	TJB	ACS	Car stacker removed	Rev	Date	Dwn	Auth	REVISIONS	

Job JS27.02	Statu	P	
No 2001	Rev	Ι	
Scale (A3) 1:	1	2	5



### General notes:


- 1. Shading indicates new construction.
- 2. All existing bathroom, kitchen and sanitaryware fittings to be removed.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined. 5.
- Existing services and drains removed and replaced throughout. 6.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms 8.
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed 9.
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.
- 11. All services and pipe routes to follow existing routes where possible to avoid additional notching of joists or removal of existing fabric.
- 12. All new doors to be timber 4 panelled doors of traditional Georgian detailing.



Notes on Second Floor:

except where indicated otherwise.

No.	NOTES (S	STATUS	S: F. F	EASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL D	. DESIGN DEV	/PRELIM M. 1	MEASURE	IENT T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCIA
1	For constr	truction	use or	ly if status 'C' and checked against current revision	F	24/03/2014	TJB AC	S General notes added	12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Em
2	All dimens	nsions to	be ch	ecked on site by contractor	E	10/03/2014	SZP AC	S Ground floor Mews rear wall aligned with Mews walls above.	- 12 Devolusing Street London W1G 7AB 1et. 020 7245 9888 Elli
3	Do not sca	ale from	this d	rawing	D	17/02/2014	JXA AC	S Re-submission of planning issue	<b>Job</b> 27 John Street & 21 John's Mews
4	Unless oth	herwise	indica	ted all dimensions are in millimetres	С	10/01/2014	JXA AC	S New proposed bath 1/ dresser room	
					В	05/09/2013	JXA AC	S Planning Issue	<b>Title</b> Proposed Second Floor Plan
					А	29/08/2013	JXA AC	S Adding Notes and alterations to layout	
					-	30/07/2013	JXA AC	S Initial Issue	
G	16/06/2017	TOB	ACS	General notes added	Rev	Date	Dwn Au	h REVISIONS	






Job JS27.02	Statu	Status P				
No 2003	Rev	G				
Scale (A3) 1:	1	2	5			

## General notes:

- Shading indicates new construction. 1.
- All existing bathroom, kitchen and sanitaryware fittings to be removed. 2.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined. 5.
- Existing services and drains removed and replaced throughout. 6.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms 8.
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed. 9.
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.



Dwn Auth REVISIONS


Rev

Date

## Notes on Lower Ground Floor:

•

Internal doors: S/F new traditionally detailed painted SW door and architraves throughout except where indicated otherwise.






Job JS27.02	Status P			
No 2004	Rev	D		
Scale (A3) 1:	1	2	5	

## General notes:

- 1. Shading indicates new construction.
- 2. All existing bathroom, kitchen and sanitaryware fittings to be removed.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined. 5.
- Existing services and drains removed and replaced throughout. 6.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms 8.
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed. 9.
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.






No.	NOTES (STATUS: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL	. D. DESIGN DEV	/ PRELIM M.	MEAS	UREM	IENT T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCI
1	For construction use only if status 'C' and checked against current revision						12 Devonshire Street London W1G 7AB Tel: 020 7245 9888
2	All dimensions to be checked on site by contractor						12 Devolishire Street London WIG /AB 1ei: 020 /245 9888
3	Do not scale from this drawing						<b>Job</b> 27 John Street & 21 John's Mews
4	Unless otherwise indicated all dimensions are in millimetres	С	16/06/2017	TOB	ACS	Amendment to notes	
		В	05/09/2013	JXA	ACS	B Planning Issue	<b>Title</b> Proposed Fourth Floor Plan
		А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	F
		-	30/07/2013	JXA	ACS	Initial Issue	
		Rev	Date	Dwn	Aut	h REVISIONS	

## Notes on Lower Ground Floor:

•

Internal doors: S/F new traditionally detailed painted SW door and architraves throughout except where indicated otherwise.






## IATES LIMITED

# CHARTERED ARCHITECTS PLANNING CONSULTANTS

Email: london@insall-architects.co.uk

Job JS27.02	Statu	Status P				
No 2005	Rev	С				
Scale (A3) 1:	1	2	5			






No.	NOTES (S	STATU	S: F. FI	EASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING	DONALD INSALL ASSOCIA					
1	For const	truction	use on	ly if status 'C' and checked against current revision						12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Er
2	All dimen	nsions to	o be che	ecked on site by contractor						12 Devolishire Street London WIG /AD Tel: 020 /245 5000 El
3	Do not sca	ale from	n this d	Irawing						Job 27 John Street & 21 John's Mews
4	Unless of	herwise	indicat	ted all dimensions are in millimetres						
					В	05/09/2013	JXA	ACS	Planning Issue	<b>Title</b> Proposed Roof Plan
					А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	
					-	30/07/2013	JXA	ACS	Initial Issue	
					Rev	Date	Dwn	Auth	REVISIONS	

©2013 DONALD INSALL ASSOCIATES LIMITED

Last saved on 17/02/2014 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2006 proposed roof plan.dwg by JXA



					12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Em
					12 Devolishire Street London W1G /AB 1el: 020 /245 9888 Elli
					<b>Job</b> 27 John Street & 21 John's Mews
С	16/06/2017	TO	B ACS	Amendment to notes	
В	05/09/2013	JX.	A ACS	Planning Issue	<b>Title</b> Proposed Front Elevation
А	29/08/2013	JX.	A ACS	Adding Notes	1
-	01/08/2013	AX	T ACS	Initial Issue	
Rev	Date	Dw	n Aut	h REVISIONS	
	C B A - Rev	B 05/09/2013 A 29/08/2013 - 01/08/2013	B         05/09/2013         JX           A         29/08/2013         JX           -         01/08/2013         AX	B         05/09/2013         JXA         ACS           A         29/08/2013         JXA         ACS           -         01/08/2013         AXT         ACS	B         05/09/2013         JXA         ACS         Planning Issue           A         29/08/2013         JXA         ACS         Adding Notes           -         01/08/2013         AXT         ACS         Initial Issue

## General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where necessary in matching mortar.
- Carefully brush clean brickwork to remove moss and staining for small areas where necessary and soot down to match existing.
- Replace mismatching brickwork with second hand bricks to match existing sample must be approved by Architect: soot down any repairs to match existing.

Stone

• Carefully brush clean stonework - remove moss and stain and repoint as necessary.

Leadwork

• Carefully investigate roof leadwork once safe access is established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.

Drainage


- Remove redundant services.
- Repair/replace damaged pipes as necessary.
- Clear all the blockages
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
- All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.

## ATES LIMITED

CHARTERED ARCHITECTS PLANNING CONSULTANTS

Email: london@insall-architects.co.uk

Job JS27.02	JS27.02					
No 2200		Rev	С			
Scale (A3)	1:	1	2	5		





NOTES (STATUS: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CON	DONALD INSALL ASSOCIA								
For construction use only if status 'C' and checked against current revision	12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Ema								
All dimensions to be checked on site by contractor	Е	12/03/2015	ERH	ACS	Garden level lowered	12 Devonsnire Street London WIG /AB 1el: 020 /245 9888			
Do not scale from this drawing	Re-submission of planning issue	<b>Job</b> 27 John Street & 21 John's Mews							
Unless otherwise indicated all dimensions are in millimetres	С	10/01/2014	JXA	ACS	New second floor window, additional french window on ground floor extensio				
	В	05/09/2013	JXA	ACS	Planning Issue	<b>Title</b> Proposed Rear Elevation			
	А	29/08/2013	JXA	ACS	Adding Notes				
	-	01/08/2013	AXT	ACS	Initial Issue				
	Rev	Date	Dwn	Auth	REVISIONS				

## General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where necessary in matching mortar.
- Carefully brush clean brickwork to remove moss and staining where necessary.
- Replace mismatching brickwork with second hand bricks to match existing - sample must be approved by Architect
- Soot down any repairs to match existing.

Stone

• Carefully brush clean stonework - remove moss and stain and repoint as necessary.

Leadwork

 Carefully investigate roof leadwork once safe access is established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.

Drainage

- Remove redundant services.
- Repair/replace damaged pipes as necessary.
- Clear all the blockages
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
- All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.

## ATES LIMITED

CHARTERED ARCHITECTS PLANNING CONSULTANTS

Cmail: london@insall-architects.co.uk

Job JS27.02	Status P					
No 2201	Rev	F				
Scale (A3) 1:	1	2	5			


- - ٠
- ٠
  - Stone •
  - Leadwork

  - Drainage
  - ٠ ٠

  - .
- remove modern skylight New painted timber windows to existing opneing
  - New painted timber french window



II





12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Email: london@insall-architects.co.uk

**Job** 27 John Street & 21 John's Mews

Title Proposed Front & Rear Mews Elevation

©2013 DONALD INSALL ASSOCIATES LIMITED

notes on windows in Mews

٠

remove existing boading and replace with lead

remove existing modern metal windows and replace with new sash

windows with traditionally detailed painted timber double glazed windows

Last saved on 12/03/2015 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2202 proposed front & rear mews elevation.dwg by ERH

Rev

## General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where necessary in matching mortar.
- Carefully brush clean brickwork to remove moss and staining where necessary.
- Replace mismatching brickwork with second hand bricks to match existing - sample must be approved by Architect
- Soot down any repairs to match existing.

Carefully brush clean stonework - remove moss and stain and repoint as necessary.

• Carefully investigate roof leadwork once safe access is established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.


- Remove redundant services.
- Repair/replace damaged pipes as necessary.
- Clear all the blockages
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
  - All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.



Job JS27.02	Status P						
No 2202	Rev	D					
Scale (A3) 1:	1	2	5				

CHARTERED ARCHITECTS


PLANNING CONSULTANTS



Scale (A3) 1: 1 2 5




0.	NOTES (STATU	S: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING	DONALD INSALL ASSOCIATI					
	For construction	a use only if status 'C' and checked against current revision	F	24/03/2014	TJB	ACS	Lower ground floor level lowered by height of one step	   12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Email: lo
2	All dimensions to be checked on site by contractor		Е	10/03/2014	SZP	ACS	Ground floor Mews rear wall aligned with Mews walls above.	- 12 Devolishine Street London W1G /AD Tel: 020 /245 9888 Email: R
}	Do not scale from this drawing			17/02/2014	JXA	ACS	Re-submission of planning issue	<b>Job</b> 27 John Street & 21 John's Mews
ŀ	Unless otherwise indicated all dimensions are in millimetres		С	10/01/2014	JXA	ACS	Reinstatement of existing light well, reduction in size of Mews extension	
			В	05/09/2013	JXA	ACS	Planning Issue and alterations to ceiling heights	<b>Title</b> Proposed Section A
			А	29/08/2013	JXA	ACS	Adding Notes and alterations to ceiling heights, room sizes etc.	
Н	12/03/15 ERH	ACS Basement extension removed	-	01/08/2013	AXT	ACS	Initial Issue	
G	25/06/14 TJB	ACS Car stacker converted to garage and store	Rev	Date	Dwn	Auth	REVISIONS	]




©2013 DONALD INSALL ASSOCIATES LIMITED

Last saved on 12/03/2015 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2301 proposed section b.dwg by ERH

Job JS27.02	Status P					
No 2301	Rev	Н				
Scale (A3) 1:	1	2	5			







Notes:										Drawing Status	Job Title:
1 Any dwg format drawing is to be read only in conjunction with and at the										F Feasibility	07.1
scale of the accompanying pdf.										S Sketch Design	27 J
2 Status 'C' drawing (Construction): All dimensions are to be checked on site by the contractor, scaling is for							-	-		D Design	1
Planning purposes only.										P Planning	1
Unless otherwise indicated, all dimensions are in millimeters.											Drawing
All information on this drawing is to be read in conjunction with the										B Building Control	5
relevant Donald Insall Associates specification and trade contractors'			_				-	-		W Working Drawing	Dart
drawings and information by specialists.										M Measurement	1 arg
<ul> <li>In the event of any query, please contact us immediately.</li> <li>This drawing contains survey information by others and is to be used</li> </ul>										T Tender	As P
4 This drawing contains survey information by others and is to be used solely for the purposes for which it was issued.					-	16/06/1	7 TO	BAC	S ISSUED FOR PLANNING	C Construction	731
© 2017 DONALD INSALL ASSOCIATES LTD	Rev	Data	Dur	Auth Revision	Rev	_	_	_		R Record	1
© 2017 DONALD INSALL ASSOCIATES LTD	Rev	Date	Dwn	I Auth Revision	Rev	Date	Dwr	n   Autr	n Revision	K Kecolu	1

Existing 20th Century floorboards. Minimum 21mm softwood flooring fixed through plasterboard to one side of channel with 55mm GypFloor SIF5 Floor Screws

19mm Gyproc Plank cut to fit between floor channels with in-built resilient layer with 3mm gap to vertical flange of floor channel

Existing timber floor joists, shown indicatively.

12.5mm Glasroc F MULTIBOARD

100mm Isover insulation

Two layers of 15mm Gyproc Soundbloc plasterboard.

	0		50	10	0		250
Purpose of Issue: FOR PLANNING	So	cale	1:5				mm
itte: John Street, London			ld In:				
ng Title:			ire Street, 245 9888				.co.uk
rty Floor/Ceiling Detail	Project	JS2	7	N	lo 34	01	
Proposed	Scale			S	tatus	Re	ev
	(A3) 1	. 5			P		