



ST GILES IN THE FIELDS CHURCHYARD dotted, all to strucutral engineeers design length of wall to be repaired CAR PARKING AREA 45 NEW COMPTON STREET OVERALL SITE PLAN



TYPICAL SECTIONAL ELEVATION







TYPICAL BUTRESS PLAN



Whymark & Moulton

Chartered Surveyors & Building Engineers

14 Cornard Road, Sudbury, Suffolk. CO10 2XA

The Association of BUILDING ENGINEERS

BOUNDARY WALL REPAIRS 45 NEW COMPTON ST LONDON WC2H 8DF

ENGINEERING PLAN

1:20, 1:50

Oct 2019

Drawing No 13/160 - 03

SIDE ELEVATION OF STEEL BUTTRESS AND FOUNDATION

FRONT VIEW OF BUTTRESS AND PAD FOUNDATION