



Principal Elevation: East

 BOWKER SADLER PARTNERSHIP LIMITED
 THIS DRAWING IS THE SUBJECT OF COPYRIGHT WHICH VESTS IN BOWKER SADLER PARTNERSHIP LIMITED. IT IS AN INFRINGEMENT OF COPYRIGHT TO REPRODUCE THIS DRAWING, BY WHATEVER MEANS, INCLUDING ELECTRONIC, WITHOUT THE EXPRESS WRITTEN CONSENT OF BOWKER SADLER PARTNERSHIP LIMITED WHICH RESERVES ALL ITS RIGHTS

RESERVES ALL ITS RIGHTS

BOWKER SADLER PARTNERSHIP LIMITED ASSERTS ITS RIGHTS TO BE IDENTIFIED AS THE AUTHOR OF THIS DESIGN

REPORT ERRORS & OMISSIONS TO ARCHITECT.
 CHECK ALL DIMENSIONS ON SITE
 DRAWING TO BE READ IN CONJUNCTION WITH THE HEALTH AND SAFETY PLAN AND ALL RELEVANT RISK ASSESSMENTS

Survey drawings are kindly provided by Malcom Hughes Land Surveys Ltd and are assumed

to accurately describe the existing buildings, services and external spaces.

Features

bhc bottom hung casement window

thc top hung casement window

vss vertical sliding sash window

shc side hung casement window

tt tilt and turn window

fl fixed light window

fl fixed light window

frl roof light (flat roof)

vrl velux style roof light (pitched roof)

h ceiling hatch

sd sliding door

sliding door

pd pivot door

new wall / roof mounted flue to gas boiler / gas fire. terminal colour is powder coated bronzed

abx new extract terminal as air brick, such as rytons rd4mfab, colour coded to suit brickwork

frx mushroom extract terminal for flat roof

prx fabricated lead pitched roof vent as extract terminal, such as provided by o'brien sheet

lead fabrications Itd

note: existing windows are generally timber frames with leaded glazing (single glazed) and fine painted metal sashes. some metalwork has been replaced with painted timber to mimic the original sash.

on the north and the west elevations of the main house the windows are simpler with single glazing and painted timber frames. there are a pair of painted metal frame windows on the north elevation

the timber casement windows found on the annexe will be replaced by low profile double glazed units with an anodised bronzed aluminum frame existing building fabric and structure, including roofs, tiling, masonry, windows, and rainwater goods are to be maintained and

repaired/refurbished where necessary. the conditions survey will form the

basis from which the maintenance works will be scheduled and agreed.

PROJECT
The Hoo,
17 Lyndhurst Gardens,
Hampstead, London
Returning A Grand Victorian House To Private Domestic Accommodation
NW3 5NU

Mr and Mrs Yu
REPRESENTED BY
JAGA Developments (London)

South and West Elevations as Proposed

SCALE SHEET SIZE DRAWN CHECKED DATE

1:50 @ A0 GMcG Oct 2019

BOWKER SADLER ARCHITECTURE

A: Hatherlow House, Hatherlow, Romiley, Stockport SK6 3DY
T: 0161 406 7333

E: bsp@bowker-sadler.co.uk
W: www.bowker-sadler.co.uk

JOB No DRAWING No REVISIO A STATUS FOR PLANNING

DATUM 84.000