

<b>Application No:</b>	<b>Consultees Name:</b>	<b>Received:</b>	<b>Comment:</b>	<b>Response:</b>
2019/5832/P	Mrs A Gager	18/12/2019 15:58:39	OBJ	Why can't a stair lift be installed inside this property, thus preventing the destruction of the uniformity of the mews? This was done previously at our address in Fairfax Place, to overcome the same difficulties from which Mr Eden now suffers. Adding a side extension to incorporate a lift shaft, will completely ruin the special appearance of this cobbled street, where orderliness and neatness are at the heart of its charm.

---