




| Source                     | Drawing Number  | Rev |
|----------------------------|---|-----|
| Saunders Boston Architects | PS01001-SBA-XX-B1-DR-A-0023_RevC1_GA Plans_Basement       |     |
| Saunders Boston Architects | PS01001-SBA-XX-00-DR-A-0024_RevC1_GA Plans_Ground         | C1  |
| Saunders Boston Architects | PS01001-SBA-XX-ZZ-DR-A-0025_RevC1_GA Plans_First & Second | C1  |
| Saunders Boston Architects | PS01001-SBA-XX-ZZ-DR-A-0026_RevC1_GA Plans_Third & Roof   | C1  |













## Indicates A Residual Risk As A Warning

The design team have highlighted unusual and significant risks that may not be obvious to a competent contractor. They are to assist with risk reduction only and are not necessarily comprehensive. It is assumed that all works will be carried out by a competent contractor working, where appropriate, to an approved method statement.

## FIRE ALARMS

SD SMOKE DETECTOR

SMOKE DETECTOR WITH SOUNDER

SMOKE DETECTOR WITH SOUNDER AND BEACON

HEAT DETECTOR

HEAT DETECTOR WITH SOUNDER

HEAT DETECTOR WITH SOUNDER & BEACON

MD MULTI-FUNCTIONAL DETECTOR

MULTI-FUNCTIONAL DETECTOR WITH SOUNDER

MULTI-FUNCTIONAL DETECTOR WITH SOUNDER & BEACON

MANUAL CALL POINT

WALL MOUNTED FIRE BEACON

FAP FIRE ALARM PANEL

FARP FIRE ALARM REPEATER PANEL

FAI FIRE ALARM INTERFACE

| C7   | Mods As Shown                                  | NB    | GD    | 21-11-19 |
|------|--|-------|-------|----------|
| C6   | BGU's relocated, detection removed from vaults | AB    | GD    | 18-11-19 |
| C5   | Detection added to cupboard                    | AB    | GD    | 12-11-19 |
| C4   | Updated to Fisk Comments                       | АВ    | GD    | 25-10-19 |
| C3   | Updated to Fire Strategy                       | NB    | GD    | 21-10-19 |
| C2   | Construction Issue                             | NB    | GD    | 09-09-19 |
| C1   | Construction Issue                             | JB    | GD    | 19-08-19 |
| rev. | description                                    | drawn | chkd. | date     |



Carmel (UK) Limited

Midland House, Midland Place
Barlborough
Chesterfield
Derbyshire S43 4FR

Tel.: +44 (0) 1246 575 800 Fax.: +44 (0) 1246 575 801 e-mail: chesterfield@carmel-uk.com

Unit A, Blenheim House
 1 Blenheim Road
 Epsom
 Surrey
 KT19 9E

Tel.: +44 (0) 1246 575 800
Fax.: +44 (0) 1372 746 301

e-mail: epsom@carmel-uk.com

Client

University College London

Address

91 Gower Street

Fire Alarm Systems All Floors Stage 4

Drawing N°.
6000 - DRG - ZZZ - ZZ - DR - E - 6700

 Project №.
 Scale
 Revision

 1790
 1:100@A1
 C7

Final Check For Issue
(uncontrolled copy unless signed)

CONSTRUCTION

Initials

Signature

0 1 2 3 4 5