

	CONSULTANTS		NOTE	LOCATION
	CLIENT:	WESTBROOK PARTNERS/ 1921 Mortimer Investments Limited	<ol> <li>Do not scale from this drawing.</li> <li>All dimensions to be checked on site by the contractor and such dimensions to be his responsibility.</li> <li>Report all drawing errors, omissions</li> </ol>	
	STRUCTURAL ENGINEER:	HEYNE TILLETT STEEL		
	MECHANICAL ENGINEER:	THORNTON REYNOLDS	and discrepancies to the architect. 4. This document may be issued in an	
	COST CONSULTANT:	LESLIE CLARK	uncontrolled CAD format to enable others to use it as background	
	PROJECT MANAGER:	RADCLIFFES CC	information to make alterations and/or additions. In that instance the file will be accompanied by a PDF version. It is for those making such alterations and additions to	
	FIRE ENGINEER:	AFFINITY FIRE		
	APPROVED INSPECTOR:	BRCS		
	PLANNING CONSULTANT:	DP9	ensure that they make use of current background information.	
	DAY LIGHT/ SUNLIGHT:	POINT 2 SURVEYORS	AHMM Ltd accepts no liability for	
	PARTY WALL CONSULTANT:	POINT 2 SURVEYORS	any such alterations or additions to the background information or arising	1
-	RESIDENTIAL ARCHITECT	COVE BURGESS	out of changes to background information which occur prior to alterations of additions being made.	
		1		/