

From: John Malet-Bates [REDACTED]
Sent: 08 April 2020 21:19
To: Constantinescu, Nora-Andreea
Subject: 2019/6387/P:Lyndhyrst Hall, Lyndhurst Road.

Follow Up Flag: Follow up
Flag Status: Flagged



Dear Nora,
Hope you and your's are OK.

HCAAC has caught up with this having not covered at meeting due to then lack of documents on the site.

HCAAC Objects to the roof form of the proposed replacement infill.
The existing barrel vault roof was carefully designed and detailed to fit within the constraints of the existing building wings and different masses.

We consider a similar effort is required for this proposal to avoid a missed design opportunity.
The new roof form could and should relate to the two different roof heights of the enclosing wings and would definitely be an innovative form and texture.
It should eschew roof glazing whose purpose is irrelevant and compromising both to the adjoining wings and attempts to reduce light pollution.

Sent temporarily from my gmail account while access to TalkTalk email is repaired on my system.
Please reply to [REDACTED]

Best regards,
John

John Malet-Bates
for Hamnstead CAAC
[REDACTED]