



- J. VP ADDED ADJACENT TO LIFT SHAFT
- POSITION OF THERMOSTATS CORRECTED
- POSITION OF SVP TO REAR OF NO. 30 REPOSITIONED
- ADJACENT TO W1.13 - SINK SOIL PIPE ALTERED
- POSITION OF CONSUMER UNITS ALTERED TO SUIT WHICH CHIMNEY BRICK TO REAR OF CENTRAL CORE SHOWN ON BACK
- H. HEIGHT OF FALSE CEILING IN BATHROOMS 5.03, 5.02 INDICATED
- SIZE OF SERVICE DUCTS CORRECTED NOTES ADDED 500mm DIA. ADDED BED 1
- THICKENING OF WALL IN ROOM 6.07 CORRECTED
- POSITION OF WATER TANKS CHANGED POSITION OF 2 HATCHES SHOWN 10.9.85
- G. 6.08.85 POSITIONS OF RISERS IN CENTRAL CORE SHOWN CORRECTED
- POSITION OF SERVICE DUCTS + BOILERS LOCATED SIDE + POSITION OF RADIATORS CORRECTED ACCORDING TO SCHEDULE
- F. NOTES ADDED POSITION OF G.W.S.T. WVP ADDED BEDROOM 2, RATS 24-6.85
- E. UPDATING OF KITCHEN LAYOUTS
- THICKENING UP OF RIGHT-HAND INTERNAL WALL OF BEDROOM 3 + RIGHT-HAND WALL OF CENTRAL STAIRS. NOTES + DIMENSIONS ADDED POSITION OF FLUES ADDED NOTES REMOVED 19/6/85
- D. DIMENSIONS ADDED K/S/85
- C. 17.2.85. DIST. STAIRS 2.700
- B. 19.3.85. CORRECTED SHOWN
- A. 14.2.85. REVISIONS TO ALL PLANS

REVISIONS

Michael Manser Associates
8 Hammersmith Broadway London W6 7AL 01-741 4381

contract **TP8501805**
38+40 ETON AVENUE
LONDON NW3

drawing
PROPOSED FIRST FLR PLANS

scale **1:50** date **oct 84**

number **562/L/32** revision **J**