



- REVISIONS
- F 6/10/85 POSITION OF ELECTRICAL SUPPLY BOX ADDED
 - NEW LEFT FLANKING WALL TO CENTRAL CORE CHANGED FROM A CAVITY WALL TO 9" BRICK POSITION OF GUTTERS SHOWN & DETAILS KEPT IN
 - FADE OF W3.3 CHANGED SO AS BALCONY IS 100% W3.3 CHANGES FROM A SINGLE GLAZED DOOR WITH SIDE LIGHTS TO A WINDOW
 - 100MM SVP ADJUNCTION TO LIFT SHAFT REMOVED & DRAINAGE RUN FROM BATHROOM SLOTT ALTERED TO BE PICKED UP FROM SVP BELOW
 - E POSITION OF DOORS IN CENTRAL CORE STAIR AMENDED 6/18/85
 - POSITION OF BOILER SERVICE DUCT ADDED SIZE OF RADIATORS CORRECTED
 - D POSITION OF C/WISTS SHOWN UNDER ADD'D STEPS ON TO 2H & 85 ROOF TERRACE AMENDED POSITION OF ROOFLIGHT ACCESS WHICH ADDED
 - C 19/6/85 DIMENSIONS & NOTES ADDED LIVING ROOM EXTRA RISER ADDED TO BOTTOM OF SPIRAL STAIRCASE STEPS AROUND RANGE OF STAIRCASE REMOVED
 - B 27/6/85 FINISH TO ROOF TERRACE
 - A 4/7/85 FINISH TO ROOF TERRACE
- 8.5.01865

Michael Manser Associates
 8 Hammersmith Broadway London W6 7AL 01-741 4381

contract
 38+40 ETON AVENUE
 LONDON NW3

drawing
 PROPOSED THIRD FLOOR+GALLERY PLANS

scale 1:50 date oct '84

number 562/L/34 revision F