




PICTURE 3 at Conservation Plan by Murray John Architects (prior 2011) Reproduction to be specified by specialist.





FIREBOX TO BE RESTORED

PICTURE 5 taken by BDP (2012)

EXISTING CHIMNEYPIECE IN SAFE STORAGE TO BE CAREFULLY REINSTATED

1.04 Reception Room fireplace to be reinstated, as recorded in this picture:

FIRST FLOOR

STONE HEARTH TO BE REINTEGRATED

STONE HEARTH TO BE REINTEGRATED




PICTURE 6 taken by BDP (2012)





DRAWN CHECKED DATE



PROPOSED REINSTATEMENT OF ORIGINAL FIREPLACES

A complete damage assessment and work proposal to reinstate the stored parts of the fireplaces will be made by the Constructor and approved by the

A. RECEPTION ROOM FIREPLACE

(A) Existing fireplace in safe storage to be reinstated

FIREBOX TO BE RESTORED

PICTURE 1 taken by BDP (2012)



STONE HEARTH TO BE REINTEGRATED

PROPOSED REINSTATEMENT OF ORIGINAL **FIREPLACES**

A complete damage assessment and work proposal to reinstate the stored parts of the fireplaces will be made by the Constructor and approved by the

A. LIVING ROOM FIREPLACE

Clean and repair existing firebox and reintegrate original hearth.

Identify original location of storaged parts of as per the attached PICTURE 4.

Clean, repair and carefully reinstate original pieces to their original location. And add new pieces, in a like for like basis, when missing or not able to be repaired.

Redecorate painted elements, using same color and type of pinture, as exisiting.

DINING ROOM FIREPLACE

by specialist.

Reintegrate original hearth (if existing). Reproduction of original chimneypiece to be reinstated as recorded PICTURE 3, specified

AS CONSENTED ref: 2017/6975/L

16 Brewhouse Yard

London, EC1V 4LJ

T +44 (0)20 7812 8000

F +44 (0)20 7812 8399

United Kingdom

www.bdp.com

Clerkenwell

BUILDING DESIGN PARTNERSHIP LTD SHALL HAVE NO RESPONSIBILITY
FOR ANY USE MADE OF THIS DOCUMENT OTHER THAN FOR THAT
WHICH IT WAS PREPARED AND ISSUED

ROOM FINISHES KEY ALL DIMENSIONS SHOULD BE CHECKED ON SITE DO NOT SCALE FROM THIS DRAWING. ANY DRAWING ERRORS OR DIVERGENCES SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP LTD AT THE ADDRESS SHOWN.

BROKEN GLASS TO BE REPLACED LIKE FOR LIKE

DRAWN CHECKED DATE REVISION / DESCRIPTION

DRAWN CHECKED DATE REVISION / DESCRIPTION DRAWN CHECKED DATE DRAWN CHECKED DATE REVISION / DESCRIPTION DRAWN CHECKED DATE REVISION / DESCRIPTION

MN MB 14.12.2017 - LBC APPLICATION - DRAFT FOR COMMENTS MN MB 08.12.2017

FIREPLACES REINSTATEMENT AS PROPOSED