				Printed on:	15/06/2020	09:10:08
Application No:	Consultees Name:	Received:	Comment:	Response:		
2020/1452/P		14/06/2020 16:28:03	OBJ	The roofs of these garages and the first garage can be seen from Swain, s. Lane. This application for the second garage to replace slatted metal garage door with inappropriate brick, door and window will set an unfortunate precedent. If other garages follow suit the outcome will be an untidy mix of infills causing visual harm to the conservation area. The proposed drawings for a children playroom are perplexing; there is a long staircase with no protective handrail, a mezzanine with 1.5m headroom, disappearing roof rafters, a door leading to outside and bare oversight from the host building. If the council is minded to approve this application the rooflights should be conservation type and colour to blend with roof.		