				Printed on: 04/08/2020 09:10:05
Application No:	<b>Consultees Name:</b>	Received:	<b>Comment:</b>	Response:
2019/3406/P	Roland Hayes	31/07/2020 14:50:13	COMNOT	The stair enclosure/extension is cantilevered and as such freestanding from the rear of 18 Princeton Street with a gap of between 100-180mm to allow air brick venting. This gap is a natural collection / trapping point for debris ¿ how will keeping this clear of rubbish be prevented?
				There is no detail of the Fire Rating status of the proposed glazing adjacent to the rooflight and rear ground floor window of 18 Princeton Street.