


KEY

1 Existing 200mm individual letter signage to be removed and make good


- Existing frosted vinyl applied on windows
- ③ Existing branch main entrance
- ④ Existing redundant letter box to be sealed internally
- 5 Existing entrance to adjacent building
- 6 Existing 570mm projecting sign to be removed and make good







PLANNING



CLOSURE 2021

| Branch Sort Code    | e Branch ID     | Supplier Project | No         |
|---------------------|-----------------|------------------|------------|
| 20-44-86            | 04              | BY106570         |            |
| Scale               | Drawn           | Checked          | Date       |
| 1:100@A3            | PC              | -                | 18/02/2021 |
| Drg.No BY106570_032 |                 |                  | Revision   |
| ° BY106570_032      |                 |                  | -          |
| Architectural       | Practice: ISG E | )esign Hub       |            |
|                     |                 |                  |            |