

3 Russell Road, Flat n.2
Kensington & Chelsea - London, W14 8JA
Email:info@asparchitects@co.uk
Website: www.asparchitects.co.uk
PH.N.: +44 02030341350



FIRE RISK ASSESSMENT

Location: 1-6 Speedy Place, London, WC1H 8BU

Local Authority: Camden Council

Client: Newmake Properties Ltd, 245 Whitton Avenue East, Greenford, UB 0QQ

Architectural Consultant: ASP Architects London Ltd, 3 Russell Road, Flat n.2, London W14 8JA

Conducted on: 10/01/2022









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350





Existing Building "Front Elevation"



Existing Building "Side & Rear Elevation"

ASP ARCHITECTS LONDON LTD








3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350





Proposal "Front Elevation"



Proposal "Side & Rear Elevations"

ASP ARCHITECTS LONDON LTD









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



Contents:

1.	Introduction	Page 5
2.	Premises Particulars	Page 6
3.	General Statement of Policy	Page 6
4.	Management System	Page 6
5.	General Description of the Premises	Page 7
6.	Fire Safety System within the Premises	Page 9
7.	Plans-Drawings of the Premises	Page 10
8.	Identify Fire Hazards	Page 11
9.	Management – Maintenance Plan	Page 12
10.	Emergency Action Plan	Page 13
11.	Training & Calling Fire Services	Page 14
12.	Fire Safety Management Plan	Page 14
13.	Emergency Action Plan	Page 15
14.	Conclusion	Page 15









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



1. INTRODUCTION:

The site visit (1-6 Speedy Place, WC1H 8BU) was carried out on Monday 10/01/2022 to ascertain the current situation of the building and the proposed development change of use from the current Class Order E to a new Class Order C3 (creation of n. 4 residential Units).

ASP will recommend and suggest to follow & ensuring sufficient & suitable level of protection of the building in compliance with the endorsed regulations:

- Building Regulations 2019 edition, Approved Document (B), Fire Safety: Dwellings
- The Regulatory Reform n.1541 (Fire Safety) Order 2005

The current building is vacant since March 2021, as per declaration by email "cited on Design Statement" by the Landlord Mr. & Mrs Tardioli and the neighbour BOOT PUB, Mrs Sharon Winder

The Proposed development: Change of use of the existing commercial unit (Class Order E) to residential units (C3) consisting of 4 flats on the ground and first floors and associated internal alteration and external treatment to the front and rear elevation. Opening a new window at Ground Floor, replacing an external door with door/window

This Fire Risk Assessment is requested by Local Authority "Camden Council" as per response of the Prior-Application received on date **08/12/2021** with letter Ref. N.: **2021/4826/P**. Therefore, this report to support the presentation of a new Full Planning Application.

The main aim of the client for this development consisting as a private investment, and each flat will be rented to private tenants. It is presumed they will all be able to Self-Evacuate without assistance should it be required

The building is at present served by two staircases, both of timber construction. One located to the left side of the building and one centrally. It is planned in the new proposal development to remove the left side stair, resulting the Ground Floor Flats n. 1 & 2 Have independent entrance and flats at First Floor n. 3 & 4 being accessed via a central single common stair. The final exit door will discharge onto the access walkway of Speedy Place leading occupants to Cromer Street

Once the development works are completed in the building, then the a FIRE SAFETY POLICY for the building would be communicated and distributed to all occupants/tenants and displayed within the common parts of the building

The development will create a small single stair, small building (below 11 meters in height) with two general needs self-contained flats per floor on the Ground & First Floors, and be constructed in such a way that will be capable of supporting a "Defend in Place, Stay-Put" fire strategy in accordance with current Building Regulations











3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



2. PREMISES PARTICULARS:

The Fire Safety Officer & the company that will be in charge for the fire safety assessment and control of the building will be assigned by the Client Newmake properties Ltd after the refurbishment works completion

Premises Name	1-6 Speedy Place	Use of Premises: Residential Units n. 4 Flats				
Address	1-6 Speedy Place London, WC1H 8BU	Owner/Employer/person in Control of the Residential Units:				
Tel No.	07555710050	Newmake Properties Ltd - Mr. Anwar Akbar				
Date of Risk Assessment	10/01/2022	Date of Review: 10/01/2023				
Name & relevant details of the person who carried out the Fire Risk Assessment Mr Sami Almaqableh, Company: ASP Architects London Ltd "The Employer after refurbishment works completion, He will appoint a Health and Safety Adviser"						

3. GENERAL STATEMENT OF POLICY:

It is a policy of the company Newmake Properties Ltd to protect all persons including employees, customers, contractors, and members of the public from potential injury and damage to their health which might rise from activities in the building.

The Company will provide & maintain a safe and healthy habitant environment, and security for all tenants, and to provide such information, training and supervision as they need for the purpose

4. MANAGEMENT SYSTEM:

The Fire Safety Management plan is contained within the Health & Safety File and will be kept in the Health & Safety Advisors office. A schematic is attached. It confirms that a fire risk assessment will be completed to ensure adequate fire safety and will be reviewed as necessary. The fire risk assessment will follow the 5- step narrative method as advocated by the Employers Guide. The significant findings will be recorded. Any deficiencies identified by the fire risk assessment process will be prioritized and rectified accordingly. Although having overall responsibility for fire safety matters the Employer has made the Health & Safety Advisor responsible for fire safety matters which includes the fire risk assessment and all matters appertaining to it. This person will be responsible for:

ASP ARCHITECTS LONDON LTD









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



- Deciding the fire safety protective and preventative measures
- Informing other responsible persons what they are
- Ensuring they are implemented and communicated to other employees
- Ensuring co-ordination between other responsible persons Fire Safety will be an agenda item for the weekly managers meeting. The other responsible persons are shown on the schematic (attached). They will be responsible for the fire safety measures as shown. The Health & Safety Advisor will be responsible for monitoring the effectiveness of the fire risk assessment process and its implementation.

5. GENERAL DESCRIPTION OF PREMISES:

5.1 DESCRIPTION OF THE EXISTING BUILDING:

The building was used for offices (E) old Class Order B1, since March 2021, and now is vacant, comprises of an old, long two storey; Ground Floor and First Floor with flat roof, brick built on front & side elevation, the rear elevation with rendered brick.

The general condition of the building is decent, except the rear elevation which is in precarious and degradant situation. The internal space is divided by Gypsum Board partition to create different offices spaces and meeting rooms.

However, in the event of fire, there is low risk because the entire two floors empty without any furniture. The building has two internal timber stairway, one central and one at side left of the building, which are protected by fire resisting walls, partition, and doors. It has two external escape staircases leading from the First Floor to Ground Floor. The final exit door will discharge onto the access walkway of Speedy Place leading occupants to Cromer Streets.

Occupancy:		Size:		
Time the premises in use:	VACANT	Building Footprint:	~ (23 x 4.75 m) =109 sq.	
The Total number of persons Employed within the Premises at any one time	0	Number of Floor:	2	
The Total Number or Persons who May Resort to the Premises at any one time	0	Number of Stairs:	2	

5.2 DESCRIPTION OF THE PROPOSAL DEVELOPMENT:

The proposal development consisting of creating a new Four Flats, Two Flats at Ground Floor and Two Flats at First Floor. The flats typology would be classified as One Bedroom Flat. Each flat would have one bedroom, Living/Kitchen, bathroom & Store (as shown in attached below plans).

- Provide an inner protected entrance hall in each flat (minimum REI 30) serving all habitable rooms with a maximum travel distance from the furthest internal fire resisting door to the entrance door of 9 metres.
- Provided lobby protection between the flat entrance doors and common stair will be provided. In small single stair buildings with no more than two flats per floor, lobby protection between the flat entrance









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



door & the common stair can be provided as long as all flats have inner protected entrance halls. So the requirement for inner protected entrance halls will apply in this case

- The travel from the flat entrance door (First Floor) to any habitable room can be a distance of 9 meters. Cooking area (Kitchen) facilities must be remote from the flat entrance door and should not impede the escape route from anywhere in the flat.
- Provide and ensure that the common escape route is constructed to provide 60 minutes fire resistance. In addition, 60 minutes fire resistance but provided between all flats, including the floor plate between the Ground Floor and First Floor.
- The Building Technical Room would be located on the Ground Floor, accessed from the proposed common parts, the room must be constructed to provide 60 minutes of resistance.
- All flat entrance doors must conform to FD30s standard and be fully self-closing via a self closing device
 that conforms to BS EN 1154. The correct operation of self-closing devices on flat entrance doors is a key
 component in maintaining a clear means of escape and preventing the spread of smoke and heat. This
 issue is of the first importance in buildings containing residential flats, regardless of the evacuation policy
 in operation.
- Provide a Fire Extinguisher to be located in Ground floor common area; the extinguisher will be as the followings:
 - Water
 - Dioxide Carbon CO2
 - o Dry Powder
 - o Foam Spray

And to provide a few Two Extinguisher at First Floor located on corridor and will be as the followings:

- Water
- Foam Spray
- it is probable that some smoke will get into the common parts from a fire in a flat. There should therefore be provisions provided to allow the Fire & Rescue Service to ventilate the common parts to control smoke and protect the common stair escape route. This means of ventilation offers additional protection to that provided by the fire doors to the stair. In a small, single stair building such as this, smoke ventilation can be achieved in one of the two following ways:
 - o A high-level openable vent with a free area of at least 1m2 at each storey
 - A single openable vent with a free area of at least 1m2 at the head of the stair, operable remotely at Fire & Rescue service access level

However, in small single stair buildings where lobby protection between the common stair & dwellings is omitted, an automatic opening vent (AOV) with a free area of 1m2 is required the head of the common stair, operated by non-sounding detection of smoke at any storey in the stair

• Each individual flat must be installed with the following domestic fire alarm system:

Grade D1: LD2 (BS 5839 Pt 6) coverage.

Category LD2: A system incorporating detectors in all circulation areas that form part of the escape route from the flat, and in all specified rooms or areas that present a high fire risk to occupants, including any kitchen and the principle habitable room. For example:

- Hallway
- Living room
- Kitchen (Heat detector)


ASP ARCHITECTS LONDON LTD







3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



• A suitable level of emergency escape lighting should be installed throughout the common stair in accordance with BS 5266.

• As the common escape route will neither be long nor complex, it is not considered necessary for fire exit signage to be installed

• On completion of the refurbishment of the building, the fire safety policy for the building should be communicated to all occupants. In addition, they should be displayed within the common parts.

Occupancy:

Time the premises in use: RESIDENTIAL UNITS

The Total number of persons/Tenants 4-8 within the Premises at any one time

The Total Number or Persons who May 8 Resort to the Premises at any one time

Size:

Building Footprint: $(23 \times 4.75 \text{ m}) = 109 \text{ sq.}$

Number of Floor: 2

Number of Stairs: 1

6. FIRE SAFETY SYSTEM WITHIN THE PREMISES:

Fire Warning System:

- Automatic Fire Detection, break glass system to BS 5839
- Domestic Fire Detection System & Alarm system to BS 5839-6 (2019)
- Manual Electric complying to BS 5839, AFD has been provided in a number of areas

Emergency Lighting System:

Non-Maintained to 3 Hours complying with BS 5266

Fire Fighting Equipment & Fire Safety Signs

- Fire Extinguishers: Type of Extinguishers to be allocated on each floor
- Ground Floor Common Area: Dioxide Carbon CO2, Dry Powder, Water, Foam Spray
- First Floor Stair Corridor Area: Dry Powder, Water
- There will be adequate Fire Safety signs and notices in the premises. All exit routes and fire safety equipment's are adequately signposted
- NON-Sprinkler system to LPC rules BS 5306

ASP ARCHITECTS LONDON LTD








3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



7. PLANS-DRAWINGS OF THE PREMISES:

The below plans refer to the proposed development at Ground Floor and First Floor, therefore, if there is any request to improve the proposed system, then the client would be happy to meet that request



ASP ARCHITECTS LONDON LTD







3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



8. IDENTIFY FIRE HAZARDS:

Sources of Ignition:

The ignition sources are commensurate with residential unit's premises, there are no significant ignition sources within the building.

Smoking will not be allowed inside the building

Sources of Fuel:

The sources of fuel are those commensurate with daily flats activity. Majority of the activity is completed in two spaces; Kitchen and Living area, so there are no vast activity or movements in the space and will be circumscribed.

Daily waste bins are emptied every night and the waste stored away (waste area) from the building in recycle bins for each flat.

Work process:

The work process is commensurate with flats premises, therefore, there are no process that pose a significant fire hazard, except some use of kitchen appliances such as; Electric Oven, Microwave and other tools for daily kitchen uses

It will be a service level agreement with an outside contractor; Electrical, Plumbing, IT for maintenance, monitoring and control of the building and its appliances.

The Electrical/Gas & Water meters and other tools will be in Technical Room and Common Area. The area is closed by security code, which will be provided to the sub-contractors and tenants in case of any emergency intervention

The company policy will provide a regular visit to the building to ensure the state of building and ascertain about fire safety and wellbeing of the tenants

Structure Features that Could Spread the Fire:

The building is an old construction, but still solid, due to the construction system of the perimeter of double brick walls and no voids internally or externally.

All services and compartments are adequately fire stopped, through doors with FD30 & FD60

The new windows and doors will comply with the endorsed legislations, in particular the building regulations 2010 Approve Documents.

ASP ARCHITECTS LONDON LTD







3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



9. MANAGEMENT - MANENANCE PLAN:

Will be a maintenance program for the fire safety provisions for the premises?	YES	NO
Commentary: File records will be maintained with the fire safety logbook		
Will be a regular check of fire resisting doors, walls and partitions carried out?	YES	NO
Commentary: Carried out by the services manager and recorded		
Will be a regular checks of fire safety signs carried out?	YES	NO
Commentary: Carried out by the services manager and recorded		
Will be a regular maintenance regime for the fire warning system?	YES	NO
Commentary: Bi-Weekly carried out by the services manager and recorded & a complete annual check of the system will be carried out by external Contractors appointed by the Employer and recorded		
Will be a regular maintenance regime for the emergency lighting system?	YES	NO
Commentary: Bi-Weekly carried out by the services manager and recorded, & a complete annual check of the system will be carried out by external contractors appointed by the Employer and recorded		
Will be a regular maintenance regime for firefighting system? (By competent Person)	YES	NO
Commentary: Bi-Weekly carried out by Competent Person and recorded, & a complete annual check of the system will be carried out by external contractors (Competent Contractor) appointed by the Employer and recorded		
Are records & their location identified?	YES	NO
Commentary: The records for all aspects relating to maintenance issues will be kept in the service managers office		

ASP ARCHITECTS LONDON LTD








3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



10. EMERGENCY ACTION PLAN

The Emergency plan should be activated when there is a fire and immediately to follow the evacuation plan which identify the process and the route to assembly area for safety of occupants



ASP ARCHITECTS LONDON LTD







3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



11. TRAINING & CALLING FOR FIRE SERVICES:

TRAINING

Training is provided by the training manager that will be appointed by the Employer
A six-month meeting is held to reminded tenants what to do in the event of fire. Also included how to call
the Fire Service, and how to operate the fire alarm system
All person including the director manager to undertake this training

CALLING FOR FIRE SERVICES:

In case of fire, follow the instruction in evacuation plan and call immediately 911

12. FIRE SAFETY MANAGEMENT PLAN:

FIRE SAFETY PLAN:	RESPONSIBLE PERSON
Person with overall responsibility for Fire Safety	Mr
To be assigned the Employer	Position
	Managing Director
FIRE RISK ASSESSMENT:	RESPONSIBLE PERSON
Person responsible for:	Mr. Sami Almaqableh
Carrying out & Review	Position
After completion of the refurbishment works, the Employer will appoint a	Principle Designer
Health & Safety Advisor	
MAINTENANCE PROGRAM:	RESPONSIBLE PERSON
Person Responsible For:	
Maintenance of Fire Safety Provisions, Fire Alarm, Emergency	Mr
Lighting, Fire Fighting Equipment, Escape Routes & Fire Safety Signs	
& Notices	Position
To be assigned the Employer	Service Manager
EMERGENCY ACTION PLAN:	RESPONSIBLE PERSON
Person Responsible For:	Mr. Sami Almaqableh
Production & Review	Position
After completion of the refurbishment works, the Employer will appoint a	Principle Designer
Health & Safety Advisor	
STAFF TRAINING:	RESPONSIBLE PERSON
Person Responsible staff training:	Mr
	Position
To be assigned the Employer	Training Manager

ASP ARCHITECTS LONDON LTD









3 Russell Road, Flat n.2 Kensington & Chelsea - London, W14 8JA Email:info@asparchitects@co.uk Website: www.asparchitects.co.uk PH.N.: +44 02030341350



13. EMERGENCY ACTION PLAN:

ASSEMBLY POINT: CROMER STREET

ACTION ON DISCOVERY OF FIRE: -SOUND THE ALARM USING THE NEAREST FIRE ALARM CALL POINT

-LEAVE THE BUILDING BY THE NEAREST FIRE EXIT

-DO NOT RE-ENTER THE BUILDING -REPORT TO THE ASSEMBLY POINT

-CALL THE FIRE BRIGADE BY MOBILE PHONE (AFTER LEAVING THE

BUILDING)

-LIAISE WITH THE FIRE BRIGADE ON THEIR ARRIVAL

-ONLY ATTEMPT TO TACKLE SMALL FIRES IF CONFIDENT TO DO SO

-DO NOT PUT YOURSELF AT RISK

ACTION ON HEARING ALARM -LEAVE THE BUILDING BY THE NEAREST FIRE EXIT

-DO NOT RE-ENTER THE BUILDING -REPORT TO THE ASSEMBLY POINT

-CALL THE FIRE BRIGADE BY MOBILE PHONE (AFTER LEAVING THE

BUILDING)

-LIAISE WITH THE FIRE BRIGADE ON THEIR ARRIVAL

VISITORS -ENSURE ALL VISITORS AND CONTRACTORS ARE TAKEN TO THE ASSEMBLY

POINT

-ASSIST ANY DISABLED PERSONS WITH THEIR EVACUATION AS NECESSARY

14. CONCLUSION:

This Fire Risk Assessment is elaborated to be attached at Full Planning Application submittal by ASP Architects London. In addition, that this Fire Risk Assessment will be implemented in construction progress on site prior presentation of F10 to the HSE.

The Employer after completion of the construction works, will appoint a qualified persons to integrate and complete the process for the occupancy of the building by tenants, and It is become on his responsibility the subsequent procedures to implement.







