

Internal Door Schedule

Document Number: CTH-PUR-XXX-SCH-31-A-7102

Document Created: 01.07.2019

Revisions: Rev. T04 dated 24.07.2020 [T03 dated 13.07.2020] [Rev. T02 dated 21.04.2020] [Rev. 06 dated 10.01.2020] [Rev. 05 dated 27.09.2019] [Rev. 04 dated 17.09.2019] [Rev. 03 dated 04.09.2019] [Rev. 02 dated 14.08.2019] [Rev. 01 dated 18.07.2019] [Rev. 0 dated 01.07.2019]

Job Number: 238664

Job Name: Camden Town Hall

WORKS: Full refurbishment and reconfiguration of existing building

AT: Camden Town Hall

CLIENT: Lendlease

STATUS: T04 TENDER

DATA SORT: All Data

Conservation Code Key:	
RFPD	- Existing significant doors requiring fire upgrade to be considered for complete replacement with new fire doors.
RMFD	- Existing modern doors requiring fire upgrade for complete replacement with new fire doors.
RPAC	- Existing doors requiring acoustic upgrade to be considered for complete replacement with new acoustic doors.
RPFA	- Existing doors requiring fire and acoustic upgrade to be considered for complete replacement with new fire doors.
APRP	- New Door.
NOCH	- Door neither upgraded or replaced but may require refurbishment.
NOTE: All dimensions shown are indicative and approximate for pricing purposes. The contractor must check all dimensions on site and establish final new dimensions through the production of fabrication drawings prior to manufacture. All to be approved by Architect before fabrication.	

Security / Access Key:	
TR	- Token Reader
EM	- Electromagnetic Locking
EML	- Electromagnetic lock with lever handle
DC	- Door Contact (Senses door position)
RTE	- Request to Exit
PP	- Push Pull Action
LL	- Lever Latch or Door Knob (See NBS Spec.)
A	- Automatic Opening via push button
CL	- Door closer (floor spring if on existing)
HO	- Elect. Hold Open / Close on Alarm
NDC	- No door closer
KO	- Key Override with UKPN locking barrel
ML2	- manual lock allowing for 2 locking cylinders

This schedule must be read in conjunction with other information including the below:

Purcell General Arrangement Plans: 2000 series
 Purcell NBS specification document
 Purcell Door Type Drawings: 8000 series
 Fire Strategy Drawings: CTH-PUR-B0-DR-36-A-5000 to CTH-PUR-XXX-DR-36-A-5013

NOTE: Please note that security requirements outlined in this door schedule are indicative only. The door schedule should not be relied upon on its own. The security design package contains the key design and specification information describing the required installation. The Hoare Lea design package takes precedence over this schedule with regards to electronic security related matters. Security Consultant's Package by Hoare Lea. See drawings: CTH-HL-B0-DR-68-Y-1001 to CTH-HL-RF-DR-68-Y-1008.pdf

REFERENCE		LOCATION					TYPE				EXISTING DIMENSIONS				PROPOSED DIMENSIONS				PERFORMANCE		SECURITY				ACCESS			GENERAL														
Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.		
DB.01-1	DEB.64-3	-1		EB.78	Vault	B.01	Records Store	E10	n/a	Existing	Add new door (DB.01-2) behind existing door	1857	847	126	n/a	Single	1865	850	759	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None										8012	Steel vault door	NOCH		
n/a	DEB.78-2	-1		EB.79	Vault	B.01	Records Store	Modern	n/a	Removed	Door removed from scheme	n/a	n/a	n/a	n/a	Single	n/a	n/a	Awaiting Survey	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None										None	Utilitarian door - no significance	RMFD		
DB.01-2	n/a	-1		n/a	n/a	B.01	Records Store	n/a	N05	New	Install new door and frame behind existing vault door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1865	841	54	1912	913	760	Single	n/a	FD120					PAS 24	PP		CL				8054		APRP
DB.01-3	DEB.78-3	-1		EB.80	Vault	B.02	General Store	No Access	N05	Replaced	Remove existing door and frame and replace all					Single			n/a	n/a	n/a	54	Measure on site (Assume 1912)	720	n/a	Single	n/a	FD120						PP		CL				8054	No access to door in locked vault	RFPD
DB.02-1	DEB.64-4	-1		EB.80	Vault	B.02	General Store	E10	n/a	Existing	Add new door (DB.02-2) behind existing door	1856	845	126	n/a	Single	1865	850	Awaiting Survey	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None											8012	Steel vault door	NOCH	
DB.02-2	n/a	-1		n/a	n/a	B.02	General Store	n/a	N05	New	Install new door and frame behind existing vault door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1865	841	54	1912	913	760	Single	n/a	FD30					PAS 24	PP		CL				8054		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.03-1	DEB.64-5	-1		EB.81	Vault	B.03	FM Store	E10	n/a	Existing	Add new door (DB.03-3) behind existing door	1856	845	126	n/a	Single	1865	850	Awaiting Survey	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None										8012	Steel vault door	NOCH	
DB.03-2	DEB.81-1	-1		EB.80	Vault	B.03	FM Store	No Access	N05	Replaced	Remove existing door and frame and replace all					Single			n/a	n/a	n/a	54	Measure on site (Assume 1912)	720	n/a	Single	n/a	FD30						PP		CL		8054	No access to door in locked vault	RFPD
DB.03-3	n/a	-1		n/a	n/a	B.03	FM Store	n/a	N05	New	Install new door and frame behind existing vault door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1865	841	54	1912	913	760	Single	n/a	FD30					PAS 24	PP		CL		8054		APRP
n/a	DEB.64-7	-1		EB.82	Vault	N/A	N/A	n/a	n/a	Existing	Removed	1856	848	126	n/a	Single	1865	850	Awaiting Survey																			None		
N/A	DEB.81-2	-1		EB.82	Vault	N/A	N/A	n/a	n/a	Existing	Removed	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a																			None		
DB.04-1	New (Replaces DEB.64-7)	-1	DEB.64-7	EB.82	Vault	B.04	Greywater Harvesting	n/a	N08	New	Vault door removed, new double opening formed	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	1865	708 / 708	54	1912	1500	n/a	Double	n/a	FD30						PP		CL		8057		APRP
DB.04-2	DEB.82-1	-1		EB.76	Water Supply	B.05	IT Intake	Modern	N05	Replaced	Replace existing door and frame.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	As Existing	As Existing	54	As Existing	705	n/a	Single	n/a	FD30						PP		CL		8054	To be surveyed	RMFD
DB.05-1	DEB.76-1	-1		EB.76	Water Supply	B.05	IT Intake	E16	N05	Replaced	Replace existing door and frames with new	2120	857	46	14	Single	2123	868	Awaiting Survey	2150	908	54	2200	990	n/a	Single	n/a	FD30	TR	EML	DC	RTE		n/a		CL		8054	Original solid timber panelled door	RFPD
n/a	DEB.75-1	-1		EB.75	None	N/A	N/A	E16	n/a	Existing	Removed					Single											n/a	n/a								None				
DB.06-1	New (Replaces DB.75-1)	-1	DEB.75-1	EB.75	None	B.06	Water Plantroom	n/a	N08	New	New double opening formed									2150	708 / 708	54	2200	1500	n/a	Double	n/a	FD30						PP		CL		8057		APRP
N/A	DEB.64-8	-1		EB.67	Store	N/A	N/A			Existing	Removed					Double																					None			
DB.07-1	New (Replaces DEB.64-8)	-1	DEB.64.8	EB.67	Store	B.07	WC's	n/a	N07	New	Turn double opening into single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	n/a	None						PP		NDC		8056		APRP
DB.07-2	New	-1		EB.65	M WC	B.08	WC's	n/a	N04	New	Form an opening for new door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	816	40	2200	897	n/a	Single	Rw30	FD30						PP		CL		8053		APRP
DB.09-1	New	-1					Circ.	n/a	N02	New	Form opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	758 / 758	40	2200	1800	750	Double	n/a	None	TR	EM	DC	RTE		PP		CL		8051		APRP
DB.09-2	DEB.63-1	-1		EB.63	None	None	None	Modern	N03	Replaced	Replace existing door and frame with new	2034	912	46	n/a	Single	2047	918	Not Measured	2030	912	40	2080	990	n/a	Single	n/a	FD30	C	C	C	C		PP		CL		8052	Modern door no significance	RMFD
DB.10-1	DEB.71-1	-1		EB.71	Circ.	B.10	Lobby	Modern	N02	Replaced	Replace existing door and frame with new	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	None						PP		CL		8051		NOCH

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.10-2	DEB.73-1	-1		EB.73	Stair G	None	Stair G	E03A	E03A Replica FD	Replaced	Replace existing door only with replica	2111	762	57	Glass	Double	2128	1527	Not Measured	As Existing	As Existing	As Existing	As Existing	As Existing	As Existing	Double	n/a	FD30S	TR	EM	DC	RTE		PP	A	CL		8004 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with leaded lights	RFPD
DB.10-3	DEB.71-2	-1		EB.71	Circ.	B.10	Lobby	Modern	N02	Replaced	Replace existing door and frame with new	2120	754/758	44	n/a	Double	2128	1521	Not Measured	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S	C	C	C	C		PP	A	CL		8051	Modern door no significance	RMFD
DB.11-1	New	-1		n/a	n/a	B.11	SME	n/a	N02	New	New double opening formed in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30	C	C	C	C		PP		CL		8051		APRP
DB.12-1	Replaces DEB.33-1 (Removed)	-1		n/a	n/a	B.12	Building Services	n/a	N08	New	Single door removed and new double opening formed	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	959 / 959	54	2200	2000	890 (Approx. with one leaf open)	Double	Rw30	FD30S						PP		CL		8057		APRP
DB.12-2	New	-1		n/a	n/a	B.12	Building Services	n/a	N05	New	New door in opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	728	54	2200	810	n/a	Single	n/a	FD30						PP		CL		8054		APRP
DB.14-1	DEB.27-1	-1		EB.27	Store	None	None	E08	N03	Replaced	Replace existing door and frame with new	2060	852	44	14	Single	2070	860	Awaiting Survey	2080	898	54	2130 (Exist)	970 (Exist)	n/a	Single	n/a	FD30S						PP		CL		8052	Possibly original: timber, glazed panelled door	RMFD
DB.14-2	New	-1		n/a	n/a	B.14	Gas Meter	n/a	N05	New	Opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	728	54	2200	810	n/a	Single	n/a	FD30						PP		CL		8054		APRP
DB.15-1	New	-1		n/a	n/a	B.15	CC Hot Water	n/a	N03	New	Opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1500	n/a	Double	n/a	FD30S	C	C	C	C		PP		CL		8052		APRP
DB.15-2	DEB.17-4	-1		EB.17	Mail Room	B.19	Building Services	Modern	N09	Replaced	Replace existing door and frame with new	2128	925/357	42	n/a	Door & half	2155	1289	Not Measured	2150	888 / 325	40	2200	1300	n/a	Door & half	n/a	FD30						PP		CL		8058	Modern door no significance	RMFD
DB.16-1	DEB.83-1	-1		EB.83	Circulation	B.16	Shared Corridor	E14	N03	Replaced	Replace existing door and frame with new	2437	1005/1008	42	n/a	Double	2460	2000	n/a	2150	959 / 959	40	2200	2000	890 (Approx. with one leaf open)	Double	n/a	FD30S	TR	EM	DC	RTE		PP	A	CL		8052	Large, steel utilitarian access doors	RFPD
DB.16-2	DEB.36-1	-1		EB.36	None	B.11	SME	Modern	N08	Replaced	Replace existing door and frame with new	1975	837/831	42	n/a	Double	1994	1690	Awaiting Survey	2150	809 / 809	54	2200	1700	740	Double	n/a	FD30S	TR	EM	DC	RTE		PP		CL		8057	Modern doors - no significance	RMFD
DB.16-3	DEB.83-2	-1		EB.84	Stair F	None	Stair F	E04	E04 FD Replica	Replaced	Replace existing door and frame with replica, change opening and swing direction	2120	859	47	Glass	Single	2129	865	n/a	As Existing	As Existing	As Existing	As Existing	As Existing	As Existing	Single	n/a	FD30S	TR	EM	DC	RTE				CL		8006 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with wired glass	RFPD
DB.16-4	New	-1		n/a	n/a	B.16	Shared Corridor	n/a	N02	New	Opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1800	650	Double	Rw30	FD30S						PP		CL		8051		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.17-1	Replaces DEB.32-1 (Removed)	-1		n/a	n/a	B.12	Building Services	n/a	N08	New	Single door removed and new double opening formed	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	708 / 708	54	2200	1500	650	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8057		APRP
DB.18-1	Replaces DEB.24-1 (Removed)	-1		n/a	n/a	B.18	Building Services	n/a	N08	New	Single door removed and new double opening formed	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	959 / 959	54	2200	2000	890 (Approx. with one leaf open)	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8057		APRP
DB.18-2	New	-1		n/a	n/a	B.18	Building Services	n/a	N02	New	New double door opening in existing wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1500	650	Double	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8051		APRP
n/a	DEB.14-1	-1		EB.14	Circ.	n/a	n/a	E03B	n/a	Removed	Remove doors and frame	2105	758/760	55	n/a	Double	2119	1527	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	None	Original timber, glazed panelled door with wired			
DB.19-1	n/a	-1		n/a	n/a	B.19	Building Services	n/a	N02	New	New doors and frame in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1800	750	Double	n/a	FD30S	C	C	C	C	-	PP	-	CL	-	8051		APRP
DB.19-2	New	-1		n/a	n/a	B.19	Building Services	n/a	N02	New	New opening in new wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1800	750	Double	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8051		APRP
DB.20-1	DEB.17-2	-1		EB.17	Mail Room	B.19	Building Services	Modern (Assumed)	N08	Replaced	Replace existing door and frame with new	-	-	-	-	Double	-	-	-	As Existing	As Existing	As Existing	Measure on site	1400 (Approx.)	n/a	Double	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8057	No access to door in Asbestos zone	RFPD
DB.21-1	New	-1		n/a	n/a	B.21	Kitchen	n/a	N02	New	New opening in new wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	40	2200	1800	750	Double	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8051		APRP
DB.22-1	New	-1		n/a	n/a	B.22	Refuse CC	n/a	N08	New	New opening in new wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	708 / 708	54	2200	1500	650	Double	n/a	FD60S	-	-	-	-	-	PP	-	CL	-	8057		APRP
DB.23-1	New	-1		n/a	n/a	B.27 (Nearest Room)	Cloakroom (Nearest Room)	n/a	N03	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8052		APRP
DB.24-1	DEB.02-1	-1		EB.02	Female WC	B.24	WC's	Pending photo survey	Pending photo survey	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	CL	-	None		NOCH	
DB.24-2	DEB.02-2	-1		EB.02	Female WC	B.24	WC's	Pending photo survey	Pending photo survey	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	None		NOCH		
DB.25-1	DEB.03-1	-1		EB.03	Stair A	B.25	Corridor	Pending photo survey	Pending photo survey	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	None		NOCH			
DB.25-2	New	-1		n/a	n/a	B.25	Corridor	n/a	N03	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8052		APRP
DB.26-1	New	-1		n/a	n/a	B.26	Kitchen Store	n/a	N03	New	New opening in new wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8052		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.26-2	DEB.14-3	-1		EB.09	Store	B.26	Kitchen Store	E16	N03	Replaced	Replace existing frame and door with new, increase opening size	1981	826	44	14	Single	2002	832	Awaiting Survey	2150	830	40	2200	910	n/a	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8052	Possibly original: Poorly made timber panelled door. Not of great significance.	RFPD
DB.26-3	DEB.05-1	-1		EB.05	Female Cloakroom	B.26	Kitchen Store	Modern	N03	Replaced	Replace existing frame and door with new, increase opening size	1981	837	43	n/a	Single	1992	841	Awaiting Survey	2150	830	40	2200	910	n/a	Single	NA	FD30	-	-	-	-	-	PP	-	CL	-	8052	Modern door no significance	RMFD
DB.27-1	New	-1		n/a	n/a	B.27	Cloakroom	n/a	N04	New	Opening formed in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8053		APRP
DB.27-2	DEB.06-2	-1		EB.11	Store	B.27	Cloakroom	E16	N04	Replaced	Replace existing frame and door with new, increase opening size	2115	857	45	14	Single	2129	860	Awaiting Survey	2150	830	40	2200	910	n/a	Single	NA	FD30	-	-	-	-	-	PP	-	CL	-	8053	Original solid timber panelled door	RFPD
DB.27-3	New	-1		n/a	n/a	B.27	Cloakroom	n/a	N04	New	New opening in new wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8053		APRP
DB.28-1	DEB.06-4	-1		EB.06	St.	B.28	Store	E16	N05	Replaced	Replace existing door and frame with new	1881	855	45	14	Single	1905	861	Awaiting Survey	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	n/a	Single	NA	FD30	-	-	-	-	-	PP	-	CL	-	8054	Original solid timber panelled door	RFPD
DB.29-1	New	-1		n/a	n/a	B.29	WC's	n/a	N04	New	Opening formed in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	n/a	None	-	-	-	-	-	PP	-	CL	-	8053		APRP
DB.30-1	New	-1		n/a	n/a	B.30	Bike Store	n/a	N09	New	Opening formed in new partition wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	905 / 511	40	2200	1500	850 (Widest Leaf Open)	Double	n/a	FD30	TR	EM	DC	RTE	PAS 24	PP	A	CL	-	8051		APRP
DB.30-2	New	-1		n/a	n/a	B.30	Bike Store	n/a	N09	New	Opening formed in new partition wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	905 / 511	40	2200	1500	850 (Widest Leaf Open)	Double	n/a	FD30	TR	EM	DC	RTE	PAS 24	PP	A	CL	-	8051		APRP
DB.31-1	New	-1		n/a	n/a	B.31	UKPN	n/a	Steel Sunray Firelock	New	Make new opening for double doors	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Standard	Standard	Standard	2175 (Standard)	1585 (Standard)	n/a	Double	n/a	FD240	-	ML2	-	-	-	-	-	NDC	-	See manufacturers standard details		APRP
DB.31-2	New	-1		n/a	n/a	B.31	UKPN	n/a	Steel Sunray Firelock	New	Opening formed in new partition wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Standard	Standard	Standard	2175 (Standard)	1585 (Standard)	n/a	Double	n/a	FD240	-	ML2	-	-	-	-	-	NDC	-	See manufacturers standard details		APRP
DB.32-1	New	-1		n/a	n/a	B.32	IT Intake	n/a	N03	New	Form new opening for new single door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	728	54	2200	810	n/a	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8052		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.33-1	DEB.41-11	-1		EB.50	Store (Lobby)	B.33	Comms	Modern	N03	Replaced	Alter existing opening to insert new door	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	728	54	2200	810	n/a	Single	n/a	FD30	TR	EM	DC	RTE	PAS 24	PP		CL		8052		APRP
DB.34-1	DEB.41-7	-1		EB.53	Stair D	None	Stair D	E03A	E03A Replica FD	Replaced	Replace existing door only with replica	2114	759	57	Glass	Double	2131	1520	Awaiting Survey	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	Match Existing Dims.	n/a	Double	n/a	FD30S	TR	EM	DC	RTE			A	CL		8004 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with leaded lights	RFPD
DB.34-2	Existing door (No ref.)	-1		EB.53	Stair D	None	Stair D	Unknown	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None													
DB.35-1	New	-1		n/a	n/a	B.35	LV Switch Room	n/a	N09	New	Create new opening for 1.5 leaf width double door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729 / 388	40	2200	1200	n/a	Door & half	n/a	FD30						PP		CL		8058		APRP
DB.36-1	New	-1		n/a	n/a	B.36	Faith Rm	n/a	N09	New	Create new opening for 1.5 leaf width double door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729 / 388	40	2200	1200	n/a	Door & half	Rw35	None						LL		NDC		8058		APRP
DB.37-2	New	-1		n/a	n/a	B.37	Hygiene F (Drying Rm)	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
DB.37-3	New	-1		n/a	n/a	B.37	Hygiene F	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
DB.37-4	New	-1		n/a	n/a	B.37	Hygiene F	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
DB.37-5	New	-1		n/a	n/a	B.37	Hygiene F	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
n/a	DEB.64-1	-1		EB.77	Vault	n/a	n/a			Removed	Remove vault door, make good for fitting new door DB.38-1	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	NA	None								CL		None		NOCH	
DB.38-1	n/a	-1		n/a	n/a	B.38	Hygiene	n/a	N05	New	Install new door in existing vault door opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1865	841	54	1912	913	760	Single	n/a	None	TR	EM	DC	RTE		PP		CL		8054		APRP
DB.38-2	New	-1		n/a	n/a	B.38	Hygiene M (Drying Rm)	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
DB.38-3	New	-1		n/a	n/a	B.38	Hygiene M	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP
DB.38-4	New	-1		n/a	n/a	B.38	Hygiene M	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None						LL		NDC		8053		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.38-5	New	-1		n/a	n/a	B.38	Hygiene M	n/a	N04	New	Part of new partition construct	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	619	40	2200	700	n/a	Single	NA	None	-	-	-	-	-	LL	-	NDC	-	8053		APRP
DB.39-1	New	-1		n/a	n/a	B.39	WC's	n/a	N04	New	Make opening for new single door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	Rw30	FD30	-	-	-	-	-	PP	-	CL	-	8053		APRP
DB.41-1	New	-1		n/a	n/a	B.41	Clin. St	n/a	N04	New	Make opening for new single door	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	728	40	2200	810	n/a	Single	Rw30	FD30	-	-	-	-	-	PP	-	CL	-	8053		APRP
DB.42-1	Replaces Vault Door DEB.45-1 (Pinned back to wall on entrance)	-1		EB.44	Vault	B.42	Meeting Rm	E10	N03	New	Remove vault door, make good and fit new door	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	1865 (Est.)	780 (Est.)	40	1912 (Estimate)	860 (Estimate)	n/a	Single	Rw35	None	-	-	-	-	-	LL	-	NDC	-	8052		APRP
DB.43-1	Replaces Vault Door DEB.45-2 (Pinned back to wall on entrance)	-1		EB.46	Vault	B.43	Meeting Rm	E10	N03	New	Remove vault door, make good and fit new door	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	1865 (Est.)	780 (Est.)	40	1912 (Estimate)	860 (Estimate)	n/a	Single	Rw35	None	-	-	-	-	-	LL	-	NDC	-	8052		APRP
DB.LW01-1	New	-1		n/a	n/a	B.LW.01	Atrium	(DT 14)	Crittall replica?	New	Item's details included in window schedule	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1912 (nstimate)	1455 (approx.)	Required	n/a	Rw30	FD60S & A.O.V.	-	-	-	-	-	A	CL	-	None		APRP	
DB.LW02-1	New (Replaces DEB.63-2)	-1				B.LW.02	Atrium	(WT B03)	To match existing lightwell doors?		Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								Rw30	FD60S & A.O.V.	-	-	-	-	-	A	CL	-	Required		APRP	
DB.LW02-2	DEB.48-3	-1		EB.LW.02	Lightwell 2	B.LW.02	Artrium	(DT 14)	E11 Replica	Replaced	Item's details included in window schedule	2492 (assumed)	720/736 (assumed)	39	Glass	Double	3497 (assumed)	1452 (assumed)	Awaiting Survey	n/a	n/a	n/a	1912 (Estimate)	n/a	n/a	n/a	NA	FD60S & A.O.V.	-	-	-	-	-	A	CL	-	Pending Survey (Assumed same as DEB.70-1)	Original external lightwell door made from metal and glass	RFPD	
DB.LW02-3	DEB.70-1	-1		EB.LW.02	Lightwell 2	B.LW.02	Artrium	(DT 14)	E11 Replica	Replaced	Item's details included in window schedule	2492	720/736	39	Glass	Double	3497	1452	Awaiting Survey	n/a	n/a	n/a	1912 (Estimate)	n/a	n/a	n/a	NA	FD60S & A.O.V.	-	-	-	-	-	A	CL	-	Data Available	Original external lightwell door made from metal and glass	RFPD	
DB.LW03-1	DEB.47-3	-1		EB.47	None	B.LW.03	Lightwell	(DT 15)	Crittall aluminium style	Replaced	Item's details included in window schedule					Double				n/a	n/a	n/a	1912 (Estimate)	As Existing	n/a	n/a	n/a	A.O.V. Only	-	-	-	-	-	A	-	-	See Type		NOCH	
DB.LW03-2	New	-1		n/a	n/a	B.LW.03	Lightwell	(DT 16)	Crittall aluminium style	New	Item's details included in window schedule	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1912 (nstimate)	1500	n/a	Double	Rw30	None	-	-	-	-	-	-	-	-	See Type		APRP	
DB.LW03-3	DEB.42-1	-1		EB.42	Switch Room	B.11	SME	(DT 15)	Crittall aluminium style	Replace	Item's details included in window schedule					Double				n/a	n/a	n/a	1912 (Estimate)	As Existing	One leaf open = 750 min.	Double	n/a	A.O.V. Only	-	-	-	-	-	A	-	HO	See Type		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DB.LW04-1	Replaces DEB.41-1 (Removed)	-1		n/a	n/a	B.LW.04	Lightwell	(WT B03)	Critall aluminium style	New	Item's details included in window schedule					Double				n/a	n/a	n/a	1912 (n/estimate)	To fit existing.	n/a	Double	Rw30	FD60S	C	C	C	C				CL		See Type		APRP
DB.10-4	DEB.73-2	-1		EB.74	Off Stair G	None	Off Stair G	E21	E21 Replica	Existing	Replace existing door only with replica	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a						Single	NA	FD60S							CL		Required		RFPD		
DB.34-2	None	-1		EB.53	Off Stair D	None	Off Stair D	E21	E21 Replica	Existing	Replace existing door only with replica	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a						Single	n/a	FD60S							CL		Required		RFPD		
DB.37-6	In position of DEB.56-1 (Removed)	-1		EB.56	Store	B.37	Hygiene F	n/a	N03	New	Replace double doors with single door	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	2150	830	40	2200	910	n/a	Single	n/a	None	TR	EM	DC	RTE		PP		CL		8052		
DB.40-1	In position of DEB.41-8 (Removed)	-1		EB.61	Store	B.40	WC's	Pending Photo Survey	N07	New	Replace existing double doors and frames with new	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1010	850	Single	n/a	None							NDC		See Type			
DB.44-1	DEB.55-1	-1		EB.55	None	B.44	FM Office	Modern	N04	Replace	Replace existing door and frames with new	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	728	40	2200	810	n/a	Single	Rw35	FD30							CL		See Type		RMFD	
DB.17-2	DEB.83.4	-1		EB.83	Circulation	B.17	Building Services Corridor	Pending Photo Survey	N03	Replaced	Replace existing door and frames with new	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150 approx.	728 approx.	40	2200 approx.	810 approx.	n/a	Single	n/a	FD30S							CL		8052			
DB.23-2	DEB.14.4	-1		EB.14	Circ.	B.23	Shared Corridor	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								NDC		None				
DG.01-1	New	0		n/a	n/a	G.05	Corridor	n/a	RW01	New	New double door opening in partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	None			DC			PP		CL	HO	8031		APRP
DG.01-2	DEG.70-11	0		EG.70	Circulation	G.20	Grand Lobby	E02	n/a	Existing	Refurb.				Double			Measure clear opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE		A		HO			NOCH	
DG.01-3	DEG.70-12	0		EG.70	Circulation	G.20	Grand Lobby	E02	n/a	Existing	Refurb.	2260	700	56	6	Double	2270	1400	Awaiting Survey	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE		A		HO	Profile Survey by RH on 12.7.19 - Not yet drawn	Original timber, glazed panelled door with leaded lights	NOCH
DG.01-4	DEG.70-1	0		EG.56	Circulation	G.31	Corridor	Pending Photo Survey	n/a	Existing	Refurb.				Double			735	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								HO	None		NOCH		
DG.02-1	DEG.86-1	0		EG.86	Reception	G.02	Reception	Pending Photo Survey	n/a	Existing	Refurb.				Single			Check if 750	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			NDC		None		NOCH	
DG.02-2	New	0		n/a	n/a	G.03	Office	n/a	E07 Replica	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2126	909	47	2200	1044	845	Single	Rw35	None							NDC		8007		APRP	
DG.03-1	DEG.85-1	0		EG.85	Electrical Services	G.03	Office	Pending Photo Survey	n/a	Existing	Refurb.				Single			830	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE					None		NOCH	
DG.03-2	DEG.70-5	0		None	Circ.	G.03	Office	Pending Photo Survey	n/a	Existing	Refurb.				Double			n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			NDC		None		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DG.03-3	New	0		n/a	n/a	G.04	Community Room	n/a	E04 Replica	New	New opening in existing wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	800	Single	Rw40	None	-	-	-	-	-	-	-	NDC	-	8006		APRP
DG.04-1	New	0		n/a	n/a	G.04	Community Room	n/a	RW01	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1650 not 1800	750	Double	Rw30	None	TR	EM	DC	RTE	-	PP	A	CL	-	8031	E01A Style wide door	APRP
DG.06-1	DEG.70-10	0		EG.73	AWC	G.06	WCs	Original Partially Glazed [R6]	n/a	Existing	Refurb. Door Swing Changed	-	-	-	-	Single	-	-	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	A	-	-	None		NOCH	
DG.06-2	New	0		n/a	n/a	G.06	WCs	n/a	N07	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
DG.06-3	New	0		n/a	n/a	G.06	WCs	n/a	N04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	728	40	2200	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	CL	-	8053		APRP
DG.07-1	New	0		n/a	n/a	G.05	Corridor	n/a	RW01 FD	New	Install new door and frame in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	TR	EM	DC	RTE	-	PP	A	CL	HO	8031 (Shows style only - See replica FD package for fire details)	E01A Style wide door	APRP
DG.07-2	New	0		n/a	n/a	G.07	Corridor	n/a	RW01 FD	New	Install new door and frame in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	-	-	-	-	-	PP	A	CL	HO	8031 (Shows style only - See replica FD package for fire details)	E01A Style wide door	APRP
DG.08-1	DEG.77-1	0		EG.77	Office	G.08	Kitchen	E04	E04 Replica FD	Replaced	Replace existing door only with replica	2111	907	56	Glass	Single	2137	912	n/a	2111	907	56	2190 (Estimated)	1040 (Estimated)	850	Single	n/a	FD30S	TR	EM	DC	RTE	-	-	-	CL	-	8006 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door	RFPD
DG.09-1	Replaces DEG.76-1 (Removed)	0		EG.76	Office	G.09	WC	E04	RP04-BD	Replaced	E04 style (solid panel) in existing enlarged opening. Disabled bi-direction with release	2111 (Est.)	907 (Est.)	56	Glass	Single	2137 (Estimated)	912 (Estimated)	n/a	2111	907	56	2190	1040	830	Single	n/a	FD30S	-	-	-	-	-	PP	A	CL	-	8033		APRP
DG.10-1	Replaces DEG.45-1 (Removed)	0		EG.45	Circulation	G.10	Wedding Suite 02	E04	E04 FD Replica	Replaced	Existing door replaced with new door with fire and acoustic upgrades	2111 (Est.)	907 (Est.)	56	Glass	Single	2137 (Estimated)	912 (Estimated)	n/a	2111	907	56	2190	1040	800	Single	Rw35	FD30S	-	-	-	-	-	LL	-	DC	-	8006	Original timber, glazed panelled door	RPFA
DG.10-2	New	0		n/a	n/a	G.18	Wedding Corridor	n/a	RWP01 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2107	957 / 957	56	2180	2054	900	Double	Rw35	FD30S	-	-	-	-	-	LL	-	CL	-	8032		APRP
DG.11-1	New	0		n/a	n/a	G.18	Wedding Corridor	n/a	RWP01 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2107	957 / 957	56	2180	2054	900	Double	Rw35	FD30S	-	-	-	-	-	LL	-	CL	-	8032		APRP
DG.12-1	New	0		n/a	n/a	G.12	Interview	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	FD30S	TR	EM	DC	RTE	-	PP	-	CL	-	8033		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DG.13-1	Replaces DEG.42-1 (Removed)	0		n/a	n/a	G.13	Flower St	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	n/a	FD30S	-	-	-	-	-	LL	-	CL	-	8033 (Shows style only - See replica FD package for fire details)		APRP
DG.14-1	Replaces DEG.45-3 (Removed)	0		n/a	n/a	G.14	Cl Store	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	n/a	FD30S	-	-	-	-	-	LL	-	CL	-	8033 (Shows style only - See replica FD package for fire details)		APRP
DG.15-1	New	0		n/a	n/a	G.15	Records Store	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8033 (Shows style only - See replica FD package for fire details)		APRP
DG.16-1	New	0		n/a	n/a	G.16	Changing	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8033 (Shows style only - See replica FD package for fire details)		APRP
DG.16-2	New	0		n/a	n/a	G.16	Changing	n/a	E07 Replica	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2126	675	47	2200	810	600	Single	n/a	None	-	-	-	-	-	-	-	-	8007		APRP	
DG.16-3	New	0		n/a	n/a	G.16	Changing	n/a	E07 Replica	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2126	675	47	2200	810	600	Single	n/a	None	-	-	-	-	-	-	-	-	8007		APRP	
DG.17-1	New	0		n/a	n/a	G.17	BOH	n/a	RP04	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	n/a	None	TR	EM	DC	RTE	-	PP	-	CL	-	8033		APRP
DG.19-1	New	0		n/a	n/a	G.19	Wedding Lobby	n/a	E04 FD Replica	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	800	Single	n/a	FD30S	-	-	-	-	-	LL	A	CL	HO	8006		APRP
DG.19-2	Replaces DEG.70-9 (Removed)	0		n/a	Circ.	G.19	Wedding Lobby	E04	E04 FD Replica	Replaced	Replace existing door only with replica	2111 (Est.)	907 (Est.)	56	Glass	Single	2137 (Estimated)	912 (Estimated)	n/a	2111	907	56	2190	1040	800	Single	n/a	FD30S	-	-	-	-	-	LL	-	CL	HO	8006		APRP
DG.21-1	DEG.53.1	0		EG.53	None	G.21	Store	E02 (modified with board face)	E02 Replica FD	Replaced	Replace existing door only with replica	2260	700/700	56	Glass	Double	2270	1400	Awaiting Survey	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Double	n/a	FD30	-	-	-	-	-	-	-	CL	-	8003 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with leaded lights	RFPD
DG.22-1	New	0		n/a	n/a	G.22	Comms	n/a	RP04 (FD)	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw30	FD30	TR	EML	DC	RTE	-	n/a	-	CL	-	8033 (Shows style only - See replica FD package for fire details)		APRP
DG.23-1	New	0		n/a	n/a	G.23	Registry	n/a	RP04	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE	-	PP	-	CL	-	8033		APRP
DG.25-1	New	0		n/a	n/a	G.25	Registry	n/a	RP04	New	New opening in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE	-	PP	-	CL	-	8033		APRP
DG.27-1	Replaces DEG.27-1 (Removed)	0		EG.27	Office	G.27	Registry	Unknown	RP04	New	New door in existing opening	n/a	n/a	n/a	n/a	Single	n/a	n/a	830 (Check)	2111	907	56	2190	1040	850	Single	n/a	None	TR	EM	DC	RTE	-	PP	-	CL	-	8033		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DG.28-1	Replaces DEG.28-1 (Removed)	0		EG.28	Office	G.28	Registry	Unknown	RP04	New	New door in existing opening	n/a	n/a	n/a	n/a	Single	n/a	n/a	830 (Check)	2111	907	56	2190	1040	850	Single	n/a	None	TR	EM	DC	RTE		PP		CL		8033		APRP
DG.29-1	Replaces DEG.29-1 (Removed)	0		EG.29	Office	G.29	Registry	Unknown	RP04	New	New door in existing opening	n/a	n/a	n/a	n/a	Single	n/a	n/a	830 (Check)	2111	907	56	2190	1040	850	Single	n/a	None	TR	EM	DC	RTE		PP		CL		8033		APRP
DG.30-1	New	0		n/a	n/a	G.30	Corridor	n/a	E01A Replica FD	New	New door in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	756 / 756	56	To be established on site	To be established on site	n/a	Double	n/a	FD30S	TR	EM	DC	RTE			A	CL	HO	8000 (Shows style only - See replica FD package for fire details)		APRP
DG.30-2	DEG.56-1	0		EG.54	Stair D	G.30	Corridor	E01A	E01A Replica FD	Replaced	Replace existing doors only with replica	2104	760	55	Glass	Double	2116	1526	710	As Existing	As Existing	As Existing	As Existing	As Existing	As Existing	Double	n/a	FD30S	TR	EM	DC	RTE		A	CL	HO	8000 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with leaded lights	RFPD	
DG.32-1	DEG.55-1	0		EG.55	Office	G.32	Registry	E04	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE				NDC		See Type		NOCH	
DG.33-1	New	0		n/a	n/a	G.33	Registry	n/a	RP04	New	Create new single opening in wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE		PP		CL		8033		APRP
DG.34-1	n/a	0		n/a	n/a	G.34	Registry	n/a	RP04	New	Create new single opening in wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE		PP		CL		8033		RPAC
DG.35-1	Door DEG.63-1 moved from EG63 to replace DEG.57-1 (Removed)	0		EG.57	Office	G.35	Registry	E04	RP04-SP	Replaced	Existing double opening reduced to single opening with side panels	n/a	n/a	n/a	Glass	Double	2136	1560 (Approx.)	847 (Estimated from detail drawing)	2111	907	56	2190 (Estimated)	1560 (Estimated)	850	Single / Side Panels	Rw35	None	TR	EM	DC	RTE		PP		NDC		8036	Original timber, glazed panelled door	RPAC
DG.37-1	New	0		n/a	n/a	G.37	Registry	n/a	RP04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE		PP		CL		8033		APRP
DG.38-1	New	0		n/a	n/a	G.38	Registry	n/a	RP04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2111	907	56	2190	1040	850	Single	Rw35	None	TR	EM	DC	RTE		PP		CL		8033		APRP
DG.40-1	DEG.69-1	0		EG.68	Circulation	G.40	Deliveries & Store Room	E04	E04 Replica FD	Replaced	Replace existing door only with replica	n/a	n/a	n/a	n/a	Single	n/a	n/a	Not Measured	2111	907	56	2190	1040	850	Single	n/a	FD30	TR	EM	DC	RTE				CL		8006 (Shows style only - See replica FD package for fire details)	Original timber door with one leaded, glazed light	RFPD
DG.41-1	DEG.56-2	0		EG.64	F WC	G.41	WCs	Original Partially Glazed [R6]	n/a	Existing	Change Swing of door, refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None						A				See Type		NOCH	
DG.41-2	New	0		n/a	n/a	G.41	WCs	n/a	N07	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None						PP		NDC		8056		APRP
DG.41-3	New	0		n/a	n/a	G.41	WCs	n/a	N04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None						PP		CL		8053		APRP
DG.42-1	New	0		n/a	n/a	G.42	SME & Office Lobby	(DT 20)	Sliding Door	New	Part of Window Package	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							A	CL		See Window Package - Allow for break open facility		APRP	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.	
DG.42-2	New	0		n/a	n/a	G.42	SME & Office Lobby	(DT 21)	Glazed as part of partition	New	Part of Window Package	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	PP	A	CL	-	See Window Package - containment provided. Automatic inward opening on alarm		APRP		
DG.42-3	New	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N03	New	New opening in existing wall	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30S	TR	EM	DC	RTE	PAS 24	PP	-	CL	-	8052		APRP	
DG.42-4	New	0		n/a	n/a	G.42	SME & Office Lobby	(DT 22)	Glazed as part of partition	New	Part of Window Package	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	750 Min.	Single	n/a	FD60S	C	C	C	C	-	-	-	CL	-	Required		APRP		
DG.42-5	New	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	Rw30	None	-	-	-	-	-	LL	-	CL	-				
DG.43-1	n/a	0		n/a	n/a	G.43	Lobby Bike & Refuse	n/a	N05	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	970	54	2200	970	900	Single	n/a	FD30	C	C	C	C	-	PP	A	CL	-	8054			
DG.44-1	DEG.01-9	0		EG.01	Entrance Lobby	G.44	Entrance Lobby	E09	E09 Replica FD	Replaced	Replace existing door only with replica	2025	860	49	Glass	Single	2034	867	n/a	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Single	n/a	FD30S	-	-	-	-	-	-	-	CL	-	8011 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with leaded lights	RFPD	
DG.45-1	DEG.01-1	0		EG.01	Entrance Lobby	G.44	Entrance Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Double	n/a	None	-	-	-	-	-	-	-	NDC	-	None	Original upholstered door	NOCH	
DG.45-2	DEG.01-2	0		EG.01	Entrance Lobby	G.44	Entrance Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Double	n/a	None	-	-	-	-	-	-	-	NDC	-	None	Original upholstered door	NOCH	
DG.45-3	DEG.01-3	0		EG.01	Entrance Lobby	G.44	Entrance Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Double	n/a	None	-	-	-	-	-	-	-	NDC	-	None	Original upholstered door	NOCH	
DG.45-4	DEG.01-4	0		EG.01	Entrance Lobby	G.44	Entrance Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Double	n/a	None	-	-	-	-	-	-	A	-	-	None	Original upholstered door	NOCH	
DG.46-1	DEG.02-5	0		EG.06	Stair B	G.46	Lobby	E18	E01A Replica FD	Replaced	Replace existing door and frame with replica	n/a	n/a	n/a	n/a	Double	n/a	n/a	Not Measured	2100	756 / 756	56	2198 (Estimate)	1690 (Estimate)	n/a	Double	n/a	FD30S	-	-	-	-	-	-	A	-	-	8000 (Shows style only - See replica FD package for fire details)	8000 (Shows style only - See replica FD package for fire details)	RFPD	
DG.46-2	DEG.06-1	0		EG.88	Circ.	G.47	Lobby	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	850	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	NDC	-	None		NOCH		
DG.46-3	DEG.06-2	0		EG.05	Box Off.	G.46	Lobby	E07 Assumed	E07 Replica FD	Replaced	Replace existing door only with replica	n/a	n/a	n/a	n/a	Single	n/a	n/a	Not Measured	2126 (Est.)	709 (Est.)	47	2200 (Estimate)	844 (Estimate)	n/a	Single	n/a	FD30S	-	-	-	-	-	-	-	-	CL	-	8007 (Shows style only - See replica FD package for fire details)		RFPD
DG.47-1	DEG.88-2	0		EG.88	Circ.	G.47	Lobby	E15	E16 Replica FD	Replaced	Replace existing door only with replica	1578	859	48	Awaiting Survey	Single	1602	862	n/a	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Single	n/a	FD30S	-	-	-	-	-	-	-	-	CL	-	8018 (Shows style only - See replica FD package for fire details)	Original timber, panelled cupboard door	RFPD
DG.48-1	DEG.21-1	0		EG.21	AWC	G.48	WCs	Modern Replica	E07 Replica	Replaced	Replace existing door and frames / change opening direction					Single			880	2126 (Est.)	909 (Est.)	47	2200 (Estimate)	1044 (Estimate)	880	Single	n/a	None	-	-	-	-	-	-	-	NDC	-	8007	Thought to be modern. Multiple timber panels.	NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DG.50-1	DEG.02-4	0		EG.02	Entrance Lobby to Grand Hall	G.45	Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							A			None		NOCH		
DG.50-2	DEG.02-3	0		EG.02	Entrance Lobby to Grand Hall	G.45	Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								NDC		None		NOCH	
DG.50-3	DEG.02-2	0		EG.02	Entrance Lobby to Grand Hall	G.45	Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								NDC		None		NOCH	
DG.50-4	DEG.02-1	0		EG.02	Entrance Lobby to Grand Hall	G.45	Lobby	E22	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								NDC		None		NOCH	
DG.50-5	DEG.91-1	0		EG.91	Circ.	G.49	Lobby	E13	TBC	TBC	Can these flush doors be upgraded for fire?	2584	789/790	56	n/a	Double	2604	1578	Awaiting Survey	n/a	n/a	n/a	n/a	n/a	n/a	n/a	NA	FD30S	C	C	C	C				CL		Data Available	Possibly original: flush timber door with no special significance	RFPD
DG.50-6	DEG.90-1	0		EG.90	Circ.	G.53	Lobby	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None								CL		None	Original Door	NOCH	
DG.51-1	DEG.15-1	0		EG.14	Green Room	G.51	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.51-2	DEG.14-1	0		EG.14	Green Room	G.51	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.51-3	DEG.14-2	0		EG.14	Green Room	G.51	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.51-4	DEG.14-3	0		EG.14	Green Room	G.51	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.52-1	DEG.13-1	0		EG.13	Green Room	G.52	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.52-2	DEG.13-2	0		EG.13	Green Room	G.52	Private Dining	No Code Assigned	n/a	Existing	n/a	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									None	Original Panelled Door	NOCH		
DG.52-3	DEG.11-1	0		EG.13	Green Room	G.52	Private Dining	E05	E16 Replica FD	Replaced	Replace existing door only with replica	2025	903	46	16	Single	2058	909	Awaiting Survey	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Single	n/a	FD30S								CL		8018 (Shows style only - See replica FD package for fire details)	Possibly original: timber, panelled door	RFPD
DG.54-1	New	0		n/a	n/a	G.54	Entrance Lobby	n/a	Tenant Fit Out Item	New	Tenant Fit Out Item	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Double	n/a	None									None		APRP		
DG.55-1	DEG.02-6	0		EG.04	Stair A	G.55	Lobby	E18	E01A Replica FD	Replaced	Replace existing door only with replica	2167	763/763	56	Glass	Double	2192	1522	Awaiting Survey	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Double	n/a	FD30S								CL		8000 (Shows style only - See replica FD package for fire details)	8000 (Shows style only - See replica FD package for fire details)	RFPD
DG.55-2	DEG.04-1	0		EG.03	Box Office	None	None	E07	E07 Replica FD	Replaced	Replace existing door only with replica	2041	681	49	Awaiting Survey	Single	2050	684	Awaiting Survey	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Single	n/a	FD30S							CL		8007 (Shows style only - See replica FD package for fire details)	Original timber, panelled door	RFPD	
DG.EX-1	DEG.EX-1	0						(DT 02)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min				DC					None		NOCH		
DG.EX-10	New	0						(DT 13)			Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min	TR	EM	DC	RTE				A		None		APRP	
DG.EX-11	DEG.EX-9	0						(DT 08)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min	TR	EM	DC	RTE						None		NOCH	
DG.EX-12	DEG.70-4	0						(DT 10)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								A		None		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DG.EX-13	DEG.70-3	0						(DT 11)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min									None		NOCH		
DG.EX-14	DEG.70-2	0						(DT 12)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min							A	None		NOCH			
DG.EX-15	DEG.EX-11	0						(DT 09)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min			DC					None		NOCH			
DG.EX-16	DEG.EX-12	0						(DT 09)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min			DC					None		NOCH			
DG.EX-17	DEG.10-1	0						(DT 06)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min			DC					None		NOCH			
DG.EX-18	DEG.10-2	0						(DT 06)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min							C	None		NOCH			
DG.EX-19	New	0						(DT 05)			Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								None		APRP			
DG.EX-2	DEG.EX-2	0						(DT 01)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								None		NOCH			
DG.EX-20	New	0						(DT 05)			Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								None		APRP			
DG.EX-21	New	0						(DT 04)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min							C	None		APRP			
DG.EX-22								(DT 17)			Item's details included in window schedule																													
DG.EX-23								(DT 18)			Item's details included in window schedule																													
DG.EX-24								(DT 18)			Item's details included in window schedule																													
DG.EX-25								(DT 19)			Item's details included in window schedule																													
DG.EX-3	DEG.EX-3	0						(DT 01)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min									None		NOCH		
DG.EX-4	DEG.EX-4	0						(DT 01)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								None		NOCH			
DG.EX-5	DEG.EX-5	0						(DT 01)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min								None		NOCH			
DG.EX-6	DEG.EX-6	0						(DT 02)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min			DC					None		NOCH			

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.	
DG.EX-7	DEG.EX-7	0						(DT 03)			External Door (see Type)					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min				DC						None		NOCH		
DG.EX-8	New	0						(DT 07)			Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min									None		APRP			
DG.EX-9	New	0						(DT 07)			Item's details included in window schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey							NA	0 min									None		APRP			
DG.SF-1	DEG.SF-1	0		EG.91	Circ.	G.49	Lobby	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None										None		NOCH			
DG.SF-2	DEG.SF-2	0		EG.17	Stair F	None	Stair F	E05	E16 Replica FD	Replaced	Replace existing door only with replica	2041	906	46	Awaiting Survey	Single	2058	914	n/a	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Single	n/a	FD305	C	C	C	C				CL		8018 (Shows style only - See replica FD package for fire details)	Original timber, panelled door	RFPD	
DG.SF-3	DEG.SF-3	0		EG.17	Stair F	None	Stair F	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None			DC							None		NOCH			
DG.SG-1	DEG.70-7	0		EG.89	Circ.	None	Stair G	Pending Photo Survey	n/a	Existing	Refurb.					Double			710	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC				CL		None		NOCH		
DG.SG-2	DEG.70-6	0		EG.79	Stair G	None	Stair G	Pending Photo Survey	n/a	Existing	Refurb.					Double			710	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC				CL		None		NOCH		
DG.SG-3	DEG.79-1	0		EG.79	Stair G	None	Stair G	Pending Photo Survey	n/a	Existing	Refurb.					Single			n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									CL		None		NOCH		
DG.SG-4	DEG.89.1	0		EG.89	Circ.	None	Stair G	Pending Photo Survey	n/a	Existing	Refurb.					Double			n/a	n/a	n/a	n/a	n/a	n/a	n/a	None			DC							None		NOCH			
D1.01-1	DE1.63-2	1		E1.63	Committee Room 4	1.01	Committee Room 4	Pending Photo Survey	n/a	Existing	Refurb.					Single			830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				CL		Required		NOCH	
D1.01-2	DEG.63-1	1		E1.63	Committee Room 4	1.01	Committee Room 4	Pending Photo Survey	n/a	Existing	Refurb.					Single			830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				CL		Required		NOCH	
D1.02-1	DE1.59-1	1		E1.59	Chief Executive's Office	1.02	Chief Executive's Office	Pending Photo Survey	n/a	Existing	Refurb of high signif. door					Single			830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				NDC		Required		NOCH	
D1.02-2	DE1.59-2	1		E1.59	Chief Executive's Office	1.02	Chief Executive's Office	Pending Photo Survey	n/a	Existing	Refurb of high signif. door					Single			830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				NDC		Required		NOCH	
D1.03-1	DE1.58-1	1		E1.58	Office	1.03	Office	Pending Photo Survey	n/a	Existing	Refurb?					Single			830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				NDC		Required		NOCH	
D1.03-2	New	1		n/a	n/a	1.03	Office	n/a	E06 Replica	New	Insert new door and frame in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2103	906	54	2200 (Estimate)	1040 (Estimate)	840	Single	n/a	None									NDC		8008		
D1.04-1	DE1.57-1	1		E1.57	Leaders Room	1.04	Office	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE				NDC		Required		NOCH	
D1.06-1	DE1.40-1	1		E1.43	M WC	1.06	WCs	Pending photo survey	n/a	Existing	Change door swing and refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							A	CL		Required		NOCH		

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D1.06-2	New	1		n/a	n/a	1.06	WCs	n/a	N07	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D1.06-3	New	1		n/a	n/a	1.06	WCs	n/a	N04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	DC	-	8053		APRP
D1.07-1	New	1		n/a	n/a	1.07	Lobby	n/a	RW01 FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	-	-	-	-	-	PP	A	CL	HO	8031 (Shows style only - See replica FD package for fire details)		APRP
D1.07-2	DE1.56-1	1		E1.56	Stair G	None	Stair G	E01A	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	705? (One leaf open)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	Required		NOCH
D1.07-3	New	1		n/a	n/a	1.07	Lobby	n/a	RW01 FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	-	-	-	-	-	PP	A	CL	HO	8031 (Shows style only - See replica FD package for fire details)		APRP
D1.08-1	DE1.55-1	1		E1.55	Committee Room 3	1.08	Committee Room 3	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	Required		NOCH
D1.09-1	DE1.54-1	1		E1.54	Leaders Room	1.09	AV Storage	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	-	-	Required		NOCH	
D1.09-2	DE1.55-2	1		E1.55	Committee Room 3	1.08	Committee Room 3	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	-	Required		NOCH	
D1.09-3	DE1.53-3	1		E1.54	Leaders Room	1.09	AV Storage	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	-	Required		NOCH	
D1-10-1	DE1.53-1	1		E1.53	Mayor's Parlour	1.10	Mayor's Parlour	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	NDC	-	Required		NOCH
D1-10-2	DE1.53-2	1		E1.53	Mayor's Parlour	1.10	Mayor's Parlour	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	NDC	-	Required		NOCH
D1-10-3	DE1.52-2	1		E1.52	Office	1.11	Office	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	NDC	-	Required		NOCH	
D1-11-1	DE1.52-1	1		E1.52	Office	1.11	Office	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	NDC	-	Required		NOCH	
D1-11-2	DE1.52-3	1		E1.52	Office	1.11	Office	E06 (Assumed)	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	NDC	-	Required		NOCH	
D1-12-1	DE1.51-1	1		E1.51	WC	1.12	WCs	n/a	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	NDC	-	Required		NOCH	
D1.13-1	DE1.47-1	1		E1.47	Circulation	1.13	Corridor	Modern	RW01	Replaced	Replace existing doors and make good partition	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	None	TR	EM	DC	RTE	-	PP	A	CL	HO	8031		NOCH
D1-14-1	DE1.39-1	1		E1.39	None	1.14	Comms Rm	E06	E06 Replica FD	Replaced	Replace existing door only with replica	2110	906	56	16	Single	2133	913	850	As Existing	As Existing	As Existing	2200 (Estimate)	1040 (Estimate)	840	Single	n/a	FD30	TR	EML	DC	RTE	-	-	n/a	CL	n/a	8008 (Shows style only - See replica FD package for fire details)	Original timber, panelled door of high quality	RFPD
D1-15-1	DE1.38-1	1		E1.38	Kitchen	1.15	Tea Point	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	NDC	-	Required	Original timber, panelled door of high quality	NOCH	
D1-16-1	DE1.33-1	1		E1.33	Kitchen	1.16	Tea Point	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	-	Required		NOCH	
D1-17-1	DE1.35-1	1		E1.35	Leaders Room	1.17	Tea Point	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	Required		NOCH	
D1-18-1	DE1.32-3	1		E1.34	Council Chamber	1.18	Council Chamber	E20	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	1374 o/a 687 (one leaf open)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	A	CL	-	Data Available		NOCH	
D1-18-2	DE1.34-1	1		E1.34	Council Chamber	1.18	Council Chamber	E20	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	None		NOCH	
D1-18-3	DE1.47-3	1		E1.34	Council Chamber	1.18	Council Chamber	E20	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	1374 o/a 687 (one leaf open)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	A	CL	-	Required		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D1-19-1	New	1		n/a	n/a	1.19	Corridor	n/a	RW01 FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	TR	EM	DC	RTE		PP	A	CL	HO	8031 (Shows style only - See replica FD package for fire details)		APRP
D1-19-2	DE1.32-1	1		E1.32	Circulation	1.19	Corridor	Modern Glazed Replica	RW01	Replaced	Replace door with wider E01A Replica in partition	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	NA	0 min	TR	EM	DC	RTE		PP	A	CL	HO	8031		NOCH
D1-20-1	DE1.22-1	1		E1.22	Office	1.20	Office	E06	E06 Replica FD	Replaced	Replace existing door only with replica	2104	907	54	16	Single	2137	916	861	As Existing	As Existing	As Existing	2200 (Estimate)	1040 (Estimate)	840	Single	n/a	FD30S	TR	EM	DC	RTE		n/a	CL	n/a	8008 (Shows style only - See replica FD package for fire details)	Original timber, panelled door of high quality	RFPD	
D1-20-2	DE1.25-3	1		E1.22	Office	1.20	Office	E06 Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-21-1	DE1.25-1	1		E1.25	Office	1.21	Office	Pending photo survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	856	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			CL		Required		NOCH	
D1-21-2	DE1.25-2	1		E1.25	Office	1.21	Office	Pending photo survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	850	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-22-1	DE1.26-1	1		E1.26	Office	1.22	Office	Pending photo survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			CL		Required		NOCH	
D1-23-1	DE1.27-1	1		E1.27	Office	1.23	Office	Pending photo survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			CL		Required		NOCH	
D1-23-2	DE1.27-2	1		E1.28	Office	1.23	Office	Pending photo survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Sliding Pocket	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None									Required		NOCH		
D1-24-1	DE1.28-1	1		E1.27	Committee Room 3	1.24	Committee Room 3	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		See Type		NOCH		
D1-25-1	New	1		n/a	n/a	1.25	Lobby	n/a	RW01 FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S						A	CL	HO	See Type		APRP	
D1-25-2	DE1.29-1	1		E1.29	Stair D	None	Stair D	E01A	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	1393 o/a, 703 (One leaf open)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			CL		Required		NOCH	
D1-25-3	New	1		n/a	n/a	1.25	Lobby	n/a	RW01 FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S						A	CL	HO	See Type		APRP	
D1-27-1	DE1.30-2	1		E1.30	Committee Room 2	1.27	Committee Room 2	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-27-2	DE1.30-1	1		E1.30	Committee Room 2	1.27	Committee Room 2	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-27-3	DE1.30-3	1		E1.30	Committee Room 2	1.27	Committee Room 2	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Sliding Pocket	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-28-1	DE1.31-1	1		E1.31	Committee Room 1	1.28	Committee Room 1	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-29-1	DE1.60-1	1		E1.60	Leaders Room	1.29	Leaders Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		TR	EM	DC	RTE			NDC		Required		NOCH	
D1-29-2	DE1.61-2	1		E1.60	Leaders Room	1.29	Leaders Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-30-1	DE1.61-1	1		E1.61	Members Room	1.30	Members Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None		RT	EM	DC	RTE			NDC		Required		NOCH	
D1-30-2	DE1.62-3	1		E1.61	Members Room	1.30	Members Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Sliding Pocket	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D1.31-1	DE1.41-1	1		E1.41	F WC	1.31	WCs	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None						A	CL		None		NOCH		
D1.31-2	New	1		n/a	n/a	1.31	WCs	n/a	N07	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None					PP		NDC		8056		APRP	
D1.31-3	New	1		n/a	n/a	1.31	WCs	n/a	N04	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None					PP		DC		8053		APRP	
D1.32.1	DE1.62-1	1		E1.62	Members Room	1.32	Members Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	705	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	RT	EM	DC	RTE		A	CL		Required		NOCH		
D1.32-2	DE1.62-2	1		E1.62	Members Room	1.32	Members Room	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		Required		NOCH		
D1-34-1	DE1.40-3	1		None	Stairs to Mezz.	None	Stairs to Mezz.	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	RT	EM	DC	RTE			CL		Required		NOCH			
D1-34-2	DE1.40-2	1		None	Stairs to Mezz.	None	Stairs to Mezz.	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	RT	EM	DC	RTE			CL		None		NOCH			
D1-35-1	DE1.64-4	1		E1.11	Gallery	1.46	Gallery	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		None		NOCH		
D1-36-1	New	1		n/a	n/a	1.36	Lobby	n/a	E06 Replica FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2103	906	54	2200	1040	840	Single	n/a	FD30S						CL		None		APRP		
D1-36-2	DE1.47-2	1		E1.64	Circ.	1.36	Lobby	E01B	E01A Replica FD	Replaced	Replace existing door only with replica. Must open be able to open in direction of lobby	2054	760/760	56.7	Glass	Double	2084	1558	703/1393	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Double	NA	FD30S	TR	EM	DC	RTE		A	CL	n/a	8000 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with wired glass	RFPD	
D1-36-3	DE1.64-1	1		E1.21	Stair F	None	Stair F	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (One leaf open)	n/a	n/a	n/a	n/a	n/a	n/a	NA	0 min						CL		See Type		NOCH			
D1-38-1	New	1		n/a	n/a	1.38	Private Dining	n/a	E06 Replica FD	New	New door in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2103	906	54	2200	1040	840	Single	n/a	FD30S						CL		See Type	Original timber, panelled door of high quality	APRP		
D1-38-2	DE1.17-1	1		E1.19	None	1.38	Private Dining	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							NDC		See Type		NOCH			
D1-39-1	DE1.16-1	1		E1.16	Stair E	None	Stair E	E07	E07 Replica FD	Replaced	Replace existing door only with replica	2126	909	47	24	Single	Not Measured	Not Measured	Not Measured	As Existing	As Existing	As Existing	As Existing	As Existing	830 Min.	Single	n/a	FD30S							CL		8007 (Shows style only - See replica FD package for fire details)	Original timber, panelled door	RFPD	
D1-40-1	DE1.15-1	1		E1.15	WC	1.40	WCs	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							CL		None		NOCH			
D1-41-1	DE1.01-1	1		E1.01	F WC	1.41	WCs	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							CL		Required		NOCH			
D1-42-1	DE1.04-2	1		E1.02	Stair A	None	Stair A	E12	E12 Replica FD	Replaced	Replace existing door only with replica	2111	767/762	51	Glass	Double	2135	1514	Not Measured	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Double	NA	FD30S							CL		8014 (Shows style only - See replica FD package for fire details)	Possibly original: flush timber door with one wired glass light	RFPD	
D1-42-2	DE1.04-1	1		E1.06	Stair B	None	Stair B	E12	E12 Replica FD	Replaced	Replace existing door only with replica	2108	767/767	56	Glass	Double	2130	1528	Not Measured	As Existing	As Existing	As Existing	As Existing	As Existing	n/a	Double	n/a	FD30S							CL		8014 (Shows style only - See replica FD package for fire details)	Possibly original: flush timber door with one wired glass light	RFPD	
D1-43-1	DE1.05-1	1		E1.05	M WC	1.43	WCs	Pending Photo Survey	n/a	Existing		n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None							CL		See Type		NOCH			

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D1-44-1	DE1.07-1	1		E1.07	Stair C	None	Stair C	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	CL	-	See Type		NOCH	
D1-44-2	DE1.32-2	1		E1.32	Circulation	I.LW.04	Lightwell	E01A Assumed	n/a	Existing	Ensure door can open in direction of lobby 1.44. Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	See Type		NOCH	
D1-44-3	New	1		n/a	n/a	1.45	Lobby	n/a	E06 Replica FD	New	Partially Infill door way to take one door and frame	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2103	906	54	2200	1040	840	Single	n/a	FD30S	-	-	-	-	-	-	CL	-	8008 (Shows style only - See replica FD package for fire details)		APRP	
D1-44-4	DE1.06-1	1		E1.06	Stair B	None	Stair B	E06	E06 Replica FD	Replaced	Replace existing door only with replica	2084	908	55	16	Single	2094	914	860	2103	906	54	n/a	n/a	840	Single	n/a	FD30S	-	-	-	-	-	-	CL	-	8008 (Shows style only - See replica FD package for fire details)	Original timber, panelled door of high quality	RFPD	
D1-45-1	DE1-11.2	1		E1.11	Gallery	1.46	Gallery	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	CL	-	See Type	Original timber, panelled door of high quality	NOCH		
D1-12-2	None	1		None	Circ.	1.12	WCs	E06	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	Required	Original timber, panelled door of high quality	NOCH	
DM-01-1	DEM.01-1	Mezz		EM.01	Stair C	None	Stair C	Pending Photo Survey	n/a	Existing	Refurb	n/a	n/a	n/a	n/a	Double	n/a	n/a	700?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	-	-	-	CL	-	Required		NOCH		
DM-02-1	DEM.03-1	Mezz		EM.03	WC	M.02	WCs	Modern with alum. frame in thin partition	E09 Replica FD	Replaced	Replace existing door and frame with replica - alter opening	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2025	859	49	2099	997	800	n/a	n/a	FD30S	-	-	-	-	-	-	CL	-	8011 (Shows style only - See replica FD package for fire details)		APRP	
DM-03-1	DEM.02-1	Mezz		EM.02	Circulation	M.01	Lobby	Modern	E09 Replica	Replaced	Replace existing door and frame with replica - alter opening	1981	837	44	Glass	Single	1992	842	Required	2025	859	49	2099	997	800	n/a	n/a	n/a	-	-	-	-	-	-	NDC	-	8011	Modern with aluminium liner	RMFD	
DM-04-1	DEM.04-1	Mezz		EM.04	Circulation	M.03	Lobby	E19	E09 Replica FD	Replaced	Replace existing door and frame with replica - alter opening	2060	908	47	Glass	Single	2085	916	Required	2025	859	49	2099	997	800	n/a	n/a	FD30S	-	-	-	-	-	-	CL	-	8011 (Shows style only - See replica FD package for fire details)	Possibly original: flush timber door with one wired glass light	RFPD	
DM-04-2	DEM.06-1	Mezz		EM.05	Mezz. Seating	M.04	Mezz. Seating	Not Surveyed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	NDC	-	None		NOCH		
DM-05-1	DEM.08-1	Mezz		EM.08	Circulation	M.06	Lobby	E19	E09 Replica FD	Replaced	Replace existing door and frame with replica - alter opening	1987	909	47	Glass	Single	2019	917	Required	2025	859	49	2099	997	800	n/a	n/a	FD30S	-	-	-	-	-	-	CL	-	8011 (Shows style only - See replica FD package for fire details)	Possibly original: flush timber door with one wired glass light	RFPD	
DM-05-2	DEM.11-1	Mezz		EM.10	Mezz. Seating	M.05	Mezz. Seating	Not Surveyed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	NDC	-	None		NOCH		
DM-06-1	DEM.07-1	Mezz		EM.07	Stair F	None	Stair F	Pending Photo Survey	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	Required	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	RTE	-	-	-	CL	-	None		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
DM-07-1	DEM.09-1	Mezz		EM.09	WC	M.07	AWC	Modern	E09 Replica FD	Replaced	Replace existing doors and frame with replica, Change Swing Direction - Alter opening	2038	924	44	44	Single	2054	934	Required	2025	859	49	2099	997	800	n/a	n/a	FD30S	-	-	-	-	-	-	-	NDC	-	8011 (Shows style only - See replica FD package for fire details)	Modern Solid Flush Door with No Lights	RMFD
D2-02-1	DE2.17-2	2		E2.18	Stair D	None	Stair D		n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (approx.)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH	
D2-02-2	New	2		n/a	n/a	2.02	Lobby	n/a	RW01 FD	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8031 (Shows style only - See replica FD package for fire details)		APRP
D2-02-3	New	2		n/a	n/a	2.02	Lobby	n/a	RW01 FD	New	New doors / frame / enlarge existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2102	832 / 832	56	2180	1800	750	Double	Rw30	FD30S	-	-	-	-	-	PP	A	-	-	8031 (Shows style only - See replica FD package for fire details)		APRP
D2-03-1	DE2.31-1	2		E2.31	F WC	2.03	WCs	E08	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	None		NOCH		
D2-03-2	New	2		n/a	n/a	2.03	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D2-03-3	New	2		n/a	n/a	2.03	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	DC	-	8053		APRP
D2-04-1	DE2.40-1	2		E2.40	MWC	2.04	WCs	Very similar to E08	n/a	Existing	Change door swing / refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	-	-	-	-	-	-	-	-	None		NOCH		
D2-04-2	New	2		n/a	n/a	2.04	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D2-04-3	New	2		n/a	n/a	2.04	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	NA	0 min	-	-	-	-	-	PP	-	DC	-	8053		APRP
D2-05-1	DE2.53-1	2		E2.53	Circulation	2.05	Lobby	Modern	RW01 FD	Replace	New doors / new frame / new partition	E. 1981	E. 830/827	E. 44	Glass	Double	E. 1991	E. 1667	750 min.	2102	832 / 832	56	2180	1800	750	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8031 (Shows style only - See replica FD package for fire details)	Modern door no significance	RMFD
D2-05-2	DE2.53-2	2		E2.54	Stair G	None	Stair G	E01B	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (approx.)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH	
D2-05-3	DE2.27-1	2		E2.53	Circulation	2.05	Lobby	E01B	E01A Replica FD	Replaced	Replace existing door only with replica	2113	760/760	56	Glass	Double	2137	1519	703/1393	As Existing	As Existing		As Existing	As Existing	As Existing	Double	n/a	FD30S	-	-	-	-	-	A	-	-	8000 (Shows style only - See replica FD package for fire details)	Original timber, glazed panelled door with wired glass	RFPD	
D2-06-1	New	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New doors / frame in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	To fit existing	To fit existing	40	As Existing (Measure on site)	1060 (Approx.)	n/a	Double	n/a	FD30	-	-	-	-	-	LL	-	CL	-	8055		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D2-06-2	New	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New doors / frame in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	To fit existing	To fit existing	40	As Existing (Measure on site)	1060 (Approx.)	n/a	Double	n/a	FD30	-	-	-	-	-	LL	-	CL	-	8055		APRP
D2-07-1	New	2		n/a	n/a	2.07	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8053		APRP
D2-07-2	New	2		n/a	n/a	2.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-07-3	New	2		n/a	n/a	2.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-07-4	New	2		n/a	n/a	2.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-07-5	New	2		n/a	n/a	2.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-07-6	New	2		n/a	n/a	2.07	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D2-08-1	New	2		n/a	n/a	2.08	Open Office	n/a	N03	New	New doors / frame / some new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8052		APRP
D2-09-1	New	2		n/a	n/a	2.09	Lobby	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D2-09-2	New	2		n/a	n/a	2.06	Open Office	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D2-09-3	DE2.26-1	2		E2.45	Stair F	None	Stair F	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH
D2.11-1	New	2		n/a	n/a	2.11	Store	n/a	N03	New	New doors / frame / new opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30	-	-	-	-	-	PP	-	CL	-	8052		APRP
D2-13-1	New	2		n/a	n/a	2.13	Open Office	n/a	N02	New	New doors and frame in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8051	Original timber, glazed panelled door with wired glass	NOCH
D2-14-1	New	2		n/a	n/a	2.14	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8053		APRP

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D2-14-2	New	2		n/a	n/a	2.14	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-14-3	New	2		n/a	n/a	2.14	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-14-4	New	2		n/a	n/a	2.14	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-14-5	New	2		n/a	n/a	2.14	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D2-14-6	New	2		n/a	n/a	2.14	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D2-15-1	DE2.63-2	2		E2.05	Stair C	None	Stair C	Not Surveyed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	710?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH
D2-15-2	New	2		n/a	n/a	2.15	Corridor	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D2-15-3	New	2		n/a	n/a	2.1	Corridor	n/a	N02	New	New doors and frame in new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D2-10-1	DE2.24-1	2		E2.24	Office	2.10	Corridor	E16	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	-	-	-	-	-	-	-	-	None		APRP	
D3.EX-1	DE3.EX-1	3						(WT 306)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-2	DE3.EX-2	3						(WT 309)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-3	DE3.EX-3	3						(WT 309)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-4	New	3						(WT 309)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		APRP	
D3.EX-5	DE3.EX-4	3						(WT 304)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-6	DE3.EX-5	3						(WT 304)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-7	DE3.EX-6	3						(WT 309)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-8	DE3.EX-7	3						(WT 304)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		NOCH	
D3.EX-9	New	3						(WT 309)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		APRP	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D3-EX-10	New	3						(WT 304)			See Window Schedule					Double	Awaiting Survey	Awaiting Survey	Awaiting Survey								NA	0 min									None		APRP	
D3-01-1	New	3		n/a	n/a	3.01	Open Office	n/a	N06	New	New doors in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	To fit existing	To fit existing	40	As Existing (Measure on site)	1080 (Approx.)	n/a	Double	n/a	FD30							LL	CL		8055		APRP
D3-01-2	New	3		n/a	n/a	3.01	Open Office	n/a	N06	New	New doors in existing opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	To fit existing	To fit existing	40	As Existing (Measure on site)	1080 (Approx.)	n/a	Double	n/a	FD30							LL	CL		8055		APRP
D3-02-1	New	3		n/a	n/a	3.14	Open Office	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	n/a	FD30S						PP	CL		8051		APRP	
D3-02-2	DE3.24-1	3		E3.24	Stair D	None	Stair D	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (approx.)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC			A	CL		See Type		NOCH	
D3-02-3	DE3.26-2	3		E3.26	Circulation	3.02	Lobby	Modern	N09	Replaced	Replace existing door and frame with wider one	1935	626/619	45	Glass	Double	1951	1291	580/1159	2150	805 / 411	40	2200	1300	750	Door & half	n/a	FD30S						PP	A	CL		8051	Modern door no significance	RMFD
D3-02-4	New	3		n/a	n/a	3.02	Lobby	n/a	N03	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30S						PP	CL		8052			
D3-03-1	DE3.28-1	3		E3.28	Female WC	3.03	WCs	Pending Photo Survey	n/a	Existing	Change door swing and refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830 (Assumed)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None						A	CL		None		NOCH	
D3-03-2	New	3		n/a	n/a	3.03	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None						PP	NDC		8056		APRP	
D3-03-3	New	3		n/a	n/a	3.03	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None						PP	CL		8053		APRP	
D3-04-1	DE3.29-1	3		E3.29	Male WC	3.04	WCs	Pending Photo Survey	n/a	Existing	Change door swing and refurb.	n/a	n/a	n/a	n/a	Single	n/a	n/a	830 (Assumed)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None						A	CL		None		NOCH	
D3-04-2	New	3		n/a	n/a	3.04	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None						PP	NDC		8056		APRP	
D3-04-3	New	3		n/a	n/a	3.04	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	729	40	2200	810	n/a	Single	n/a	None						PP	CL		8053		APRP	
D3-05-1	DE3.49-1	3		E3.49	Circulation	3.01	Open Office	Modern	N09	Replaced	Replace existing door and frame with wider one	1935	626/619	45	Glass	Double	1951	1291	580/1159	2150	805 / 411	40	2200	1300	750	Door & half	n/a	FD30S						PP	A	CL		8051	Modern door no significance	RMFD
D3-05-2	New	3		n/a	n/a	3.06	Open Office	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30S						PP	CL		8051		APRP	
D3-05-3	DE3.50-3	3		E3.50	Stair G	None	Stair G	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (approx.)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC			A	CL		None		NOCH	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.
D3-05-4	New	3		n/a	n/a	3.05	Lobby	n/a	N03	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8052		APRP
D3-07-1	New	3		n/a	n/a	3.07	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8053		APRP
D3-07-2	New	3		n/a	n/a	3.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D3-07-3	New	3		n/a	n/a	3.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D3-07-4	New	3		n/a	n/a	3.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D3-07-5	New	3		n/a	n/a	3.07	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP
D3-07-6	New	3		n/a	n/a	3.07	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP
D3-08-1	New	3		n/a	n/a	3.08	Lobby	n/a	N02	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D3-08-2	New	3		n/a	n/a	3.11	Open Office	n/a	N02	New	New doors / frame / new opening - opens out from office	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	958 / 958	40	2200	2000	750 min. (single leaf open)	Double	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D3-08-3	DE3.41-1	3		E3.41	Stair F	None	Stair F	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH
D3-08-4	New	3		n/a	n/a	3.08	Lobby	n/a	N03	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8052		NOCH
D3-12-1	New	3		n/a	n/a	3.11	Open Office	n/a	N02	New	New doors / frame / new opening - opens out from office	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D3-12-2	New	3		n/a	n/a	3.12	Lobby	n/a	N02	New	New doors / frame / new opening	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	858 / 858	40	2200	1800	800 (Approx. with one leaf open)	Double	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8051		APRP
D3-12-3	DE3.03-1	3		E3.03	Stair C	None	Stair C	E01A Assumed	n/a	Existing	Refurb.	n/a	n/a	n/a	n/a	Double	n/a	n/a	700 (approx.)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	None	TR	EM	DC	-	-	-	-	CL	-	None		NOCH

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.		
D3-12-4	New	3		n/a	n/a	3.12	Lobby	n/a	N03	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	929	40	2200	1010	750 Min.	Single	n/a	FD30S	-	-	-	-	-	PP	-	CL	-	8052		APRP		
D3-13-1	New	3		n/a	n/a	3.13	WCs	n/a	N04	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850	Single	Rw30	FD30S	-	-	-	-	-	PP	-	CL	-	8053		APRP		
D3-13-2	New	3		n/a	n/a	3.13	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP		
D3-13-3	New	3		n/a	n/a	3.13	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP		
D3-13-4	New	3		n/a	n/a	3.13	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP		
D3-13-5	New	3		n/a	n/a	3.13	WCs	n/a	N01	New	New cubicle door / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	1740	729	40	2100	810	n/a	Single	n/a	None	-	-	-	-	-	PP	-	-	-	8050		APRP		
D3-13-6	New	3		n/a	n/a	3.13	WCs	n/a	N07	New	New doors / frame / new partition	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	2150	930	40	2200	1010	850 Min.	Single	n/a	None	-	-	-	-	-	PP	-	NDC	-	8056		APRP		
D4.01-1	DE4.03-1	4		E4.03	Roof Space	4.03	Building Services	Not Surveyed	N05	Replaced	New doors / frame / existing opening altered	n/a	n/a	n/a	n/a	Single	n/a	n/a	n/a	2150	860	54	2200	940	792	Single	n/a	None	TR	EM	DC	RTE	-	-	PP	-	CL	-	8054		NOCH	
D4.EX-1	New	4													Double	n/a	n/a	n/a									NA	0 min								None		APRP				
D4.EX-2	New	4													Double	n/a	n/a	n/a									NA	0 min								None		APRP				
RDB-09-1	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	800	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDB-09-2	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1590	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-09-3	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1590	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-09-4	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1590	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-09-5	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1590	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-09-6	n/a	-1		n/a	n/a	B.09	Corridor	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	800	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.		
RDB-40-1	n/a	-1		n/a	n/a	B.40	WC's Disabled Shower	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a		
RDB-07-1	n/a	-1		n/a	n/a	B.07	WC's Disabled	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDB-29-1	n/a	-1		n/a	n/a	B.29	WC's	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	FD30?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDB-29-2	n/a	-1		n/a	n/a	B.29	WC's	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1360	n/a	Double	n/a	FD30?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-30-1	n/a	-1		n/a	n/a	B.30	Bike Store	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	FD30?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDB-30-2	n/a	-1		n/a	n/a	B.30	Bike Store	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1360	n/a	Double	n/a	FD30?	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDB-40-1	n/a	-1		n/a	n/a	B.07	WC's Disabled	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG-42-1	n/a	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	750	n/a	Single	n/a	FD30S	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG-42-2	n/a	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1500	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-42-3	n/a	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1500	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-42-4	n/a	0		n/a	n/a	G.42	SME & Office Lobby	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1500	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-11-1	n/a	0		n/a	n/a	G.11	Wedding Suite 01	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-11-2	n/a	0		n/a	n/a	G.12	Wedding Suite 01	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-11-3	n/a	0		n/a	n/a	G.13	Wedding Suite 01	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-11-4	n/a	0		n/a	n/a	G.14	Wedding Suite 01	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	540	n/a	Single	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG-11-5	n/a	0		n/a	n/a	G.15	Wedding Suite 01	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	710	n/a	Single	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG-11-6	n/a	0		n/a	n/a	G.16	Wedding Suite 01	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-11-7	n/a	0		n/a	n/a	G.17	Wedding Suite 01	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw40	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG-10-1	n/a	0		n/a	n/a	G.10	Wedding Suite 02	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.			
RDG.10-2	n/a	0		n/a	n/a	G.10	Wedding Suite 02	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a			
RDG.10-3	n/a	0		n/a	n/a	G.10	Wedding Suite 02	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RDG.03-1	n/a	0		n/a	n/a	G.03	Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1360	n/a	Double	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RDG.06-1	n/a	0		n/a	n/a	G.06	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1500	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG.06-2	n/a	0		n/a	n/a	G.06	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	790	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG.06-3	n/a	0		n/a	n/a	G.06	WCs	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a		
RDG.36-1	n/a	0		n/a	n/a	G.36	Registry Waiting	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG.41-1	n/a	0		n/a	n/a	G.41	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1500	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RDG.41-2	n/a	0		n/a	n/a	G.41	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	790	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG.41-3	n/a	0		n/a	n/a	G.41	WCs	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	750	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a		
RDG.23-1	n/a	0		n/a	n/a	G.23	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	790	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RDG.56-1	n/a	0		n/a	n/a	G.56	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	790	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-20-1	n/a	1		n/a	n/a	1.20	Deputy Leader's Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1540	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-20-2	n/a	1		n/a	n/a	1.20	Deputy Leader's Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1550	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-20-3	n/a	1		n/a	n/a	1.20	Deputy Leader's Office	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	810	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-12-1	n/a	1		n/a	n/a	1.12	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	500	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-12-2	n/a	1		n/a	n/a	1.12	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	720	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-12-3	n/a	1		n/a	n/a	1.12	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1400	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-12-4	n/a	1		n/a	n/a	1.12	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	940	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.	
RD1-12-5	n/a	1		n/a	n/a	1.12	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1320	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-06-1	n/a	1		n/a	n/a	1.06	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	800	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-06-2	n/a	1		n/a	n/a	1.06	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1540	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-06-3	n/a	1		n/a	n/a	1.06	WCs	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	
RD1-31-1	n/a	1		n/a	n/a	1.31	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1540	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD1-31-2	n/a	1		n/a	n/a	1.31	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	820	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-31-3	n/a	1		n/a	n/a	1.31	WCs	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	
RD1-29-1	n/a	1		n/a	n/a	1.29	Group Room	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	660	n/a	Single	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD1-03-1	n/a	1		n/a	n/a	1.03	Chief Exec Admin Office	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	660	n/a	Single	n/a	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-03-1	n/a	2		n/a	n/a	2.03	WC's	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1540	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-03-2	n/a	2		n/a	n/a	2.03	WC's	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	820	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-03-3	n/a	2		n/a	n/a	2.03	WC's	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	
RD2-04-1	n/a	2		n/a	n/a	2.04	WC's	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	800	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-04-2	n/a	2		n/a	n/a	2.04	WC's	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1540	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-04-3	n/a	2		n/a	n/a	2.04	WC's	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	
RD2-01-1	n/a	2		n/a	n/a	2.01	Open Office	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-01-2	n/a	2		n/a	n/a	2.01	Open Office	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				TBC	680	n/a	Single	Rw35	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-01-3	n/a	2		n/a	n/a	2.01	Open Office	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	680	n/a	Single	n/a	None	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-06-1	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a				2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.				
RD2-06-2	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a			
RD2-06-3	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RD2-06-4	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RD2-14-1	n/a	2		n/a	n/a	2.14	WC's	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RD2-14-2	n/a	2		n/a	n/a	2.14	WC's	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-14-3	n/a	2		n/a	n/a	2.14	WC's	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	520	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a		
RD2-06-5	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-06-6	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-06-7	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-06-8	n/a	2		n/a	n/a	2.06	Open Office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-07-1	n/a	2		n/a	n/a	2.07	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD2-07-2	n/a	2		n/a	n/a	2.07	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	520	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD2-07-3	n/a	2		n/a	n/a	2.07	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	980	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-06-1	n/a	3		n/a	n/a	3.06	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-06-2	n/a	3		n/a	n/a	3.06	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-06-3	n/a	3		n/a	n/a	3.06	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-06-4	n/a	3		n/a	n/a	3.06	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-07-1	n/a	3		n/a	n/a	3.07	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3-07-2	n/a	3		n/a	n/a	3.07	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	520	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	

Proposed Door No.	Door Reference (Existing)	Floor	New Door Replaces Original Door (Provide No.)	Existing Room Number	Existing Room Name	Proposed Room Number	Proposed Room Name	Door Style Code (Existing)	Door Style Code (Proposed)	Existing, New, Replaced	Works	Lf. H. Existing	Lf. W. Existing	Lf. T. Existing	Exist. Min. Panel Thick.	Single / Double	Height from FFL to soffit of door head liner (Existing)	Width between internal faces of door liner / frame (Existing)	Clear Opening Width (Existing)	Lf. H. Proposed	Lf. W. Proposed	Lf. T. Proposed	Structural Opening H. Proposed	Structural Opening W. Proposed	Clear Width Proposed	Single / Double Proposed	Acoustic Rating	Proposed Fire Rating	Token Reader?	Locking Type?	Door Contact?	Request to Exit?	PAS 24 Certified?	Push-Pull / Lev. Latch	Automatic Opening?	Door Closer?	Elect. Hold Open / Close on Alarm	Type Drawing	Character / Significance (Existing)	Existing doors requiring fire upgrade to be considered for complete replacement.		
RD3.07-3	n/a	3		n/a	n/a	3.07	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	980	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a		
RD3.14-1	n/a	3		n/a	n/a	3.14	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.14-2	n/a	3		n/a	n/a	3.14	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.14-3	n/a	3		n/a	n/a	3.14	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	Rw35	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.14-4	n/a	3		n/a	n/a	3.14	Open office	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	1000	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.13-1	n/a	3		n/a	n/a	3.13	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	840	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.13-2	n/a	3		n/a	n/a	3.13	WCs	n/a	N06	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	980	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.13-3	n/a	3		n/a	n/a	3.13	WCs	n/a	N10	New	New riser doorset	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	520	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD3.04-1	n/a	3		n/a	n/a	3.04	WCs	n/a	N06	New	New riser door provis.	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	TBC	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.04-2	n/a	3		n/a	n/a	3.04	WCs	n/a	N10	New	New riser door provis.	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	TBC	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD3.04-3	n/a	3		n/a	n/a	3.04	WC's	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	
RD3.03-1	n/a	3		n/a	n/a	3.03	WCs	n/a	N06	New	New riser door provis.	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	TBC	n/a	Double	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8055	n/a	
RD3.03-2	n/a	3		n/a	n/a	3.03	WCs	n/a	N10	New	New riser door provis.	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	2200	TBC	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	8060	n/a	
RD3.03-3	n/a	3		n/a	n/a	3.03	WC's	n/a	Panel TBC	New	Access Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	-	-	-	TBC	700	n/a	Single	n/a	FD30	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	None	n/a	