

Application No:	Consultees Name:	Received:	Comment:	Response:
2022/1675/HS2	Roger Low	17/05/2022 11:41:48	OBJ	<p>3.2.3 Reference is made to "potential" OSD. Given that there is no certainty of OSD and that the timing of any OSD is unknowable, not enough planning has gone into the appearance of the slab until such OSD construction MIGHT commence. Whilst to the proposers of this slab, it is temporary, to those of us who are septuagenarians or octogenarians, the view of the slab will last a lifetime.</p> <p>3.7.8. Related to the above comment, there is no mention of the views from upper level windows of Park Village East, some of which give directly onto the slab.</p> <p>More and better efforts must be made to improve the view of the slab.</p> <p>3.2.18. Why leave earthworks covered with graded gravel? Why not make them "green"?</p> <p>3.2.21. The effect of moving air on the "tunnels" is discussed. What is not discussed is the effect of air movement between the Euston Scissor Box (Open Section) and the slab when trains pass on the surrounding area.</p> <p>3.2.21. Nor is the effect of nose on the surrounding area discussed as trains pass between the Euston Scissor Box (Open Section)</p> <p>The Application should be rejected or, at least, required to positively address the above concerns.</p>
