



PHD ASSOCIATES LLP


Consultants in Architecture, Planning, Property Development & Construction

Braemar House, Water Lane, Stansted, Essex, CM24 8BJ - website : www.PHDAssociates.co.uk - Tel. 01279-817342 x100 - Email: info@phdassociates.co.uk



Project Ref. No: 2105- INTERNAL DOOR SCHEDULE - Oxford House Hostel, Tavistock Place, London, WC1H 9RE Rev (-) 18/08/2022

General notes:
 Door to be 44mm solid core hardwood door. Doors to be white painted 4 panel FD 30S SC Fire Doors, allow for vision panels between lobbies and stairwell. Paint to all joinery to be Thermoguard Woodcoat Eggshell or other equally durable paint finish achieving Class O/Class B s1 d0.
 Doors to stores or plant areas in common parts to be FD60S SC with Fire Door Keep Locked notice. Locks in common parts, if provided, are to be suited. Allow for concealed closers with hydraulic and check action to all doors.
 New wood skirtings to match section of original in No.32 are to be installed. Architraves to match existing in GF of No.32 are to be supplied and installed
 Refer to general arrangement plan drawings 2105-BC-(A)-401/402/403 for the location of the door.
 Refer to internal door detail drawings 2105-BC-J(-)-010/011/12 for the specification.



NOTES: All dimensions are shown in millimetres. All dimension to be checked on site.

Internal doors

Floor No.	Door No.	Location	Leaf width mm	Door Height mm	Fire resistant / Door type	Door Swing
BF Basement Floor	D-1-01	Room 1	762	1981	FD30S/SC	L
	D-1-02	Bathroom - Room 1	800*	1981*	n/a	L
	D-1-03	Room 2	762	1981	FD30S/SC	L
	D-1-04	Bathroom - Room 2	762*	1981*	n/a	R
	D-1-05	Room 14	765*	1981*	FD30S/SC	L
	D-1-06	Room 15	762	1981	FD30S/SC	L
	D-1-07	Bathroom - Room 15	755*	1981*	n/a	L
GF Ground floor	D0-01	Room 3	762*	1981*	FD30S/SC	R
	D0-02	Room 4	762*	1981*	FD30S/SC	L
	D0-03	Room 18	762*	1981*	FD30S/SC	L
	D0-04	Room 19	762*	1981	FD30S/SC	R
1F First floor	D1-01	Room 6	762*	1981*	FD30S/SC	R
	D1-02	Room 5	762*	1981*	FD30S/SC	L
	D1-03	Room 6	762*	1981*	FD30S/SC	L
	D1-04	Room 20	816*	1981*	FD30S/SC	L
	D1-05	Room 21	762*	1981*	FD30S/SC	R
	D1-06	Room 22	838*	1981*	FD30S/SC	L
2F Second floor	D2-01	Room 9	762*	1981*	FD30S/SC	R
	D2-02	Room 8	762*	1981*	FD30S/SC	L
	D2-03	Room 10	762*	1981*	FD30S/SC	L
	D2-04	Room 23	762*	1981*	FD30S/SC	L
	D2-05	Room 24	770*	1981*	FD30S/SC	R
	D2-06	Room 25	762*	1981*	FD30S/SC	L
3F Third floor	D3-01	Room 12	805*	1981*	FD30S/SC	R
	D3-02	Room 11	762*	1981*	FD30S/SC	L
	D3-03	Room 13	762*	1981*	FD30S/SC	R
	D3-04	Room 26	790*	1981*	FD30S/SC	R
	D3-05	Room 27	762*	1981*	FD30S/SC	L
	D3-06	Room 28	762*	1981*	FD30S/SC	R

Common area doors

BF Basement Floor	CD-1-1	Corridor	800*	1981*	FD30S/SC/VP*	R
	CD-1-2	Corridor	728*	1981*	FD30S/SC/VP*	R
	CD-1-3	Store	670*	1981*	FD60S/SC	L
	CD-1-4	Corridor	762*	1981*	FD30S/SC/VP*	L
	CD-1-5	Corridor	762*	1981*	FD30S/SC/VP*	L
	CD-1-6	Technical Room	600x2*	1981	FD60S/SC	L/R
GF Ground floor	CD0-1	Corridor	820*	1981*	FD30S/SC/VP*	L
	CD0-2	Corridor	770*	1981*	FD30S/SC/VP*	R
	CD0-3	Corridor	905*	1981*	FD30S/SC/VP*	L
	CD0-4	Store	762*	1981*	FD60S/SC	L
	CD0-5	Store room 1	762*	1981*	FD60S/SC	R
	CD0-6	Store room 2	790*	1981*	FD60S/SC	R
1F First floor	CD1-1	Corridor	762*	1981*	FD30S/SC/VP*	R
	CD1-2	Corridor	792*	1981*	FD30S/SC/VP*	R
	CD1-3	Shared bathroom	745*	1981*	n/a	R
	CD1-4	Laundry room	705*	1981*	FD30S/SC	R
2F Second floor	CD2-1	Corridor	762*	1981*	FD30S/SC/VP*	R
	CD2-2	Corridor	762*	1981*	FD30S/SC/VP*	L
	CD2-3	Store room 3	802*	1981*	FD60S/SC	R
3F Third floor	CD3-1	Corridor	806*	1981*	FD30S/SC/VP*	L
	CD3-2	Corridor	720*	1981*	FD30S/SC/VP*	R

*Door noted with VP subject to building control approval.

* All dimensions to be checked on site before ordering, and if any discrepancies occur, the architect must be informed to amend the drawing schedule and relative drawings.