
## NOTES

- New galvanised steel access ladder to replace the existing ladder in this position. Ladder to be detailed as detailed drawing 506MA/SK119.
- 2 New fall arrest system to be bolted to the string of the new ladder.
- (3) New galvanised steel freestanding hand rail to walkway.



NORTH WALL

95 KINGSLAND ROADLONDON E2 8AGPHONE 020 7729 5111www.julianharraparchitects.co.uk

DRAWING REVISIONS: -Rev. B: Aug. 2022: Guarding at roof level, horizontal design added.