

| Application No: | Consultees Name: | Received: | Comment: | Response: |
|------------------------|-------------------------------------|---------------------|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2022/3230/L | THE HEATH & HAMPSTEAD SOCIETY | 06/10/2022 16:55:40 | COMMNT | Comment from: THE HEATH & HAMPSTEAD SOCIETY. It seems that the new door and frame has been well made - but it is a shame that the door was not repaired. Age cannot be replicated - this looks like a shiny new door clashing with the rest. The frame detail is not the same as the existing - which could be rectified. |
