# APPENDICES

Options Appraisal Services Drawings Structural Drawings Existing Drawings

## Option 1: Building in the nave


This option proposed a three storey timber building at the west end. At ground floor level, this could open up to the nave so as not to limit use of the nave. This proposal takes advantage of the largely blank west wall of the nave.

It would need to include a list and stair to provide access to the upper floors, which limits the available space on each floor.

We anticipated building over the single-storey west end building, above the kitchen and office, but windows in the party wall preclude this.

The parish felt that this proposal would be too dominant within the space of the nave, and would limit activity. It would also specifically limit use of the font.











## Option 2: Building in the transept


This option proposed a two storey timber building at the north transept. This would provide a small office at ground floor, plus a stair to a counselling room at the first floor.


While not providing all the required spaces in the brief, this might improve an otherwise makeshift office.

However, there would not be sufficient space for a lift and so the upper floor would not be compliant.

In addition, the DAC were very concerned about the impact on the organ, which is adjacent, and so this option was discarded.













## Option 3: Building above the church hall

This option proposed rasing the roof of the church hall to provide an additional floor above the existing space of the hall. We proposed that the new roof volume would be a metal-clad mansard.

However, unless access to an upper floor is via the existing spiral stone staircase, which is not compliant and indeed is very constricted, then a new stair and lift would use half the available floor plan, and so the effective outcome would be two spaces half the size of the existing one.













## Option 4: Single-storey east end extension


This option proposed demolishing the St Mary's Centre, and replacing it with a single storey building with a bigger footprint.


However, this would not be sufficiently big to provide the accommodation required, and would also require the catulpa tree to be removed.











**Dow Jones Architects** 


## **Option 5: Undercroft development**


This option retains the St Mary's Centre, and makes a connection from it into the existing undercroft.


The St Marys Centre would provide a front door for Mary's, and the multi-use space could be in the undercroft.


However, the undercroft is not very large (only under the chancel) and there is not enough space in the undercroft to provide the accommodation required. In addition, there is no daylight, and no means of providing it (no space to make a lightwell or doubleheight space).

For these reasons, this proposal was discounted.









**Dow Jones Architects** 

## Option 6: Single-storey extension plus undercroft

This option combines a new building on the site of the St Mary's Centre, with a connection from it into the existing undercroft.

The new building at street level would provide a front door for Mary's plus an office, and the multi-use space could be in the undercroft.


However, as established in Option 5, the undercroft is not very large (only under the chancel), there is no daylight, and no means of providing it (no space to make a lightwell or double-height space). The quality of space we would provide would be poor.


In addition, the loss of storage space for the parish would be significant.


For these reasons, this proposal was discounted.




-+













J201105 SK\_AH\_E/02 P2

1:50@A3 For Comment

SMC Youthwork
WE REDUCE VIOLENCE - WE SAVE LIVES
Excavation
Demolition
New wall
1500mm up/down
suspended light with daylight dimming control
1200mm surface light fitting with on/off control
Surface fitting with daylight
dimming control
O Downlight type fitting with daylight dimming control
Surface wall light with daylight dimming control
IP44 surface fitting with occupancy control
Vertical suspended feature
lighting in void
Assume 50% of fittings are emergency Electrical socket and data provision to be
confirmed, the following is assumed:
Multi-purpose Room 8no. double sockets + 4no. data points + high level power and data
for projector. With additional power for white goods and induction hob/oven.
Landing 2no. double sockets + high level data for WiFi
Small Consulting Room: 4no. double sockets
+ 2no. data points
Main Hall: Matching existing provision
TWO STOREY OPTION
DOW JONES ARCHITECTS
10 Station Parade, Balham High Road, London , SW12 9AZ
T 020 8675 2544 mail@dowjonesarchitects .com
www.dowjonesarchitects .com
St Mary's Primrose Hill

430-00-110 C





1:50@A3

J201105 SK\_AH\_ M/02 P2

For Comment



New wall

## TWO STOREY OPTION

#### DOW JONES


#### ARCHITECTS


10 Station Parade, Balham High Road, London , SW12 9AZ T 020 8675 2544 mail@dowjonesarchitects .com www.dowjonesarchitects .com

#### St Mary's Primrose Hill

First floor plan 1:50 05.10.2020 STATUS: FOR COMMENT


430-00-110 C






	Co	lumn Schedu	lle		
	C1	SHS	80x80x6.3		
$\left.\right>$	C2		w SHS 80x80 s to be used ible)		
ree					
Y					
		Existing 2 substruct re-used	200thk suspe ure from c. 2	nded slab and 006 works reta	l ained and
		reinforcer supported external e footings a	ment) with he d on screw pi edge and exis along internal e locations to	ed slab (allow eave board und les (to SSC de sting ground b l edges to suit tree ro	der. Slab esign) along eams /
		Assumed retained	existing grou	und bearing sl	ab to be
		studs at 4		per wall. 50x1 lly with 11thk ( sides)	
	/				
			MØ	MEN	
Primrose Hill		se Hill	01225 44	Bath Lond	tural engineers ON 7739 6939
nd	Floc	or Plan	www.mom	ientumengine	ering .com
			<sup>ву</sup> РG	Date 25 /	/ 05 / 21


**Dow Jones Architects** 





 50 x 200 C24 rafters at 400c/c with 2 x 18thk ply sheathing over

# Appendix D: Existing drawings







Notes



## DOW JONES

## ARCHITECTS


10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mail@dowjonesarchitects.com www.dowjonesarchitects.com

#### St Mary The Virgin Primrose Hill

Existing Ground Floor Plan 1:100 @A1 07.08.2020 STATUS: For Comment



## 430-01-100 -



1 Ground floor plan Existing 1:50



Notes

DOW JONES

ARCHITECTS

10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mail@dowjonesarchitects.com www.dowjonesarchitects.com


#### St Mary The Virgin Primrose Hill

Existing Ground Floor Plan 1:50 @A1 07.08.2020 STATUS: For Comment

0 1m 2m 3m 4m 5

430-01-101 -





0 1m 2m 3m 4m 5m 6m 7m 8m 9m 10m



Notes

## DOW JONES


## ARCHITECTS

10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mail@dowjonesarchitects.com www.dowjonesarchitects.com

#### St Mary The Virgin Primrose Hill

Existing North Elevation 1:100 @A1 07.08.2020 STATUS: For Comment

430-01-200 -







2 Existing East Elevation 1:100



Notes

#### DOW JONES

#### ARCHITECTS


10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mai@dowjonesarchitects.com www.dowjonesarchitects.com

#### St Mary The Virgin Primrose Hill

Existing East and West Elevations 1:100 @A1 07.08.2020 STATUS: For Comment

430-01-210 -





0 1m 2m 3m 4m 5m 6m 7m 8m 9m 10m



Notes

#### DOW JONES


#### ARCHITECTS

10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mai@dowjonesarchitects.com www.dowjonesarchitects.com

#### St Mary The Virgin Primrose Hill

Existing South Elevation 1:100 @A1 07.08.2020 STATUS: For Comment

430-01-220 -







Notes

## DOW JONES

#### ARCHITECTS

10 Station Parade, Balham High Road, London, SW12 9AZ T 020 8675 2544 mail@dowjonesarchitects.com www.dowjonesarchitects.com

#### St Mary The Virgin Primrose Hill

Existing Section AA 1:100 @A1 07.08.2020 STATUS: For Comment

430-01-300 -