

www.gibsonsonthornley.com info@gibsonsonthornley.com +44 (0)20 7729 7064 Perseverance Works 25-27 Hackney Road 32. New internal light fittings33. Penetrations in wall for new services Application (Drawing Revision P05) 14. New cast iron downpipe and discrepancies to the architect. STRUCT, ENGINEER HTS O2. New rooflight
O3. New paving 4. This document may be issued in an uncontrolled CAD format to enable 15. New built in benches PLANNING CONSULTANT HGH Consulting London E2 7NX 16 New pre-cast cill others to use it as background 04. New anodised aluminium windows and panelling 17. New pre-cast pier information to make alterations HOLBORN LINKS: 6-8 SOUTHAMPTON PLACE DRAWING TITLE and/or additions. In that instance the file will be accompanied by a PDF version. It is for those making 05. New anodised aluminium window assembly 18. New air brick O6. New anodised aluminium glazed door assembly
O7. New anodised aluminium fixed window
O8. New glazed timber framed door 19. Repaired brickwork/pointing No. 07 PROPOSED LONG SECTION 02 20. Existing render re-finished such alterations and additions to ensure that they make use of current 21. Removed vent fitting and replaced glazing locally DRAWN BY background information. Gibson Thornley Architects accepts no 09. New timber door 22. Repaired cornicing MJT 1:50@A1 PLANNING 10. New boxing in to conceal servicing 23. Repaired and re-painted balustrating liability for any such alterations or 1:100@A3 additions to the background 11. For proposed works to roof coverings and proposed 24. Repaired and re-painted stair information or arising out of changes PROJECT ZONE TYPE CLASSIFICATION DRAWING NO REVISION 20023 - AL [00] 312 PO4A 25. Repaired entrance floor finish plant equipment please see seperate Full Planning to background information which 20023 occur prior to alterations of addition being made. Application (Drawing Revision P05) 26. New secure entry fitting