GWA

GRANT WRIGHT ASSOCIATES LLP

External Front

- 1. Cut out and make good all cracking to external rendering.
- 2. Repair works specification re. any brickwork issues exposed. (Provisional Sum. £1000).
- 3. Render externally to crack repair areas.
- 4. Re-decoration works to all rendering.
- 5. Cut out defective sections of timber to fascia near roof drainage.
- 6. Install new timber work to replace that removed near fascia.
- 7. Re-decoration to all timberwork.
- 8. Hack off and repair rendering to retaining wall to front boundary/retaining wall.
- 9. Repair brickwork as necessary to front boundary/retaining wall. Provisional Sum £1000).
- 10. Reset Coping stones to front boundary/retaining wall.
- 11. Overhaul roof and replace cracked tiles etc.
- 12. Renew cement fillet to either end of lead apron over parapet Party Wall.
- 13. Carefully remove defective timberwork to gutter, eaves and fascia area and replace removed timberwork with new fully treated timber.
- 14. Take out and replace cast iron air vent under front door.
- 15. Provisional sum for works to form bin storage area. (Provisional Sum £1500).

Roof

- 1. Construct fencing/privacy shielding to front of walkway area to match that at rear.
- 2. Railing along line of parapet-party wall. (Provisional Sum £1500).
- 3. Inspect and overhaul all guttering and downpipes to all elevations.
- 4. Piece in matching bricks and repair corbel and flaunching to the front chimney.
- 5. Piece in matching bricks and repair area above corbel to the rear chimney.
- 6. Prepare and redecorate all joinery to loft door to roof.

