Application No:	Consultees Name:	Received:	Comment:	Printed on: 17/01/2023 Response:	09:10:08			
2022/4791/P	Rees Aronson	13/01/2023 16:14:15	SUPPRT	I have lived at 7 Oak Hill Park Mews since 2005 and I am extremely positive about these proposals and support them wholeheartedly. In my view, they are a major enhancement in particular the removal of the currently unattractive elevated western section and it is replacement with a much more thoughtful design. I am very grateful to the owners of the property for the submission of this contemporary and elegant design each I firmly believe to be hugely positive for the neighbourhood.				
2022/4791/P	Claire Newbrook	12/01/2023 11:29:02	OBJ	Dear Sirs We are the managing agents for Dawlin RTM Limited and Dawlin Property Management Limited who are the Management company and Freeholder of Oak Hill Park NW3. My client would like to object to these works based on the following: EEC – Plant Noise impact assessment – The plant room in this document is not located as per the proposed Ground Floor Plan (P-4-10) that has been submitted and therefore the plant room is now nearer to Northwood Lodge, yet no noise impact assessment has been undertaken for this building. Also, the report does not mention about the noise impact from the demolition. Drainage report – there is no drainage plan or report. It is believed that the drainage from the current property is connected to that of my client's land and therefore this is required. Also the additional hard standing areas could have an effect on the water table on my clients land. Gas and Electricity Supply – there is no mention as to whether the current gas supply to the building is sufficient. Please note that if an additional gas or electric supply is required then access to my client's land would be required. Construction/Demolition Management Plan – Item 7: The entrance to Oak Hill Park from Frognal is a blind bend. There are parking spaces directly to either side of the driveway to 4 Oak Hill Park and the roadway is 4.25 meters with parking on one side. This means that delivery vehicles will damage the roadway and bank opposite the driveway. There is no parking/ or waiting on Oak Hill Park for any contractors, visitors, or residents of 4 Oak Hill. No consideration to these points has been raised. Item 18 – the access to and from the site is a 90 degree turn on a single lane, as a result it would cause obstructions and congestion based on this route let m 19 – Vehicles cannot wait on Oak Hill Park for arrive before 8am as this will cause disturbance to residents at Falcon Lodge, Martlett Lodge and Northwood Lodge. Due to the number of vehicles that are proposed daily a Banksman should be on site for all				

				P	rinted on:	17/01/2023	09:10:08	
Application No:	Consultees Name:	Received:	Comment:	Response:				
2022/4791/P	Ivy Dieltiens	13/01/2023 22:27:34	COMMNT	I support the proposal as the new design significantly improves the existing building and will enhance the neighborhood. It¿s stylish, modern and as a family home rebuilt on the existing footprint is not intrusive at all. The current building is outdated and an eye sore - this is a magnificent upgrade!				