

**Site Inspection Report**

Project Details					
Project number	2022/IN/19504	Inspection No	1	Project Surveyor	Jason Andrijasevic
Initial Notice Date	03/Mar/2022	Requested Date	28/02/2023		
Site Address	Barrie House, 29 St. Edmunds Terrace, London NW8 7QH			Inspection Type	Foundations
Project Description	Erection of a part four, part five storey residential extension and structural alterations			Weather	Dry
				Photographs	Yes - On File
Applicant	Broxwood View Ltd				
Main Contractor Details	Mr. Arek Targosz				
Site Contact Details					
Disclaimer	This inspection report does not constitute evidence that the Building Regulations have been satisfied until a Final (completion) Certificate has been issued for the project. It remains the responsibility of the person carrying out the work to ensure the work complies with Building Regulations. This site inspection report has recorded the work that could be relatively seen at the time of this periodic inspection, it does not reflect items of work that have been covered or concealed at the date/time of this inspection.				

Observations / Comments		Status
Inspection Record:	Inspection undertaken with - Site Contact (named above) Work commenced with piling to the associated retaining walls and appear generally satisfactory from what could be seen.	For Information
Action required:		Please Confirm
Photo Reference		
Time Taken: (including travel):		90
Name of Site Surveyor:		Date/Time of Inspection: 28/02/2023 15:34

**END OF REPORT**