Tree & damage photos to support application



Photo 1: Seq 27 Cockspur Thorn FO 168 Maygrove Road



Photo 2: Aspen trees Seq 49, 53, 54 & 55 POS opp claim address; Ginkgo (Seq 17) in foreground



Photo 3: Privet hedge FG 172 Maygrove Road and location near to claim address



Photo 4: Cracks in bay window structure, claim address



Photo 5: Cracks in window surround, claim address




Photo 6: Front door with distortion and cracks around frame, claim address