

Undercover

13 Belsize Crescent




Belsize Crescent Street View






13 Belsize Crescent

External Front | 13 Belsize Crescent

Photo Survey | Ground Floor




Existing Ground Floor Plan | 13 Belsize Crescent




Entrance | 13 Belsize Crescent

Photo Survey | Ground Floor





View from light-well




Entrance | 13 Belsize Crescent

Photo Survey | Ground Floor





Entrance Hall | 13 Belsize Crescent

Photo Survey | Ground Floor




Reception Room | 13 Belsize Crescent

Photo Survey | Ground Floor





Reception Room | 13 Belsize Crescent

Photo Survey | Ground Floor




Bathroom | 13 Belsize Crescent

Photo Survey | Ground Floor





Bathroom | 13 Belsize Crescent

Photo Survey | Ground Floor





Existing Lower Ground Floor Plan | 13 Belsize Crescent




Hallway | 13 Belsize Crescent

Photo Survey | Lower Ground Floor





Hallway | 13 Belsize Crescent

Photo Survey | Lower Ground Floor






Front Room | 13 Belsize Crescent

Photo Survey | Lower Ground Floor





Back Room | 13 Belsize Crescent

Photo Survey | Lower Ground Floor




External Front Light-well | 13 Belsize Crescent

Photo Survey | Lower Ground Floor




WC | 13 Belsize Crescent

Photo Survey | Lower Ground Floor




Storage Room | 13 Belsize Crescent

Photo Survey | Lower Ground Floor



Existing First Floor Plan | 13 Belsize Crescent



First Floor Hallway | 13 Belsize Crescent

Photo Survey | First Floor